

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number G9467	
4. Organization Name and Address: Velocity Aerospace - Burbank, Inc. 2840 N. Ontario Street Burbank, CA 91504 Ph: 818-333-5600,				5. Work Order/Contract/Invoice Number: T35706	
Repair Station Cert. # RB1R197K					
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	SMOKE DETECTOR	CGDU2000-00	1	11763	REPAIRED
12. Remarks: All work has been accomplished in accordance with FAA approved data: CMM: 26-16-17 Rev. 6 Dated: 3/25/2009					
Certified that the work specified in block 11/12 was carried out in accordance with EASA PART 145 and in respect to that work the component is considered ready for release to service under EASA Part 145 approval no. EASA.145.4002. For complete details of work accomplished reference tracking number in block (3) three or as attached.					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12			14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13b. Authorized Signature:		13c. Approval Authorization No.:		14c. Approval Certificate No.: RB1R197K	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14d. Name (Typed or Printed): Jose Ramon Flores 14e. Date (dd/mm/yyyy): 19/Oct/2021	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



Velocity Aerospace - Burbank, Inc.

2840 N. Ontario Street
Burbank, CA 91504
Ph: 818-333-5600,

Repair Station: RB1R197K FAA/EASA.145.4002

RECAP

Work Order #: G9467

Date Printed: 10/19/2021

Time: 11:58:37 AM

Page: 1

To: AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVE, SLINFOLD
WEST SUSSEX RH13 0AS UK
payableinvoices@ajw-group.com, UNITED
KINGDOM

Ship To: AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVENUE, SLINFOLD
WEST SUSSEX, RH13 0AS
UNITED KINGDOM

Ref #: T35706

Phone #: 441403711414

Fax #:

Email: chris.apestake@ajw-aviation.com

Mfg: SIEMENS SAS

Serial #: 11763

PN: CGDU2000-00

Descr: SMOKE DETECTOR

ATA Chapter: 26-16-17

Revision #: 6

Revision Date: 3/25/2009

Test Record: 2423

Technician: KFISHER

Type:

Entry Date: 10/11/2021

Need Date: 10/22/2021

Compl. Date: 10/19/2021 11:58:13 A

Container:

Warranty: No

Symptoms:

WORKSCOPE: TEST

REASON FOR REMOVAL

DEFECT - FOR TEST AND RECERT

A/C REG - FROM STOCK

MODS IN

B

Faults:

COMPLAINT NOT VERIFIED

PRELIM TEST & EXAM

Received unit dirty.

Unit passes functional test; however internal inspection required.

TEARDOWN INSPECTION

Labyrinth assembly and PCB are dusty.

Unit requires cleaning and calibration.

Corrective Actions:

FINAL DISPOSITION: RP

FINAL WORK ACCOMPLISHED

Cleaned housing, labyrinth assembly and PCB. Inspected wiring and components. Reassembled, calibrated and functionally tested unit per MFG specs.

MODS OUT

B

TEST EQUIPMENT:

ABI 1620, ABI 835, ABI 834A, ABI 1787, ABI 1715, ABI 1759, ABI 1846

Final Inspector Signature: Jose Ramon Flores Certificate number: 4372619