

1. Approving Civil Aviation Authority / Country: FAA/United States	2.	Authorized Release Certificate FAA Form 8130-3, Airworthiness Approval Tag		3. Form Tracking Number: 146352	
4. Organization Name and Address: Aviation Instruments Repair Specialists, Inc. A.I.R.S./14316 Commerce Way - Miami Lakes, FL 33016 U.S.A. Phone: (305) 887-5600 Fax: (305) 820-0931		5. Work Order / Contract / Invoice Number: R339346			
6. Item: 1	7. Description: N1% RPM INDICATOR	8. Part Number: WL101EED3	9. Quantity: 1ea.	10. Serial Number: AF564/107	11. Status/Work: REPAIRED
12. Remarks: REPAIRED in accordance with CMM: 77-10-36 Revision: 12 Date: 3/2/2011 Full details of work carried out per work order no. 146352 Modification Level: 1 Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the N1% RPM INDICATOR is considered ready for release to service under EASA Part 145 approval no. EASA.145.5033. No applicable A.D. or S.B. Required.					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.					
13b. Authorized Signature: Not Applicable		13c. Approval/Authorization No.: Not Applicable		14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13d. Name (Typed or Printed): Not Applicable		13e. Date (dd/mm/yyyy): Not Applicable		14b. Authorized Signature:  14c. Approval/Certificate No.: VTBR433V	
				14d. Name (Typed or Printed): Marshall Garber 14e Date (dd/mm/yyyy): 04/Jun/2018	
User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block1. Statements in Block13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

TearDown/Inspection Form

Aviation Instruments Repair Specialists, Inc.

A.I.R.S./14316 Commerce Way

Miami Lakes, FL 33016

U.S.A.

Phone: (305) 887-5600 Fax: (305) 820-0931

C.R.S. No.: VTBR433V

Work Order: 146352

Date: June/4/2018

Phone:(305) 887-5600

Fax: (305) 820-0931

Sold To:

AVTRADE (UK) LTD

GLOBAL HEADQUARTERS SAYERS COMMON

WEST SUSSEX, BN6 9JQ

Ship To:

Avtrade (UK) LTD

Avtrade Global Headquarters Sayers Common, West Sussex

BN6 9JQ England

Part Number: WL101EED3

Serial: AF564/107

Manufacturer: GE AVIATION

Description: N1% RPM INDICATOR

Model: WL101EED3

Purchase Order: R339346

Service Performed: REPAIRED

Data used: Manual Number: 77-10-36 Revision: 12 Date: 3/2/2011

TearDown/Inspection Data

1. Removal: BACK LIGHT U/S

Inst.: REPAIR

2. Initial Inspection Findings

Appearance: Normal on Visual Inspection

Corrosion: No Corrosion Noted

Loose or Missing Parts: No Loose or Missing Parts

Physical Damage: Lamps

Mod. Level: I

3. Teardown

Dissassembly: Normal

Cleaning: Normal Cleaning

Painting: Normal Painting

Assembly: Normal Assembly

4. Test

Operation: Operation I/A/W Mfg. Specs

Was Complaint Verified: Yes

Mods. Completed: None

5. Final

Warranty Accepted: N/A

Final Test and Inspection:

Final Inspection Normal

T.S.O.: TSO

A.T.A.: 77-10-36

A.D. S.B. NO A.D. / S. B. REQUIRED

Work Done: UNIT FOUND WITH DEFECTIVE LAMPS. UNIT WAS INSPECTED, DISASSEMBLED, CLEANED, REPLACED DEFECTIVE LAMPS, AND ASSEMBLED. REPAIRED I/A/W MFG. SPECS. TESTED OPERATION AND FOUND READY TO RETURN TO SERVICE. NO APPLICABLE SB OR A/D'S ON FILE. ATA 77-10-36. WORK BY EYDA DOMINGUEZ.

Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect to the work performed is approved to return to service. Pertinent details of the work performed are on File at this Agency under Work

Order No.: 146352

Inspector's Name: Marshall Garber

Certificate No. 2506369

Technician: Eyda Dominguez

Signature: _____

Date: June/04/2018

Form CRS-3