Approving Civil Aviation Authority/Country Transport Canada 2.	AUTHORIZED RELEASE	E CERTIFICATE	3. Form Tracking Number. WO8843
4. Organization Name and Address.			
AJW Technique Inc 7055, rue Alexander Fleming	<u>></u>	AIW technique	5. Work Order, Contract or Invoice Number:
Saint-Laurent QC H4S-2B7 Canada	3		T18599-1
6. Item: 7. Description:	8. Part Number:	9. Quantity: 10. Serial/Batch Number:	ich Number: 11. Status/Work:
Decoder Encoder Unit DEU Type B	Z040H0003110	0	
12. REMARKS			
INSPECTED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 23-73-47 REV 10 DATED SEP 26/2013.	N ACCORDANCE WITH CMM 23-73-47 REV	10 DATED SEP 26/2013.	
FOR MORE INFORMATION, REFER TO THE TEARDOWN/INSPECTION REPORT.	TEARDOWN/INSPECTION REPORT.		
	*		
THE TROP IN THE PROPERTY OF TH	THE TROPIO FILE	Maintenan	EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17
 13a. Certifies the items identified above were manufactured in conformity to: Approved design data and are in a condition for safe operation. 	actured in conformity to: for safe operation.	14a. Certifies that, except where otherwise 11 and described in Block 12 was performed. Regulations.	Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.
Non-approved design data specified in Block 12	12	X CAR 571.10 Maintenance Release	SO .
		Other regulation specified in Block 12	k 12
13b. Signature: 13c. /	13c. Approved Organization Number	14b. Signature 160	14c. Approval Organization Number
		Then More (116)	33-12
13d. Name (Typed or Printed): 13e. Date	Date	14d. Name (Typed or Printed)	14e. Date (dd/mmm/уууу)
		Bernard Belanger	11/Sep/2014
	Installer Res	Installer Responsibilities	-
This certficate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified.	the part. Julations of a country other than specified in B	llock 1, must ensure that their regulations recogn	ze certifications from the
applicable national regulations before the aircraft may be flown.	y be flown.		



7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7 www.ajw-aviation.com

Tear Down/Inspection Report

Work Order #: WO8843 Date Printed: 11/09/2014 Customer RO: T18599-1

Page: 1

To: A J WALTER AVIATION LTD THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS **UNITED KINGDOM**

Phone #:

Fax #:

Code: AJW01

PN: Z040H0003110

Serial #: 01035

Email:

Qty: 1

Mfg: AIRBUS

TSN: 0

TSO: 0

Descr: Decoder Encoder Unit DEU Type B

TSR: 0

CSN: 0

CSO: 0

NO

CSR: 0

P/N Out: Z040H0003110

Serial # out: 01035

Symptoms:

CODE:

TEST AND RECERTIFY

DETAILS:

Evaluation only. Do not repair before QUOTE is approved.

Faults:

CODE:

QUOTE

DETAILS:

PRELIMINARY INSPECTION (VISUAL):

PART MISSING:

YES

DAMAGE FOUND (CID):

NO

HRS/CYCLE RECEIVED:

NO

ADDITIONAL REQUIREMENT:

AD, SB, MOD, SIL

NO

ADD.CUST. REQUEST

NO

WARRANTY REQUESTED?

NO

TEST ARRIVAL:

INITIAL TEST FAIL? NO

REASON FOR REMOVAL CONFIRMED: NO

DISASSEMBLY/INSPECTION:

ANY ANOMALIES FOUND DURING DISASSEMBLY/INSPECTION

WORK TYPE:

TEST

WORKSCOPE:

CALIBRATION CLEANING **OUT OF SCOPE**

NO NO

OVERHAUL **PAINTING**

NO NO NO



Tear Down/Inspection Report

Work Order #: WO8843 Date Printed: 11/09/2014 Customer RO: T18599-1

Page: 2

7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H45 2B7 www.ajw-aviation.com

NO

PCBR REPAIR **REWORK**

NO NO

TIME CONTROLLED/TX

NO

RE-QUOTE:

NO

CODE:

PARTS MISSING/INCOMPLETE

DETAILS:

Unit came without protective connector covers.

New covers will be install.

CODE:

CUSTOMER REASON FOR REMOVAL CONFIRMATION

DETAILS:

This unit will be tested several times and a visual check will be done for the outside of the unit.

- Test and re-certification only as per customer request .

Corrective Actions:

CODE:

INSPECTION

DETAILS:

UNIT TESTED SEVERAL TIMES WITHOUT ANY FAILURE AND VISUAL CHECK DONE FOR THE OUTSIDE OF THE UNIT.

NEW PROTECTIVE CONNECTOR COVER INSTALLED.

INSPECTED AND TESTED SERVICEABLE IN ACCORDANCE WITH CMM 23-73-47 REV 10 DATED SEP 26/2

	PN	Description		REV 10 DATED SEP 26/2013.		
-	7-10	Description	Reason	Qty Needed	CD	Disposition
	4272-15P	D-TYPE CONNECTOR COVER	MI	1	NE	Consumable
	4272-25S	D-TYPE CONNECTOR COVER	MI	1	NE	Consumable
	4272-50S	D-TYPE CONNECTOR COVER	MI	1	NE	Consumable



7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7 www.ajw-aviation.com

Tear Down/Inspection Report

Work Order #: WO8843 Date Printed: 11/09/2014 Customer RO: T18599-1

Page: 3

REASON LEGEND

- (AD) AD: Part replaced due to Air worthiness Directive that needs to be incorporated. This code will include the last digits of the "AD".
- (BR)* BROKEN: Part found Broken, cracked, crushed, ruptured, split, frayed, deformed. "NOT Customer Induced".
- (BU)* BURNT: Part found burnt, overheated, scorched, seared, blistered, short circuited etc...
- (CID) CUSTOMER INDUCED DAMAGED: Part which is found damaged due to lack of maintenance, incident, mishandling, FOD etc....
- (CO)* CORRODED: Part found corroded, pitted, rusted, decayed, oxidized, powdery and is beyond repair.
- (CM) 100% CMM: Part which is a mandatory replacement as per CMM.
- (CT)* CONTAMINATED: Part found contaminated by foreign object, debris, water, oil etc..." NOT Customer Induced".
- (DE)* DEFECTIVE: Part defective, intermittent or loose
- (DL)* DELAMINATED: Part found delaminated.
- (LE)* LEAKING: Part Leaking, seeping, porous beyond acceptable level as per CMM
- (MI) MISSING: Part missing to complete a unit as per CMM. "Customer responsibility"
- (MO) MODIFICATION: Part requires modification as per CMM or other technical documentation. Part may be modified or replaced with a modified part.
- (NR)* NOT REUSABLE: Part that cannot be reused EX: O-ring, rings, gaskets, packing's, retainers, stripped screws, lock nuts, seals, lock washer.
- (OT)* OUT OF TOLERANCE: Part did not meet the tolerance or calibration as per CMM.
- (RP)* RUPTURED: Part Punctured, ripped, torn, cut, deteriorated. (For Diaphragm, bellows...)
- (RW)* REWORKED: Part reworked, refurbished, machined as per CMM.
- (SB) SB: Part replaced due to Service Bulletin that needs to be incorporated. This code will include the last digits of the "SB"
- (SE)* SEIZED: Part seized.
- (SI) SIL: Part replaced due to Service Information Letter that needs to be incorporated. This code will include the last digits of the SIL.
- (TX) TIME CONTROLED: Part reached the end of its life, it is time expired and may either be overhauled if applicable or replaced due to times or cycles.
- (WO)* WORN: Part scratched, grinded, rubbed, grooved, scrapped, gouged, chipped, abrasion etc....
- (WT) WARRANTY: Part replaced under warranty
- * NORMAL WEAR AND TEAR