


FAA/UNITED STATES		AUTHORIZED RELEASE CERTIFICATE		3. Form Tracking Number: 1043392	
4. Organization Name and Address: Velocity Aerospace - Ft. Lauderdale 5352 NW 21st Terrace Ft. Lauderdale, FL 33309 Ph: 954/772-4559, Fax: 954/493-8960				5. Work Order/Contract/Invoice Number: 04_270356 / T32537	
6. Item		7. Description:		11. Status/Work:	
1		PRESSURE CONTROLLER		REPAIRED	
8. Part Number:		9. Quantity:		10. Serial Number:	
9022-15702-11		1.00		9858613	
12. Remarks: Full details of the work performed indicated in Block 11 are documented on W/O 04_270356					

Technical Data: 21-31-20
Revision#: 13 Revision Date: 6/25/2012

Certifies work specified in Blocks 11/12 was carried out in accordance with EASA Part 145, and with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number EASA.145.4579.

13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13b. Authorized Signature:		14b. Authorized Signature: 	
13c. Approval Authorization No.:		14c. Approval/Certificate No.: WI4R623M	
13d. Name (Typed or Printed):		14d. Name (Typed or Printed): RAFAEL HERNANDEZ	
13e. Date (dd/mm/yyyy):		14e. Date (dd/mm/yyyy): 24-Apr-2019	

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Velocity Aerospace - FT.
Lauderdale
5352 NW 21 Terrace
Ft. Lauderdale, FL 33309

800/422-4559 or 954/772-4559
954/493-8960(Fax)
FAA CRS NO> WI4R623M

WORK ORDER FORM 100

WORK ORDER 04_270356

Entry Date: 4/16/2019
Work Req: REPAIR
PN: 9022-15702-11
Desc.: PRESSURE CONTROLLER
Serial: 9858613
Manuf: -
Model
Mnl Id: NDM002
Cust Ref#: T32537

Bill To
AJ WALTER AVIATION LTD
Accountspayable@ajw-aviation.
WEST SUSSEX RH13 0AS
UNITED KINGDOM
011441403711777(PHONE)
011441403710936(FAX)

Ship To:
AJ WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
WEST SUSSEX
SLINFOLD RH13 0AS
UNITED KINGDOM
011441403711777(PHONE)
011441403710936(FAX)

REASON FOR REMOVAL:

NONE GIVEN

PRELIMINARY INSPECTION:

VERIFIED P/N AND S/N. NO EXTERNAL DAMAGE NOTED.

HIDDEN DAMAGE:

N/A

TEARDOWN FINDINGS:

OPENED UNIT AS REQUIRED FOR VISUAL INSPECTION AND REPAIR. FOUND UNIT CONTAMINATED (DUST). DOWNLOADED AND ANALYZED NVM FAULT BUFFERS AND IS NECESSARY NVM RESET, CLEANING AND REPAIR.

CORRECTIVE ACTION:

THIS UNIT WAS DISASSEMBLED, CLEANED, INSPECTED, REASSEMBLED AND FUNCTIONALLY TESTED I/A/W CURRENT MFRS SPECIFICATIONS. UNIT CONFORMS TO REPAIR.

TECHNICIAN: ROBERTO SOLER

DATE: 04/24/19

CALIBRATION INFORMATION:

NO AD'S. NO AMEND.

FINAL INSPECTION:

THE COMPONENT IDENTIFIED ABOVE WAS SERVICED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION AGENCY REGULATIONS AND FOUND TO BE AIRWORTHY FOR RETURN TO SERVICE.

INSPECTOR SIGNATURE

DATE

CERTIFICATE NUMBER

NEW / OHC / REP / BC / CERTIFIED TO