

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: D 03237488	
4. Organization Name and Address: THE BOEING COMPANY, 737 LOGAN AVE N, RENTON, WA 98057-0000				5. Work Order/Contract/Invoice Number: 3061504	
6. Item: 000001		7. Description: VALVE, CHECK - CAC OUTLET		8. Part Number: 7010105H02	9. Quantity: 2 EA
				10. Serial Number: 2019120263 AND 2019120251	11. Status/Work: NEW
12. Remarks: 5002 AJW		SHIPMENT: 3061504			
AIRWORTHINESS DOCUMENT. THIS FAA FORM 8130-3 CORRECTS THE ERROR IN BLOCK 10 OF THE FAA FORM 8130-3 03237488 DATED 11/JUL/2023 AND DOES NOT COVER CONFORMITY/CONDITION/RELEASE TO SERVICE.					
13a. Certifies the item identified above were manufactured in conformity to: ☒ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.					
13b. Authorized Signature: 		13c. Approval/Authorization No: PC700		14a. ☐ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13d. Name (Typed or Printed): YONGHWAN CHO		13e. Date (dd/mm/yyyy): 28/JUL/2023		14b. Authorized Signature: 14c. Approval/Certificate No:	
				14d. Name (Typed or Printed): 14e. Date (dd/mm/yyyy):	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

Dalit (US), John Michael Vincent A

From: Dalit (US), John Michael Vincent A
Sent: Friday, July 28, 2023 12:25 PM
To: Bajrektarevic (US), Semir; GRP SCLBGSSUPPORT; Noinala (US), Sounanh; Sun (US), Sophan
Subject: Service Request: 270832105

A.J. WALTER AVIATION LIMITED
MAYDWELL AVENUE
THE BUSINESS PARK
LOGISTICS CENTRE
SLINFOLD
WEST SUSSEX
UNITED KINGDOM
RH13 OSH
Byron Napper
Phone Number

44 1403 798363
Order Notification Email
byron.napper@ajw-group.com

THANK YOU,

John Michael Vincent A. Dalit
Quality Systems Specialist
SEATTLE DISTRIBUTION CENTER & REPAIR STATION
Mobile: (206) 637-1632

Dep: 270832105---
Date: 29Jul23
Wgt: 1.00 LBS
CV:
of pkgs: 1
SHIPPING: 13.63
SPECIAL: 2.94
HANDLING: 0.00
TOTAL: 16.57
SVCS: INTL ECONOMY
TRACK: 6151 9842 5067