

1. Approving Civil Aviation Authority/Country Transport Canada		2.		AUTHORIZED RELEASE CERTIFICATE FORM ONE		3. Form Tracking Number: WO9284	
4. Organization Name and Address: AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada				5. Work Order, Contract or Invoice Number: T18935-1			
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:		
1	Drain Mast Controller	Z220H0001110	1.00	00292	REPAIRED		
12. REMARKS Repaired as per CMM 30-71-04 Rev.9 Aug.08/13. For additional information refer to tear down report.							
PRINTED FROM ELECTRONIC FILE							
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12							
EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17							
14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12							
13b. Signature:		13c. Approved Organization Number		14b. Signature		14c. Approval Organization Number	
						33-12	
13d. Name (Typed or Printed):		13e. Date		14d. Name (Typed or Printed) Jacques Moisan		14e. Date (dd/mm/yyyy) 07/Jan/2015	
Installer Responsibilities							
This certificate does not constitute authority to install the part.							
Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.							



technique

Tear Down/Inspection Report

7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7
www.ajw-aviation.com

Work Order #: WO9284

Date Printed: 07/01/2015

Customer RO: T18935-1

Page: 1

To:

A J WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Phone #:

Code: AJW01

Fax #:

PN: Z220H0001110

Serial # : 00292

Email:

Qty: 1

Descr: Drain Mast Controller

Mfg: AIRBUS

TSN: 0

TSO: 0

TSR: 0

CSN: 0

CSO: 0

CSR: 0

P/N Out: Z220H0001110

Serial # out: 00292

Symptoms:

CODE: TEST AND RECERTIFY

DETAILS: Please test and recertify.

Faults:

CODE: QUOTE

DETAILS: PRELIMINARY INSPECTION (VISUAL):

PART MISSING: NO
DAMAGE FOUND (CID): NO
HRS/CYCLE RECEIVED: N/A

ADDITIONAL REQUIREMENT:

AD, SB, MOD, SIL NO
ADD.CUST. REQUEST NO

WARRANTY REQUESTED? NO

TEST ARRIVAL:

INITIAL TEST FAIL? YES

REASON FOR REMOVAL CONFIRMED: UNKNOWN

DISASSEMBLY/INSPECTION:

ANY ANOMALIES FOUND DURING DISASSEMBLY/INSPECTION NO

WORK TYPE: TEST/REPAIR

WORKSCOPE:

CALIBRATION NO



technique

7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7
www.ajw-aviation.com

Tear Down/Inspection Report

Work Order #: WO9284

Date Printed: 07/01/2015

Customer RO: T18935-1

Page: 2

CLEANING		YES
OUT OF SCOPE		NO
OVERHAUL		NO
PAINTING		NO
PCBR		NO
REPAIR		YES
REWORK	NO	
TIME CONTROLLED/TX		NO
RE-QUOTE:		NO

CODE: CLEANING

DETAILS: Cleaning is required due to unit dirty.

CODE: INITIAL TEST FAILURE

DETAILS: Initial test failure is attributed to heater values out of tolerance.

CODE: REPAIR

DETAILS: The following repair(S) will be performed:
Heater values to be adjusted per cmm specs.
Unit to be cleaned.

Corrective Actions:

CODE: REPAIRED

DETAILS: Heater values adjusted per cmm specs.
Unit cleaned.

Repaired as per CMM 30-71-04 Rev.9 Aug,08/13.