


1. Approving Competent Authority / Country AESA SPAIN		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. FORM TRACKING NUMBER MI/23786487	
4. ORGANIZATION NAME AND ADDRESS IBERIA MAINTENANCE Adolfo Suarez Madrid - Barajas Intl. Airport - Zona Industrial No. 2 www.iberiamaintenance.com 28042 MADRID - SPAIN				5. WORK ORDER / CONTRACT / INVOICE 7200705830	
6. ITEM	7. DESCRIPTION	8. PART N°	9. QTY	10. SERIAL No.	11. STATUS / WORK
1	MDDU MULTIPURPOSE DISK DRIVE UNIT	AC68A200	1	2007	INSPECTED/TESTED
12. REMARKS WORKS PERFORMED I.A.W. CMM:31-35-50 REV.4 OCT 2018 Customer: AJW RO: R419635 As per CMM storage chapter, every 6 months check bag and dessicant. Every 3 years complete destorage for a new check and funtional test. Id plate date: 11 O2; Amdt:A counters according customer RO and works performed at Iberia: TSN:Unknown, CSN:Unknown, TSI:Unknown, CSI:Unknown The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate No.ILAY037F. TCCA Approval Number: 898-27 Records of works performed are on file at this maintenance organization under Work Order stated in block 5 13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in condition for safe operation ☐ non-approved design data specified in block 12 13b. AUTHORISED SIGNATURE 13c. APPROVAL/AUTHORISATION NUMBER 13d. DATE(dd/mm/yyyy) 13e. NAME USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer works in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from their airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national 14a. ☒ Part 145.A.50 Release to Service ☒ Other regulation specified in block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with part 145 and in respect to that work the items are considered ready for release to service. 14b. AUTHORISED SIGNATURE N° DE NÓMINA 484643 14c. CERTIFICATE/APPROVAL REF. No. ES.145.011 14d. NAME: ISRAEL GARCÍA AMADOR 14e. DATE (dd/mm/yyyy): 14/DEC/2023					

1. Approving Competent Authority / Country : CAA UK		2. AUTHORISED RELEASE CERTIFICATE CAA FORM 1		3. FORM TRACKING NUMBER. MI/23786486	
4. ORGANIZATION NAME AND ADDRESS IBERIA MAINTENANCE Adolfo Suarez Madrid - Barajas Intl. Airport - Zona Industrial No. 2 www.iberiamaintenance.com 28042 MADRID - SPAIN				5. WORK ORDER / CONTRACT / INVOICE 7200705830	
6. ITEM	7. DESCRIPTION	8. PART N°	9. QTY	10. SERIAL No.	11. STATUS / WORK
1	MDDU MULTIPURPOSE DISK DRIVE UNIT	AC68A200	1	2007	INSPECTED/TESTED
12. REMARKS WORKS PERFORMED I.A.W. CMM:31-35-50 REV.4 OCT 2018 Customer: AJW RO: R419635 As per CMM storage chapter, every 6 months check bag and dessicant. Every 3 years complete destorage for a new check and functional test. Id plate date: 11 02; Amdt:A counters according customer RO and works performed at Iberia: TSN:Unknown, CSN:Unknown, TSI:Unknown, CSI:Unknown					
Records of works performed are on file at this maintenance organization under Work Order stated in block 5					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in condition for safe operation ☐ non-approved design data specified in block 12					
13b. AUTHORISED SIGNATURE		13c. APPROVAL/AUTHORISATION NUMBER		14a. ☒ Part 145.A.50 Release to Service ☐ Other regulation specified in block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with part 145 and in respect to that work the items are considered ready for release to service.	
13d. AUTHORIZED SIGNATURE		13e. DATE(dd/mm/yyyy)		14b. AUTHORIZED SIGNATURE N° DE NÓMINA 484643	
13f. NAME		13g. DATE(dd/mm/yyyy)		14c. CERTIFICATE/APPROVAL REF. No. UK.145.01413	
USER/INSTALLER RESPONSIBILITIES				14d. NAME: ISRAEL GARCÍA AMADOR	
14e. DATE (dd/mm/yyyy): 14/DEC/2023					
This certificate does not automatically constitute authority to install the item(s). Where the user/installer works in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from their airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national					

WORK SHOP REPORT

MAINTENANCE ORGANIZATION EASA PART 145 APPROVAL CERTIFICATE Nº ES.145.011		FAA AIR AGENCY CERTIFICATE NUMBER ILAY037F	
IBERIA WORK ORDER		7200705830	
CUSTOMER		AJ WALTER AVIATION	
CUSTOMER REPAIR ORDER		R419635	
DENOMINATION		MDDU MULTIPURPOSE DISK DRIVE UNIT	

INCOMING DATA		OUTGOING DATA	
INCOMING DATE:	21.NOV.2023	OUTGOING DATE:	14.DEC.2023
INCOMING P/N:	AC68A200	OUTGOING P/N:	AC68A200
INCOMING S/N:	2007	OUTGOING S/N:	2007
MOD IN:	A	MOD OUT:	A
TASK REQUESTED:	REPAIRED	STATUS/WORK PERFORMED:	INSPECTED/TESTED
REASON FOR REMOVAL:	REP		
CMM NUMBER:	31-35-50 REV.4 OCT 2018		
AIRCRAFT TAIL NUMBER:	Not reported		
ENGINE SERIAL NUMBER:	Not reported		
WARRANTY REQUESTED:	NO.	WARRANTY STATUS:	Not applicable
WARRANTY COMMENTS:	Not applicable		

EXTERNAL CONDITION / INCOMING INSPECTION:

Equipment Identification Data	☒ Yes ☐ No
Documentation	☒ Yes ☐ No
Correct config and complete	☒ Yes ☐ No
External misused (Burned, forced,	☐ Yes ☒ No

CORRECTLY PACKED AT INCOMING: YES
TYPICAL SEQUENTIAL TASKS:

Visual Incoming inspection	☒ Yes ☐ No ☐ N/A
Incoming test	☒ Yes ☐ No ☐ N/A
Disassembly	☒ Yes ☐ No ☐ N/A
Cleaning	☒ Yes ☐ No ☐ N/A
NDT Check	☐ Yes ☐ No ☒ N/A
Assembly	☒ Yes ☐ No ☐ N/A
FOD Check inspection	☒ Yes ☐ No ☐ N/A
Final Test	☒ Yes ☐ No ☐ N/A

TYPE OF FAULT:NOT FOUND FAULTY

<http://www.iberiamaintenance.com>**WORK SHOP REPORT****SHOP FINDINGS AND WORKS PERFORMED:**

SHOP FINDING	WORK PERFORMED
VERY DIRTY	INTERNAL AND EXTERNAL CLEANED
NO FAULT FOUND	TESTED I.A.W. CMM

SERVICE BULLETINS: N/A

PARTS REPLACED: N/A

SUBASSYS REPLACED: N/A

REMARKS:

As per CMM storage chapter, every 6 months check bag and dessicant.

Every 3 years complete destorage for a new check and funtional test.

Id plate date: 11 02; Amdt:A

counters according customer RO and works performed at Iberia:

TSN:Unknown, CSN:Unknown, TSI:Unknown, CSI:Unknown