

1. Approving Civil Aviation Authority / Country: FAA/United States		2. Authorized Release Certificate FAA Form 8130-3, Airworthiness Approval Tag			3. Form Tracking Number: R258086	
4. Organization Name and Address: AOG Accessories Inc. 2549 N.W. 74th Ave. Miami FL 33122 USA Phone: 305-591-1899 Fax: 305-489-0176						
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	5. Work Order/Contract/ Invoice Number: 10823
1	TOILET ASSEMBLY	J540AI1-510	1ea.	99011541	REPAIRED	
12. Remarks: REPAIRED in accordance with CMM 38-32-44 Revision 2. Full details of work carried out per work order no. 10823 Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the TOILET ASSEMBLY is considered ready for release to service under EASA Part 145 approval no. EASA 145.5924.						
NO A.D. / S. B. REQUIRED						
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.						
14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.						
13b. Authorized Signature: Not Applicable		13c. Approval/Authorization No: Not Applicable		14b. Authorized Signature: 		14c. Approval/Certificate No: XB4R642M
13d. Name (Typed or Printed): Not Applicable		13e. Date (dd/mm/yyyy): Not Applicable		14d. Name (Typed or Printed): AL Soto		14e. Date (dd/mm/yyyy): 17/Mar/2015
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/aircraft. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/aircraft(s) from the airworthiness authority of the country specified in Block 1. Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

TearDown/Inspection Form

AOG Accessories Inc.

2549 N.W. 74th Ave.

Miami FL 33122

USA

Phone: 305-591-1899 Fax: 305-489-0176

C.R.S. No.: XB4R642M

Work Order: 10823

Date: March/17/2015

Sold To:

AJ WALTER AVIATION, LTD

THE HEADQUARTERS MAYDELL AVE SLINFOLD RH130AS

WEST SUSSEX UNITED KINGDOM

Ship To:

AJ WALTER AVIATION, LTD

THE HEADQUARTERS MAYDELL AVE SLINFOLD RH130AS

WEST SUSSEX UNITED KINGDOM

Part Number: J540A11-510

Serial: 99011541

Manufacturer: AOA

Description: TOILET ASSEMBLY

Model: J540A11-510

Purchase Order: R258086

Service Performed: REPAIRED

Data used: Manual Number: 38-32-44 Revision: 2 Date: 6/8/2004

TearDown/Inspection Data

1.- Trouble Reported: Unknown

Inst.: Repair Only.

Appearance: Normal

Corrosion: No Corrosion Noted.

Loose or Missing Parts: No Loose or Missing Parts.

Physical Damage: No damage found.

2. Teardown

Disassembly: Only as Required for Repair.

Cleaning: Performed cleaning as required

Painting: None Performed.

Assembly: As Required

3. Test

Was Complaint Verified: Yes

Operation: TESTED I/A/W Mfg. Specs.

Modifications: NONE

Other problems found: None Found

4. Final

Warranty Accepted: N/A

Final Test and Inspection:

Final Inspection Normal.

A.D. S.B. NO A.D. / S. B. REQUIRED

5. Work Performed: LRU WAS DISASSEMBLED, CLEANED, INSPECTED AND REPAIRED. PERFORM RETURN TO SERVICE TEST, LRU MEETS MFGS SPECS AND IS READY FOR SERVICE.


Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect to the work performed is approved to return to service. Pertinent details of the work performed are on File at this Agency under Work

Order No.: 10823

Inspector's Name: AL Soto

Technician: Ricardo Mena

Signature: 

Inspector

Date: March/17/2015

Form: AOG 103