

1. Approving Civil Aviation Authority/Country: <b>FAA/UNITED STATES</b>	2. <b>AUTHORIZED RELEASE CERTIFICATE</b> <b>FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG</b>	3. Form Tracking Number: <b>2990-1</b>
--	---	---

4. Organization Name and Address: <b>Ametek MRO Florida Inc. 5900 NW 97th Avenue, Suite 3 Doral, FL 33178 US</b>	5. Work Order, Contract or Invoice Number: <b>Work Order No.: CHY100174 Customer RO.: R277327</b>
---	--

Repair Station No.: **Y9FR104Y**

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	TE FLAP TRANSMISSION	251N4022-32	1.00	SG0266	TESTED

12. REMARKS  
CMM: 27-51-13 Rev: 50 Date: 01-Jul-2015  
ARTICLE HAS BEEN TESTED AND INSPECTED IN ACCORDANCE WITH CURRENT FAA APPROVED TECHNICAL DATA AND FOUND TO BE ACCEPTABLE FOR RETURN TO SERVICE. DETAILED RECORDS ARE ON FILE AT THE REPAIR STATION UNDER THE ABOVE REFERENCED WORK ORDER.

Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number EASA.145.5627.

13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12	14a <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	14b <input checked="" type="checkbox"/> Other regulation specified in Block 12
--	---	--

13b. Authorized Signature:	13c. Approval Authorization No:	14b. Authorized Signature: <i>Alfonso Ojeda</i>	14c. Approval/Certificate No: Y9FR104Y
13d. Name (Typed or Printed):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed): Alfonso Ojeda	14e. Date (dd/mm/yyyy): 23/Sep/2015

**User/Installer Responsibilities**  
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.  
Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.  
Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



**Ametek MRO Florida Inc.**  
5900 NW 97th Avenue, Suite 3  
Doral, FL. 33178  
US

## Tear Down/Inspection

Work Order #: CHY100174

Date Printed: 23-Sep-15

Page: 1 of 1

### To:

ATTN: RICHARD GARDINER  
AVTRADE LTD.  
GLOBAL HEADQUARTERS  
SAYERS COMMON  
WEST SUSSEX BN6 9JQ  
UNITED KINGDOM

### Ship To:

AVTRADE LTD.  
GLOBAL HEADQUARTERS  
SAYERS COMMON  
WEST SUSSEX, BN WEST SUSSEX

Cust.PO Ref.: R277327

Cust.Phone: 011-441-273 833 330

Cust.Email:

Cust.Code: 201176

Cust.Fax: 011-441-273 833 880

Station: ACI

IN. PN: 251N4022-32

Descr: TE FLAP TRANSMISSION

Qty: 1

OUT PN: 251N4022-32

Serial Numbers: SG0266

### Faults:

#### PRELIMINARY INSPECTION

PART NUMBER AND SERIAL NUMBER VERIFIED ON ID PLATE AND RO. NO OBVIOUS EXTERNAL DAMAGE NOTED.  
PART IS CORRECTLY IDENTIFIED PER CMM.

#### HIDDEN DAMAGE

NONE NOTED.

#### SHOP FINDINGS

UNIT WAS TESTED AND PASSED ALL FUNCTIONAL TEST.  
NO DISCREPANCIES NOTED.

#### Corrective Actions:

#### BENCH TEST

ARTICLE HAS BEEN TESTED AND INSPECTED IN ACCORDANCE WITH, CURRENT FAA APPROVED TECHNICAL DATA  
AND FOUND TO BE  
ACCEPTABLE FOR RETURN TO SERVICE. DETAILED RECORDS ARE ON FILE AT THE REPAIR STATION UNDER THE  
ABOVE REFERENCED  
WORK ORDER.

CMM: 27-51-13 Rev: 50 Date: 01-Jul-2015