

1. Approving Competent Aviation Authority / Country:
United Kingdom
Civil Aviation Authority

AUTHORISED RELEASE CERTIFICATE EASA FORM 1

3. Form Tracking Number:
L 1505907

4. Approved Organisation Name and Address:

Panasonic Panasonic Avionics Corporation
Quadrant House, Heron Drive, Parlant Road, Langley Berks, SL3 8XP, UK
Telephone: + 44(0) 1753 741450. Fax: + 44(0) 1753 741481


5. Work Order/Contract/Invoice

W0036910

6. ITEM	7. DESCRIPTION	8. PART NO.	9. ELIGIBILITY*	10. QTY.	11. SERIAL/BATCH NO.	12. STATUS/WORK
1	SEAT ELECTRONICS BOX	RD-AX4331	UNKNOWN	1	234493	<input checked="" type="checkbox"/> INSPECTED/TESTED <input checked="" type="checkbox"/> REPAIRED <input type="checkbox"/> MODIFIED <input type="checkbox"/> MANUFACTURED

13. REMARKS ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 23-34-73 REV 16 DTD NOV 09.

Limited life parts will normally be accompanied by maintenance history including life used.

14. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> approved design data and are in a condition for safe operation. <input type="checkbox"/> non-approved design data specified in block 13.		19. <input checked="" type="checkbox"/> PART 145.A.50 Release to Service <input type="checkbox"/> Other regulation specified in block 13 Certifies that unless otherwise specified in Block 13, the work identified in block 12 and described in block 13, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.	
15. Authorised Signature:		20. Authorised Signature: 	
16. Approval/Authorisation Number		21. Certificate/Approval reference No: UK.145.00297	
17. Name		22. Name Sham Harrar	
18. Date:		23. Date: 11-SEP-10	

Panasonic

Panasonic Avionics CorporationQuadrant House, Heron Drive, Parlaunt Road,
Langley Berks, SL3 8XP, UK.

Tel: +44(0) 1753 741450 Fax: +44(0) 1753 741481

SOLD TO **GERMANIA FLUGGESELLSCHAFT MBH**
RIEDEMANNWEG 58
BERLIN, 13627, DE**REPAIR REPORT / DELIVERY ORDER**SHIP TO **GERMANIA FLUGGESELLSCHAFT MBH**
GEBAUDE N1-HANGAR
FLUGHAFEN BERLIN-TEGEL
BERLIN, 13405, DE

PAGE 1 of 1

SHIP TRANSACTION:

CUSTOMER P.O. NUMBER W0036910		CUSTOMER 1230	TAIL NO. NOT GIVEN	CUST PROD REF 2863648	SERVICE REQUEST 2118567	
PART NUMBER RD-AX4331	NOMENCLATURE SEAT ELECTRONICS BOX			DATE REMOVED	DATE RECEIVED 25-AUG-2010	
SERIAL NUMBER 234493	DATE OF MFG 30-JUN-1997	WTY START DATE 30-JUN-1997	WTY END DATE 30-DEC-2000	DATE REPAIRED 09-SEP-2010	SHIP DATE	
MOD IN 1,5,7,8						
REASON FOR CUSTOMER REJECTION	FAILED EX STORE. AISLE CHANNEL DEFECT. PLEASE REPAIR ON WARRANTY. WITH REFER TO LAST SHOP VISIT R1895210					
INTERNAL INSPECTION	No Physical Damage					
EXTERNAL INSPECTION	No Physical Damage					
ACTUAL FAILURE / CORRECTIVE ACTION	STRIPPED AND CLEANED. FAILED ON TEST. IC5 FAULTY. FAULT NOT RELATED TO PREVIOUS SERVICE. REPLACED IC5. UNIT CLEANED, TESTED AND PASSED ALL FUNCTIONAL TESTS. ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 23-34-73 REV 16 DTD NOV 09.					

MOD OUT: 1,5,7,8

INSPECTED BY: **Sham Harrar**REPAIRED BY: **BLACKWELL, GARY**

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	EXTENDED PRICE	CHARGED AMOUNT	WTY*
CUST LABOR R2IUPC339T	OUT OF WARRANTY CHARGE IC, LINEAR	210 1	1.92 4.25	402.50 4.25	402.50 4.25	NO

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

Cost of Labor	402.50
Cost of Material	4.25
Total Cost	406.75

* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged