


1. Approving National Aviation Authority / Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, Airworthiness Approval Tag				3. Form Tracking Number: 7277	
4. Organization Name and Address: General MRO AeroSpace, Inc. 3064 N.W. 72 Ave Miami, FL 33122 USA Phone: 305 482-9903 Fax: 305 482-9905 C.R.S.: 19GR994Y						5. Work Order / Contract / Invoice Number: 165744	
6. Item:	7. Description:	8. Part Number:	9. Eligibility*:	10. Quantity:	11. Serial / Batch Number:	12. Status/Work:	
1	Mechanism Assy	65-54200-8	N/A	1ea.	287	REPAIRED	
13. Remarks: REPLACED PARTS AS LISTED IN TEARDOWN REPORT. UNIT HAS BEEN REPAIRED IN ACCORDANCE WITH CURRENT BOEING CMM 27-16-05 REV 15 DTD JULY 01, 2011. COMPONENT IS READY TO RETURN TO SERVICE. Certifies that the work specified in block 12/13 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: "EASA.145.6095".							
14. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 13.			19. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 13 Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block B was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.				
15. Authorized Signature: Not Applicable		16. Approval/Authorization No.: Not Applicable		20. Authorized Signature: 		21. Approval/Certificate No.: 19GR994Y	
17. Name (Typed or Printed): Not Applicable		18. Date (m/d/y): Not Applicable		22. Name (Typed or Printed): Cristian Munoz		23. Date (m/d/y): Nov/21/2011	
User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1. Statements in Block 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							



3064 NW 72 Avenue Miami FL 33122
Phone: 305-482-9903
Fax: 305-482-9905
FAACRS# 19GR994Y

Work Order: 7277

Date: November/21/2011



TearDown/Inspection Form

Sold To: AJW AVIATION LTD

Purchase Order: 165744

Part Number: 65-54200-8

Serial: 287

Description: Mechanism Assy

Model: 65-54200-8

Reason for Removal: Unknown TSN: N/A TSO: N/A TSR: N/A

Incoming Inspection

Preliminary: UNIT ARRIVED DIRTY

Date: 11/21/2011

Hidden Damage: NONE FOUND

Date: 11/21/2011

N.D.T. Performed: NDT WAS NOT PERFORMED

Teardown Report :

UNIT ARRIVED WITHOUT NAMEPLATE. VERIFIED UNIT THROUGH CMM. INSPECTED & TESTED I/A/W MFG SPECS. FOUND TORN LABELS & MISSING HARDWARE. UNIT REQUIRES MENTIONED PARTS FOR REPAIR.

Technician: Manuel A Hernandez

Date: November/21/2011

Modifications S.B./ A.D./ E.O. performed: NONE

Work Done: REPLACED PARTS AS LISTED IN TEARDOWN REPORT. UNIT HAS BEEN REPAIRED IN ACCORDANCE WITH CURRENT BOEING CMM 27-16-05 REV 15 DTD JULY 01, 2011. COMPONENT IS READY TO RETURN TO SERVICE.

Removal response verified?: N/A Response: N/A

In accordance with Mfg's specs. /A.T.A. No.: 27-16-05 Rev. Date: 7/1/2011 Revision: 15

Remarks: No Remarks

Maintenance Release Statement (FAR Parts 121, 125 and 135)

The Instruments and/or Components above was Serviced and Inspected with Pride and in accordance with current F.A.A. Regulations and is ☒ Approved ☐ Not approved to Return to Service. Pertinent details of the Services are on files at this Repair Station under Work Order No.: 7277

Signature:

Cristian Munoz

Inspector Seal

Date: November/21/2011

Form GMA 340