



1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 257373	
4. Organization Name and Address: Aero Accessories & Repair, Inc. FAA CERT #77AR783B 15501 SW 29TH ST. SUITE#201 MIRAMAR, FL 33027 Ph: 954-266-1300,		5. Work Order/Contract/Invoice Number: 61409 T42555		6. Status/Work: REPAIRED	
7. Description: 1 VALVE ASSY, MOTOR OPERATED		8. Part Number: 2960035-101		9. Quantity: 1	
10. Serial Number: T97162		11. Status/Work: REPAIRED			

12. Remarks:
The component identified above was REPAIRED in accordance with Federal Aviation Regulation and is approved for return to service with respect to the work performed.
Pertinent details of the work accomplished are on the file at this agency under Form Tracking Number identified above.
S/B and A/D: None Applicable.
OEM CMM: 29-11-11, Revision#: 10, Revision Date: 12/9/2014

ORIGINAL

Certifies work specified in blocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the component is considered ready for release to service under EASA part 145 Approval Number EASA 145-6467

13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13b. Authorized Signature: 		14b. Authorized Signature: 	
13c. Approval Authorization No.:		14c. Approval/Certificate No.: 77AR783B	
13d. Name (Typed or Printed):		14d. Name (Typed or Printed): WELCEMEN B. JEANNOT	
13e. Date (dd/mm/yy):		14e. Date (dd/mm/yy): 21-Nov-2023	

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.
Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.
Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

**Aero Accessories & Repair, Inc.**

FAA CERT #77AR783B
15501 SW 29TH ST. SUITE#201
MIRAMAR, FL 33027
Ph: 954-266-1300,

Work Order**Work Order #: 61409**

Date Printed: 11/21/2023

Time: 2:02:20 PM

Page: 1

To:

AJW AVIATION LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, SLI RH13 0AS
UNITED KINGDOM

Ship To:

AJW AVIATION LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WS RH13 0AS
UNITED KINGDOM

Ref #: T42555

Phone #: 305 470 8007

Fax #: 441.403.710.936

Email: louise@ajw-group.com

Code: 45

Site: JM/DV

PN: 2960035-101

Descr: VALVE ASSY, MOTOR OPERATED

Qty: 1

Station: HYDRAULIC

Make:

Model:

Mfg: ITT

Repair Manual(s): 29-11-11 Rev: 10 Rev. Date: 12/9/2014

Entry Date: 11/10/2023

Need Date: 11/24/2023

Compl. Date: 11/21/2023 2:02

Warranty: No

Container:

Serial Numbers:

T97162

RECEIVING INSPECTION

P/N and S/N verified on unit and customer RO. No external damage noted. See RO for work scope. Technician must verify.

PRELIMINARY INSPECTION

P/N 2960035-101 verified IAW technical reference data listed above.

S/N T97162 verified through ID Plate and customer RO.

No AD'S applicable for the unit at this time.

TSN: UNK CSN: UNK

TSO: UNK CSO: UNK

HIDDEN DAMAGE

None noted.

Tech: AL 123

INITIAL FINDINGS

Unit failed functional check IAW technical data referenced above.

Reason: Externally Leaking.

Customer Complaint: N/A

Tech: AL #123

TEARDOWN FINDINGS

Unit partially disassembled, cleaned and inspected IAW technical data referenced above. Unit requires replacement of all packings, seals and retainers removed during disassembly. The following part(s) require replacement: connector -corroded. Minor nicks, scratches and dents do not affect fit, form, or function of the unit.

Unit will be Repaired.

Tech: AL #123

CORRECTIVE ACTION

All parts listed in Teardown Report were replaced and findings listed were corrected. Unit was repaired and tested IAW technical data reference above.

Tech: AL #123

Authorized Signature: _____

Name: WELCEMEN JEANNOT

Date: 11/21/2023