| 1. Approving Civil Aviation Authority/Country | 2. | 3. Form Tracking Number. |
|---|---|---|
| **Transport Canada** | **AUTHORIZED RELEASE CERTIFICATE** *FORM ONE* | **WO48439** |

4. Organization Name and Address.

**AJW Technique Inc**
**7055, rue Alexander Fleming**
**Saint-Laurent QC H4S-2B7**
**Canada**

AJW technique

5. Work Order, Contract or Invoice Number:

**R314530-1**

| 6. Item: | 7. Description: | 8. Part Number: | 9. Quantity: | 10. Serial/Batch Number: | 11. Status/Work: |
|---|---|---|---|---|---|
| 1 | CFDIU | B401ACM0507 | 1.00 | 738 | INSPECTED/TESTED |

12. REMARKS

UNIT TESTED SERVICEABLE AS PER CMM 31-32-34A REV N: 9 DATED FEB 03 /2006. FOR MORE INFORMATION REFER TO TEAR DOWN REPORT.

***PRINTED FROM ELECTRONIC FILE***

EASA Approval No.: EASA.145.7260
Maintenance performed in accordance with FAR 43.17

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.

☒ CAR 571.10 Maintenance Release

☒ Other regulation specified in Block 12

| 13b. Signature: | 13c. Approved Organization Number | 14b. Signature | 14c. Approval Organization Number |
|---|---|---|---|
| | | | **33-12** |
| 13d. Name (Typed or Printed): | 13e. Date | 14d. Name (Typed or Printed) | 14e. Date (dd/mmm/yyyy) |
| | | Aili Abdeljalil | 31/Mar/2017 |

**Installer Responsibilities**

This certficate does not constitute authority to install the part.

Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified.
Statements in blocks 13a or 14a do not constitute installation certification. In all cases,the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

AJW technique

7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7
www.ajw-aviation.com

# Tear Down/Inspection Report

**Work Order #: WO48439**
**Date Printed:** 31/03/2017
**Customer RO:** R314530-1
**Page:** 1

**To:**
**A J WALTER AVIATION LIMITED**
**THE HEADQUARTERS**
**MAYDWELL AVENUE**
**SLINFOLD, WEST SUSSEX RH13 0AS**
**UNITED KINGDOM**

**Phone #:** **Fax #:** **Email:**
**Code:** AJW01 **PN:** B401ACM0507 **Serial # :** 738 **Qty:** 1
**Descr:** CFDIU **Mfg:** THALES

**TSN:** UNK **TSO:** UNK **TSR:** 0 **CSN:** UNK **CSO:** UNK **CSR:** 0

**P/N Out:** B401ACM0507 **Serial # out:** 738

**Symptoms:**

CODE: REPAIR
DETAILS: REPEATEDLY DROPPING TO BACK UP MODE. AMBER XX INSTEAD OF TIME.

**Faults:**

CODE: QUOTE
DETAILS: PRELIMINARY INSPECTION (VISUAL):

| | |
|---|---|
| PART MISSING: | NO |
| DAMAGE FOUND (CID): | NO |
| HRS/CYCLE RECEIVED: | N/A |

ADDITIONAL REQUIREMENT:

| | |
|---|---|
| AD, SB, MOD, SIL | NO |
| ADD.CUST. REQUEST | NO |

WARRANTY REQUESTED? NO

TEST ARRIVAL:

INITIAL TEST FAIL? NO

REASON FOR REMOVAL CONFIRMED: NO

DISASSEMBLY/INSPECTION:

ANY ANOMALIES FOUND DURING DISASSEMBLY/INSPECTION NO

WORK TYPE: TEST

WORKSCOPE:

| | |
|---|---|
| CALIBRATION | NO |
| CLEANING | NO |
| OUT OF SCOPE | NO |
| OVERHAUL | NO |
| PAINTING | NO |

*Form created with Quantum Control(tm) technology. Product Licensed to: AJW Technique Inc.*

| | | |
|---|---|---|
| PCBR | | N/A |
| REPAIR | | NO |
| REWORK | NO | |
| TIME CONTROLLED/TX | | NO |
| RE-QUOTE: | | NO |

CODE: NO FAULT FOUND

DETAILS: Unit pass the acceptance test on ATEC6.
No fault found.

**Corrective Actions:**

CODE: INSPECTED/ TESTED

DETAILS: UNIT TESTED SERVICEABLE AS PER CMM 31-32-34A REV N: 9 DATED FEB 03 /2006. FOR MORE INFORMATION REFER TO TEAR DOWN REPORT.