

1. Approving Competent Authority/Country FEDERAL OFFICE OF CIVIL AVIATION (FOCA) SWITZERLAND		2.		AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 86930135-10300	
4. Organisation Name and Address Meggitt SA Route de Moncor 4, CH-1752 Villars-sur-Glâne, Switzerland Phone: +41 (0)26 407 11 11 Fax: +41 (0)26 407 18 60				5. Work Order/Contract/Invoice Notification: 350565286 PO: T42411/LCB133 Item:			
6. Item	7. Description	8. Part No.	9. Qty	10. Serial No.	11. Status / Work		
1	EIVMU ASSEMBLY (A330/RR)	271-200-027-305	1	4590	INSPECTED / TESTED		
12. REMARKS This document has been issued according to an approved computer generated signature procedure. The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for release or return to service under certificate no. VM8Y694J. SN:(4590);MOD Strike:12,17 Applicable Technical Docs: CMM 73-25-37 REV. 7 DATED MAY 26/2020 For work carried out, refer to Service Breakdown Report for Service Order 45462082							
13a. Certifies that the items identified above were manufactured in conformity to ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in Block 12		14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part -145 and in respect to that work the items are considered ready for release to service					
13b. Authorised Signature		13c. Approval/Authorisation Number		14b. Authorised Signature  VM - CS COA - 14 V. De Campos		14c. Certificate/Approval Ref No. CH.145.0251	
13d. Name		13e. Date (dd mmm yyyy)		14d. Name VICTOR DE CAMPOS		14e. Date (dd mmm yyyy) 06NOV2023	

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1. Approving Competent Authority/Country CAA/UK		2.		AUTHORISED RELEASE CERTIFICATE CAA FORM 1		3. Form Tracking Number 86930135-10300	
4. Organisation Name and Address Meggitt SA Route de Moncor 4, CH-1752 Villars-sur-Glâne, Switzerland Phone: +41 (0)26 407 11 11 Fax: +41 (0)26 407 18 60				5. Work Order/Contract/Invoice Notification: 350565286 PO: T42411/LCB133 Item:			
6. Item	7. Description	8. Part No.	9. Qty	10. Serial No.	11. Status / Work		
1	EIVMU ASSEMBLY (A330/RR)	271-200-027-305	1	4590	INSPECTED / TESTED		
12. REMARKS This document has been issued according to an approved computer generated signature procedure. SN:(4590);MOD Strike:12,17 Applicable Technical Docs: CMM 73-25-37 REV. 7 DATED MAY 26/2020 For work carried out, refer to Service Breakdown Report for Service Order 45462082							
13a. Certifies that the items identified above were manufactured in conformity to ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in Block 12				14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part -145 and in respect to that work the items are considered ready for release to service			
13b. Authorised Signature		13c. Approval/Authorisation Number		14b. Authorised Signature  VM - CS COA - 14 V. De Campos		14c. Certificate/Approval Ref No. UK. 145.01715	
13d. Name		13e. Date (dd mmm yyyy)		14d. Name VICTOR DE CAMPOS		14e. Date (dd mmm yyyy) 06NOV2023	

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

**MEGGITT**

Service Breakdown Report

Sold to
A.J.WALTER AVIATION
The Headquarters
Maydwell Avenue, Slinfold
WEST SUSSEX
RH13 0AS
UNITED KINGDOM

Page 1 of 2
Date 02.11.2023
Service notification 350565286
Meggitt quality notification
Service order/Report No 45462082
Sales order 9953492990
Customer PO# T42411/LCB133
Customer quality ref
Customer Part#

Equipment serviced here

Item	Part number/ Description	Serial number	Mod Status/Revision
1	271-200-027-305 Engine Interface and Vibration Monitoring Unit (EIVMU) Applicable Technical Docs:	4590	12,17 / - CMM 73-25-37 REV. 7 DATED MAY 26/2020

Failure / complaint (as reported by customer)

FOR TEST:
UNDER T&M
REMOVED IN SERVICEABLE CONDITION
A/C REG: @@A6-EYH@@
EASA/FAA/UK CAA

Findings

Seal(s) ok and no physical damage has been noticed.
No internal failure detected in memory at reception.
Self test is pass.
Unit works within specifications.
No fault found.
Warranty not applicable.

Materials

Item	Qty	UOM	Part Number	Batch Number	Description	Cond
------	-----	-----	-------------	--------------	-------------	------

Work performed

Incoming Inspection (Admin)
Preliminary hidden damage inspection
SB/SIL/AD status check performed
Visual Inspection
Confirm Customer complaint - NA
Check connectors condition
Read & Analyze Internal Memory
Incoming ATP Technician
Incoming ATP Test System
Inspected IAW CMM listed above
Final ATP Technician

Meggitt SA, Rte. de Moncor 4, PO Box, CH-1701, Fribourg, Switzerland

VAT Number: CHE-107.769.496 TVA Custom Account: 1065-1
GST 10-2364-0691-TQ0001 GST 890 368 079 RT0001 Customs 890 368 079 RM0001


Tel: +41 (0) 26 407 11 11
Fax: +41 (0) 26 407 17 00
www.meggitt.com

Service Breakdown Report

Sold to
A.J.WALTER AVIATION
The Headquarters
Maydwell Avenue, Slinfold
WEST SUSSEX
RH13 0AS
UNITED KINGDOM

Page 2 of 2
Date 02.11.2023
Service notification 350565286
Meggitt quality notification
Service order/Report No 45462082
Sales order 9953492990
Customer PO# T42411/LCB133
Customer quality ref
Customer Part#

Final ATP Test System
Final FOD check
Administration





Meggitt SA, Rte. de Moncor 4, PO Box, CH-1701, Fribourg, Switzerland

VAT Number: CHE-107.769.496 TVA Custom Account: 1065-1
GST 10-2364-0691-TQ0001 GST 890 368 079 RT0001 Customs 890 368 079 RM0001

Tel: +41 (0) 26 407 11 11
Fax: +41 (0) 26 407 17 00
www.meggitt.com

TEST REPORT

Subject: ACCEPTANCE TEST REPORT
Item: Engine Interface and Vibration Monitoring Unit
Type: EIVMU-101
MFR: S3960
PNR: 271-200-027-305
Cust. PNR: 63-9581-24-00
Mod. Record: 12,17
SER: 004590
DMF: 042015
Applicable Doc.: ATP-1046-07 rev-02
Software PNR: 299-500-000-015
Database PNR: 299-506-520-302
AU SER: AH76031
Operator: JEME
Test Result: **PASS**
Started: 23 Oct 2023 10:09:41
Finished: 23 Oct 2023 10:47:14
Report generated: 23 Oct 2023 10:47:14
Report Location: \\ngts\atr\atp1046_07r02_eivmu305/P-004590-20231023-104759.html
GTS Hostname: gtsxp0040
Comment:

Signature: 
Department Approval: 
Date of Approval: 23 OCT. 2023