

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG			3. Form Tracking Number G9465	
4. Organization Name and Address: Velocity Aerospace - Burbank, Inc. 2840 N. Ontario Street Burbank, CA 91504 Ph: 818-333-5600,					5. Work Order/Contract/Invoice Number: T35703	
Repair Station Cert. # RB1R197K					11. Status/Work: REPAIRED	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:		
1	SMOKE DETECTOR	CGDU2000-00	1	2230		
12. Remarks: All work has been accomplished in accordance with FAA approved data: CMM: 26-16-17 Rev: 6 Dated: 3/25/2009 C/W SIL-26-GASKET-CGDU						
Certified that the work specified in block 11/12 was carried out in accordance with EASA PART 145 and in respect to that work the component is considered ready for release to service under EASA Part 145 approval no. EASA.145.4002. For complete details of work accomplished reference tracking number in block (3) three or as attached.						
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.				
13b. Authorized Signature:		13c. Approval Authorization No.:		14b. Authorized Signature:		14c. Approval/Certificate No.: RB1R197K
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14d. Name (Typed or Printed): Jose Ramon Flores		14e. Date (dd/mm/yyyy): 19/Oct/2021
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

**Velocity Aerospace - Burbank, Inc.**

2840 N. Ontario Street
Burbank, CA 91504
Ph: 818-333-5600,

Repair Station: RB1R197K FAA/EASA.145.4002

RECAP**Work Order #: G9465**

Date Printed: 10/19/2021

Time: 8:07:16 AM

Page: 1

To: AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVE, SLINFOLD
WEST SUSSEX RH13 0AS UK
payableinvoices@ajw-group.com, UNITED
KINGDOM

Ship To: AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVENUE, SLINFOLD
WEST SUSSEX, RH13 0AS
UNITED KINGDOM

Ref #: T35703

Phone #: 441403711414

Fax #:

Email: chris.copestake@ajw-aviation.com

Mfg: SIEMENS SAS

Serial #: 2230

PN: CGDU2000-00

Descr: SMOKE DETECTOR

ATA Chapter: 26-16-17

Revision #: 6

Revision Date: 3/25/2009

Test Record: 2423

Technician: CURQUILLA

Type:

Entry Date: 10/11/2021

Need Date: 10/19/2021

Compl. Date: 10/19/2021 8:06:46 AM

Container:

Warranty: No

Symptoms:

WORKSCOPE: TEST

REASON FOR REMOVAL

FOR TEST AND RECERT
A/C REG - FROM STOCK
MODS IN

A

Faults:

NO COMPLAINT GIVEN

PRELIM TEST & EXAM

Unit passed FT.
TEARDOWN INSPECTION

Opened unit, dusty inside. Labyrinth assembly and housing requires cleaning. Unit requires modification of gasket per SIL-26-GASKET-CGDU.
Corrective Actions:

FINAL DISPOSITION: RP

FINAL WORK ACCOMPLISHED

Replaced part listed, cleaned labyrinth assembly and housing. Inspected components and wiring. Assembled, calibrated, and F/T unit to mfg's specs.
C/W SIL-26-GASKET-CGDU

MODS OUT

A

TEST EQUIPMENT:

ABI1620 ABI835 ABI834A ABI1846 ABI1759 ABI1787

Parts

PN	Description	Qty Issued	CD
1500008	GASKET	1	NE

Final Inspector Signature: Jose Ramon Flores Certificate number: 4372619