



1. Approving Competent Authority/Country Civil Aviation Authority United Kingdom		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 27038	
4 Approved Organisation Name and Address REHEAT INTERNATIONAL LTD Riverside, Omega Park, Alton, Hampshire GU34 2UF Tel +44 (0)1420 594000 Fax: +44 (0)1420 594001				5. Work Order/Contract/Invoice 024794/00	
6. Item	7. Description	8. Part Number	9. Qty	10. Serial/Batch No.	11. Status/Work
01	DOUBLE OVEN	HE61070MOD4	1 EA	115509	Repaired
12. Remarks The Unit has been disassembled, cleaned, inspected, repaired as necessary and reassembled, it has been tested in accordance with approved standards and technical data REPAIRED IAW CMM 25-31-78 REV 1 DATED 24/SEP/99 FOR AJ WALTER AVIATION REPAIR ORDER: 145898					
Transport Canada CAR 571 Maintenance Release Certifies that unless otherwise specified in block 12, the work identified in block 11 was performed in accordance with CAR 571					
14 CFR 43.9 Return to Service Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12 was accomplished in accordance with Title 14, Code of Federal Regulations Part 43 and in respect to that work, the items are approved for return to service					
13a. Certifies that the items identified above were manufactured in conformity to: [] approved design data and are in condition for safe operation [] non-approved design data specified in block 12		Authorised Signature 	Certificate/Approval Ref No. 807-12	Authorised Signature 	Certificate/Approval Ref No. RHUY491X
		Name P. Vince	Date (d/m/y) 30 NOV 2011	Name RHI 11	Date (d/m/y) 30 NOV 2011
13b. Authorised Signature		14a. [x] Part-145A.50 Release to Service Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12 was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service		Other Regulation specified in block 12	
13c. Approval /Authorisation Number		14b. Authorised Signature 		14c. Certificate/Approval Ref No. UK.145.00472	
13d. Name		14d. Name P. Vince		14e. Date (d/m/y) 30 NOV 2011	
13e. Date (d/m/y)					
Note: USER/INSTALLER RESPONSIBILITIES 1. This certificate does not automatically constitute authority to install the item(s) 2. Where the user/installer performs works in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in Block 1 it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1 3. Statements in 13a and 14a do not constitute installation certification. In all cases aircraft maintenance record must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown					



INSPECTION RECORD CARD WORKSHOP WORKSHEET

MAINTENANCE RELEASE EASA: UK.145.00472

CERTIFIES THAT THE WORK SPECIFIED EXCEPT AS OTHERWISE SPECIFIED WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND WITH RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE

AUTHORISED SIGNATURE	REHEAT INTERNATIONAL APPROVAL STAMP
	NO: RHI 07
NAME: G. Pocock	DATE: 29 NOV 2011

MAINTENANCE RELEASE FAA: RHUY491X

THE AIRCRAFT/ENGINE/PROPELLER OR APPLIANCE IDENTIFIED HEREWITH WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE WITH RESPECT TO THE WORK CARRIED OUT. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER RHI ORDER NUMBER

AUTHORISED SIGNATURE	REHEAT INTERNATIONAL APPROVAL STAMP
	NO: RHI 07
NAME: G. Pocock	DATE: 29 NOV 2011

TRANSPORT CANADA MAINTENANCE RELEASE TCCA: 807-12

CERTIFIES THAT THE WORK SPECIFIED UNLESS OTHERWISE SPECIFIED WAS CARRIED OUT IN ACCORDANCE WITH CAR 571 AND WITH RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE

AUTHORISED SIGNATURE	REHEAT INTERNATIONAL APPROVAL STAMP
	NO: RHI 07
NAME: G. Pocock	DATE: 29 NOV 2011

CARD 1 OF 10	CUSTOMER NAME/ OWNERSHIP AJ WALTER AVIATION	MANUFACTURER'S PART NO HE61070MOD4
MOD STATUS MOD 4		SERIAL NUMBER 115509
SPECIAL INSTRUCTIONS NONE		DESCRIPTION DOUBLE OVEN
		A/C REGISTRATION N/K
		RHI ORDER NUMBER 024794/00
		CUSTOMER ORDER NO 145898
		DATE ITEM RECEIVED 16-Feb-11
		C.M.M. REF NO 25-31-78
		C.M.M. REV. 1 DATED: 24/SEP/99 EFF. CODE: ---
		ADDITIONAL C.M.M.: MOTOR
		C.M.M. REF NO: 25-30-52
		C.M.M. REV. 3 DATED: 22/JUN/94 EFF. CODE: A
		DATE OF LAST SHOP VISIT: None
		COPY OF LAST JOB CARD YES (NO)
		LEVEL OF MAINTENANCE REQUIRED REPAIR
		EASA FORM 1 BLOCK 11 STATEMENT nspain

ADDITIONAL DATA


NOTES:



Inspection Record Card

Workshop Continuation Worksheet

Card 2 of 10	RHI ORDER NUMBER: 024794/00	CUSTOMER ORDER NUMBER: 145898
	WORK TO BE DONE	WORK CARRIED OUT
1	CONFIRM PART NUMBER AND SERIAL NUMBER ON DATA PLATE	PART NUMBER: 14E 610704MOD4- SERIAL NUMBER: 115509
2	CARRY OUT VISUAL INSPECTION	Visual Carried out.
3	CARRY OUT PRE-TEST, RECORD DATA IN ACCORDANCE WITH THE COMPONENT MAINTENANCE MANUAL (RE-TEST IF REWORK HAS BEEN CARRIED OUT)	UNABLE TO PRE-TEST MOTOR SEIZED
4	IF A FULL PRE-TEST IS NOT POSSIBLE CARRY OUT STATIC TESTS IF APPROPRIATE TO IDENTIFY DEFECTS	OWNERS PROVIDED UP. CARRY DEFECTS IDENTIFIED
5	CHECK APPLICABLE AD'S AND SB'S FOR COMPLIANCE UPON COMPLETION OF WORK	APPLICABLE AIR WORTHINESS DIRECTIVES AND SERVICE BULLETINS CHECKED FOR COMPLIANCE
6	REMOVE COVERS AND CARRY OUT VISUAL INSPECTION	COVERS REMOVED AND VISUAL INSPECTION CARRIED OUT.



Inspection Record Card Workshop Continuation Worksheet

Card 3 of 10	RHI ORDER NUMBER: 024794/00	CUSTOMER ORDER NUMBER: 145898
WORK TO BE DONE		WORK CARRIED OUT
7	CARRY OUT INSPECTION OF OVER ANCHOR POINTS	ANCHOR POINTS INSPECTED
8	FRONT LEFT ANCHOR FIXING PLATE CORRODED - RENEW PLATE	PLATE REPLACED
9	LEFT CAVITY MOTOR SEIZED - DISMANTLE MOTOR AND CARRY OUT INSPECTION	MOTOR INSPECTED
10	LEFT MOTOR BEARINGS SEIZED - RENEW BEARINGS	BEARINGS REPLACED
11	LEFT MOTOR SHAFT SEIZED - RENEW SHAFT	SEAL REPLACED
12	LEFT CAVITY DOOR HANDLE MISSING - RENEW HANDLE AND RELATED COMPONENTS	HANDLE AND RELATED COMPONENTS REPLACED


Mech	NEIL
Insp	RHI 08
Date	28 FEB -11
Mech	NEIL
Insp	RHI 07
Date	29-11-11
Mech	NEIL
Insp	RHI 08
Date	28 FEB -11
Mech	NEIL
Insp	RHI 07
Date	25-11-11
Mech	NEIL
Insp	RHI 07
Date	25-11-11
Mech	NEIL
Insp	RHI 07
Date	28-11-11



Inspection Record Card Workshop Continuation Worksheet

Card 4 of 10	RHI ORDER NUMBER: 024794/00	CUSTOMER ORDER NUMBER: 145893
WORK TO BE DONE		WORK CARRIED OUT
13	LEFT Cavity DOOR SEAL TORN AND SECTION MISSING - REVIEW SEAL	Door Seal Replaced.
14	DISMANTLE LEFT DOOR ASSEMBLY AND CARRY OUT INSPECTION	DOOR DISMANTLED AND INSPECTED
15	LEFT DOOR INNER FRAME ANCHOR NUTS CORRODED/MISSING - RENEW ANCHOR NUTS AND RIVETS	ANCHOR NUTS AND RIVETS REPLACED.
16	LEFT DOOR INSULATIONS. DETERIORATED - RENEW INSULATION	INSULATION REPLACED.
17	LEFT DOOR PANEL - OUTER CORRODED - RENEW DOOR PANEL	Left Door Panel Replaced.
18	LEFT DOOR DECOR PANEL TORN - RENEW DECOR PANEL	Decor Panel Replaced.

Mech	Insp	Date
NEIL	RHI 07	28-11-11
Mech	Insp	Date
NEIL	RHI 08	28-FEB-11
Mech	Insp	Date
NEIL	RHI 07	28-11-11
Mech	Insp	Date
NEIL	RHI 07	28-11-11
Mech	Insp	Date
NEIL	RHI 07	28-11-11
Mech	Insp	Date
NEIL	RHI 07	28-11-11




Inspection Record Card

Workshop Continuation Worksheet

Card 5 of 10	RHI ORDER NUMBER: 024794/00	CUSTOMER ORDER NUMBER: 145898
WORK TO BE DONE		WORK CARRIED OUT
19	LEFT DOOR COUNTERSINK SCREWS WORN - RENEW SCREWS AND INTERFACE WASHERS	SCREWS AND INTERFACE WASHERS REPLACED.
20	LEFT DOOR INNER PANEL STATE - RENEW INNER PANEL	INNER PANEL REPLACED.
21	LEFT DOOR HINGE INTERFACE WASHERS DAMAGED / MISSING - RENEW WASHERS.	INTERFACE WASHERS REPLACED.
22	LEFT CAVITY, Baffle Plate DISTORTED AND CONTAMINATION - RENEW PLATE	Baffle Plates REPLACED.
23	LEFT DOOR HINGE PIN BROKEN - RENEW HINGE BRACKET.	HINGE BRACKET REPLACED.
24	LEFT AND RIGHT CAVITY DOOR HINGE SECURING SCREWS WORN - RENEW SCREWS	SCREWS RENEWED.

Mech	Insp	Date
NEIL	RHI 07	29-11-11
NEIL	RHI 07	29-11-11
NEIL	RHI 07	28-11-11
NEIL	RHI 07	28-11-11
NEIL	RHI 07	29-11-11
NEIL	RHI 07	29-11-11
NEIL	RHI 07	29-11-11
NEIL	RHI 07	29-11-11



Inspection Record Card Workshop Continuation Worksheet

Card 6 of 10	RHI ORDER NUMBER: 024794/00	CUSTOMER ORDER NUMBER: 145898
WORK TO BE DONE		WORK CARRIED OUT
25	RIGHT CAVITY DOOR SEAL TORN -RENEW SEAL	Door Seal Replaced.
26	DISMANTLE RIGHT DOOR ASSEMBLY AND CARRY OUT INSPECTIONS	DOOR DISMANTLED AND INSPECTED
27	RIGHT DOOR HANGING SPRING BUSHES AND SCREW MISSING - RENEW SCREW AND SPRING	SCREW AND SPRING REPLACED
28	RIGHT DOOR HINGE INTERFACE WASHERS MISSING - RENEW WASHERS	INTERFACE WASHERS REPLACED.
29	RIGHT DOOR PUNISHING BUSH WORK -RENEW BUSH AND SCREW	BUSH REPLACED.
30	RIGHT DOOR WINDOW FRAME ANCHOR NUTS CORRODED - RENEW NUTS AND PLUGS	ANCHOR NUTS AND RIVETS REPLACED.

Mech	NEIL
Insp	RHI 07
Date	28-11-11
Mech	NEIL
Insp	RHI 08
Date	28-FEB-11
Mech	NEIL
Insp	RHI 07
Date	28-11-11
Mech	NEIL
Insp	RHI 07
Date	29-11-11
Mech	NEIL
Insp	RHI 07
Date	28-11-11
Mech	NEIL
Insp	RHI 07
Date	28-11-11



Inspection Record Card Workshop Continuation Worksheet

Card 7 of 10

RHI ORDER NUMBER:

024794/00

CUSTOMER ORDER NUMBER:

145898

WORK TO BE DONE

RIGHT DOOR OUTER PANEL
CORRODED -- REPAIR PANEL

WORK CARRIED OUT

Outer Panel Replaced.

Mech NEIL

Insp RHI 07

Date 29-11-11

Mech NEIL

Insp RHI 07

Date 29-11-11

Mech NEIL

Insp RHI 07

Date 29-11-11

Mech NEIL

Insp RHI 07

Date 29-11-11

Mech NEIL

Insp RHI 07

Date 29-11-11

Mech NEIL

Insp RHI 07

Date 29-11-11

Mech NEIL

Insp RHI 07

Date 29-11-11

RIGHT DOOR DECOR PANEL SPOT
TOLDS -- REPAIR PANEL

Decor Panel Replaced.

RIGHT DOOR INNER PANEL SPOT
AT CORNER POINT -- REPAIR PANEL

Inner Panel Replaced.

RIGHT DOOR QUARTERMASTER INTERFAC
WASHERS MISSING -- REPAIR WASHERS


INTERFACE WASHERS REPLACED.

RIGHT DOOR INSULATION CARPET
DETACHED PANELS -- REPAIR INSULATION

INSULATION REPLACED.

VARIOUS LEFT HAND RIGHT DOOR
FIXING SECURITY SCREWS DAMAGED
WASHERS -- REPAIR SCREWS

SCREWS REPLACED.



Inspection Record Card

Workshop Continuation Worksheet

Card 8 of 10

RHI ORDER NUMBER:

02447914/100

CUSTOMER ORDER NUMBER:

1458918

WORK TO BE DONE

WORK CARRIED OUT

37. CHECK THERMOSTAT PLATE AND
MOUNTING. REQUIRE WELD REPAIRS

WELD REPAIRS COMPLETED OUT AT
ATE LASHAM EASA FORM 1 TRACKING
NUMBER 11597 REPAIRS

38. CARRY OUT DEEP CLEAN OF BOILER
(INTERIOR)

MAJOR CLEAN COMPLETED.

39. ASSEMBLE AND CARRY OUT MOTOR
SPEED AND ROTATION CHECKS

OVEN ASSEMBLED. MOTOR SPEED AND
ROTATION CHECKS COMPLETED:
LEFT: 6983 RPM, ANTICLOCKWISE (VIEWED FROM IMPELLER)
RIGHT: 7903 RPM, ANTICLOCKWISE (VIEWED FROM REAR)

40. CARRY OUT OVERHAUL TESTS.

TESTS PASSED.

41. CARRY OUT FULL FUNCTION TEST.
- RECORD TEMPERATURES.

FUNCTION TEST COMPLETED:
LEFT
142°C / 199°C
RIGHT
143°C / 203°C

42. RESEAL THERMOSTAT ACCESS
TUBES.

TUBES RESEAL.

Mech Insp

RHI 07

Date

13 APR 2011

Mech Insp

NEIL

Mech Insp

RHI 07

Date

29-11-11

Mech Insp

NEIL

Mech Insp

RHI 07

Date

29-11-11

Mech Insp

NEIL

Mech Insp

RHI 07

Date

29-11-11

Mech Insp

NEIL

Mech Insp

RHI 07

Date

29-11-11

Mech Insp


NEIL

Mech Insp

RHI 07

Date

29-11-11



Inspection Record Card Workshop Continuation Worksheet

Card 9 of 10

RHI ORDER NUMBER:

045872/00

CUSTOMER ORDER NUMBER:

145872

WORK TO BE DONE

WORK CARRIED OUT

43 RE-SLEEVE TERMINAL T1 AND T4 TERMINAL WIRES

T1 AND T4 WIRES RESLEEVED

Mech NEIL
Insp RHI 07
Date 29-11-11

44 CARRY OUT CLEAN UP REAR WIRING FURTHER REPAIRS (DAMAGED) CABLE TIES AS REQUIRED

WIRING AREA CLEANED. DAMAGED CABLE TIES REPLACED.

Mech NEIL
Insp RHI 07
Date 29-11-11

45 CARRY OUT CLEAN UP REAR EXTERIOR

EXTERIOR CLEANED.

Mech NEIL
Insp RHI 07
Date 29-11-11

46 REPT COUPLER AND CHECK OUT. OPERATIONAL. CHECK

COVERS REFITTED AND OPERATIONAL CHECK PASSED.

Mech NEIL
Insp RHI 07
Date 29-11-11

47 OVEN RECEIVED WITH DIRTY TRAY RACKS

TRAY RACKS RETURNED WITH OVEN.

Mech NEIL
Insp RHI 07
Date 29-11-11

UNABLE TO FUNCTION UNIT IN THIS UNSERVICEABLE CONDITION
- A FURTHER REPORT MAY FOLLOW

FURTHER FAULTS LISTED BELOW.

Mech NEIL
Insp RHI 07
Date 29-11-11