

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 221702 CTLID 1	
4. Organization Name and Address: BP Aero Services 4965 HANSON DR. IRVING, TX 75038 USA Ph: 469-208-0060, Fax: 972-252-2009		5. Work Order/Contract/Invoice Number: 96089		Number of attached pages – 1	
6. Item 1		7. Description: CASE-CPRSR STTR REAR		8. Part Number: 1559M4DG03	
9. Quantity: 1		10. Serial Number: GWNMW815		11. Status/Work: OVERHAULED	
12. Remarks: ATA: 72-33-01 E.S.N. 779481 Repair Order: ERO17573 Customer: AJ Walter Aviation Ltd See Workscope Report: 96089 All work performed in accordance with CFM56-5B Manual ID: CFMI-TP-SM.9, Revision #: 79, Revision Date: 4/15/2023 Also meets the inspection criteria of: CFM56-5C Manual ID: CFMI-TP-SM.8, Revision #: 57, Revision Date: 5/15/2023 CFM56-5A Manual ID: CFMI-TP-SM.7, Revision #: 69, Revision Date: 2/15/2023 CFM56-7B Manual ID: CFMI-TP-SM.10, Revision #: 64, Revision Date: 6/15/2023					
Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the component is considered ready for release to Service under EASA Part 145 Approval Number: EASA.145.6427					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12					
13b. Authorized Signature:		13c. Approval Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14b. Authorized Signature: 	
14c. Approval/Certificate No.:		14d. Name (Typed or Printed): Ian McCarragher		14e. Date (dd/mm/yyyy): 25-Aug-2023	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					
FAA Form 8130-3 (02-14)					

1 国家 Country P.R. CHINA	2. 中国民用航空总局 C.A.A.C ☐ 符合性 Conformity	☒ 适航性 Airworthiness	3 证书编号 Certificate Ref. No. 94293			
批准放行证书/适航批准标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG		5 工作单/合同单/发票 Work Order / Contract / Invoice 96089				
4 单位 BP Aero Services FAA Repair Station # 442R874B 4965 HANSON DR. IRVING, TX 75038 USA Tel: 972-252-2800, Fax: 972-252-2009	Number of attached pages - 1					
6 序号 Item	7 内容 Description	8 件号 Part No.	9 适用性 Eligibility	10 数量 Qty	11 系列号/批号 Serial/Batch No.	12 产品状态 Status/Work
1	CASE-CPRSR STTR REAR	1559M40G03	CFM56-5B	1	GWNMW815	OVERHAUL
13 备注 Remarks ATA: 72-33-01 E.S.N. 779481 Repair Order: ERO17573 Customer: AJ Walter Aviation Ltd See Workslope Report : 96089 All work performed in accordance with CFM56-5B Manual ID: CFMI-TP-SM.9, Revision #: 79, Revision Date: 4/15/2023 Also meets the inspection criteria of: CFM56-5C Manual ID: CFMI-TP-SM.8, Revision #: 57, Revision Date: 5/15/2023 CFM56-5A Manual ID: CFMI-TP-SM.7, Revision #: 69, Revision Date: 2/15/2023 CFM56-7B Manual ID: CFMI-TP-SM.10, Revision #: 64, Revision Date: 6/15/2023						
14 新产品 New Parts 被声明上述产品除第13项的其他规定以外, 以按照上述国家适航条例进行制造/检查, 并且该产品(出口产品)符合经批准的型号设计数据和进口国提出的专用要求。 Certifies that the part(s) identified above, except as otherwise specified in block 13 was (were) manufactured/inspected in accordance with the airworthiness regulations of the stated country and/or in the case of parts to be exported with the approved design data and with the notified special requirements of the importing country.		15 使用过的产品 Used Parts 被声明上述产品除第13项的其他规定以外, 已按照上述国家适航条例和进口国通知的特殊要求进行了工作, 该产品出于安全可用状态可以批准放行使用。 Certifies that the work specified above except as specified in block 13 was carried out in accordance with the airworthiness regulations of the stated country and the notified special requirements of the importing country and in respect to that work, the part(s) is (are) in condition for safe operation and considered ready for release to service. (over)				
16 批准人签名 Signature 		19 中国民航总局授权 Issued by or on behalf of the CAAC				
17 批准人姓名(打印的) Name (Printed) Ian McCarragher		F00100709				

Workscope Report

Work Order #: 96089

Date Printed: 8/25/2023

Time: 2:35:34 PM

Page: 1

BPAERO SERVICES

4961 HANSON DRIVE IRVING TX 75038 972-252-2800 WWW.BPAERO.COM

FAA Repair Station #442R874B



To: AJ Walter Aviation Ltd THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM		Ship To: Repairs Group THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS UNITED KINGDOM	
Ref #: ERO17573	Phone #: +44 1403 711 777	Fax #: +44 1403 710 936	Email: stockmarket@ajw-avation.com
Code: 12	Site: AWAL	PN: 1559M40G03	Descr: CASE-CPRSR STR REAR
Qty: 1	Station:	Make:	Model:
CFM56-TP-SM.9 CFM56-5B CFM56-TP-SM.8 CFM56-5C CFM56-TP-SM.7 CFM56-5A CFM56-TP-SM.10 CFM56-7B			
ESN 779481		Warranty Request N/A	
CSN		Complies With	
Entry Date: 6/27/2023		Need Date: 7/7/2023	
Compl. Date: 8/25/2023 2:34		Warranty: No	
Container:			

Serial Numbers: GWNMMW815

Inspection Findings:

Visual / Dimensional Findings

Wear on rub land coating

Repair Required:

REPAIR 005 - REPAIR OF DAMAGED FLOW PATH SURFACES

Corrective Actions:

Overhauled - 8130/CAAC Issued

Repair Performed:

REPAIR 005 - REPAIR OF DAMAGED FLOW PATH SURFACES

Task Description

Status

Seq

RECEIVING INSPECTION	Complete	0
PRELIMINARY INSPECTION	Complete	10
CFM56-5B-ESM-TASK-72-33-01-100-001 - CLEANING	Complete	100
CFM56-SPM-TASK-70-21-11-110-002 - CHEMICAL	Complete	110
CFM56-5B-ESM-TASK-72-33-01-200-001 - INSPCTN 001	Complete	200
CFM56-SPM-TASK-70-32-12-230-006 - PENETRANT	Complete	232
CFM56-5B-ESM-TASK-72-33-01-300-005 - REPAIR 005	Complete	305
PHASE II FINAL INSPECTION	Complete	399
FINAL CLEANING AND CONDITIONING	Complete	00000
FINAL INSPECTION	Complete	00000



fm



BPAERO SERVICES, LLC
FAA REPAIR STATION # 442R874B WWW.BPAEROSERVICES.COM

Packing Slip

Shipping No: 62854

Bill To:

AJ Walter Aviation Ltd
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX
RH13 0AS

Deliver To:

Repairs Group
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX
RH13 0AS

Carrier

Ship Date

**FED P-INT
124277507**

8/29/2023

Qty	Part No.	Description	Serial Number	Condition	Customer Reference #	BP WO
1	1559M40G03	CASE-CPRSR STTR RE/	GWNMW815	OH	ERO17573	96089

We hereby certify that the parts in this shipment conform with applicable specifications and that documentation and/or data is on file and available for examination.



Shipping No: 62854

AJ Walter Aviation Ltd
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX
RH13 0AS

Repairs Group
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX
RH13 0AS



Ship Date

FED P-INT
124277507

8/29/2023

Qty	Part No.	Description	Serial Number	Condition	Customer Reference #	BP WO
1	1559M40G03	CASE-CPRSR STTR RE/	GWNMW815	OH	ERO17573	96089

We hereby certify that the parts in this shipment conform with applicable specifications and that documentation and/or data is on file and available for examination.

--	--