

1. Approving National Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: 196525	
4. Organization Name and Address:  615 West Knox Road Tempe, AZ 85284 480-831-1268 FAX 480-831-1314		Z6AR209Y				5. Work Order/Contract/Invoice Number: W0075438	
6. Item: 1	7. Description: OUTBOARD GIMBAL ASSY	8. Part Number: 65B08415-601	9. Eligibility:* N/A	10. Quantity: 1	11. Serial/Batch Number: SAK6	12. Status/Work: REPAIRED	
13. Remarks: REPAIRED UNIT IAW BOEING CMM 57-52-35, REV #89 DATED MAR 01/13.							
"AIR TRANSPORT COMPONENTS CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 12/13 WAS CARRIED OUT IN ACCORDANCE WITH PART-145 AND IN RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA APPROVAL CERTIFICATE NO: EASA.145.5116." 14. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation ☐ Non-approved design data specified in Block 13 15. Authorized Signature: 16. Approval/Authorization No: 17. Name (Typed or Printed): 18. Date (m/d/y): 19. ☒ 14 CFR 43.9 Return to Service Certifies that unless otherwise specified in Block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. 20. Authorized Signature: 21. Approval/Certificate No: Z6AR209Y 22. Name (Typed or Printed): JEREMY M. LAND 23. Date (m/d/y): MAR/28/2013 User/Installer Responsibilities It is important to understand that the existence of this Document alone does not automatically constitute authority to install the part/component/assembly. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts parts/components/assemblies from the airworthiness authority of the country specified in block 1. Statements in blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulation by the user/installer before the aircraft may be flown.							



615 W. Knox Road
Tempe, AZ 85284
Ph: 480-831-1268

FAA Repair Station #
Z6AR209Y
Fx: 480-831-1314

COMPONENT TEARDOWN/CONDITION REPORT

Customer 10824 AJ WALTER AVIATION / RECOVERY WORK ORDER# W0075438
Nomenclature OUTBOARD GIMBAL ASSY MFG CUST-PO# 196525
Part Number 65B08415-601 S/N SAK6 A/C

Reason For Removal/Customer Instructions Modifications/S.B/A.D Compliance
REPAIR AS REQUIRED IAW MFG SPECS.
DUAL RELEASE REQUIRED.
MIS-IDENTIFIED S/N SSAK6 ON RO, IDENTIFIED AS SAK6 ON UNIT.

Visual Inspection Prior To Teardown:
UNIT DIRTY. PAINT CHIPPED / WORN.

Preliminary Test Results:
NOT REQUIRED.

Teardown And Inspection Findings:
SLEEVES BAD, DIRTY, MINOR WEAR, CAD PLATE WORN, REFINISH REQUIRED.

Corrective Action Taken:
REPAIRED UNIT IAW BOEING CMM 57-52-35, REV #89 DATED MAR 01/13.

Final Disposition: REPAIRED

TECH JB JOHN BERRY INSPECTOR JML JEREMY M. LAND DATE MAR/28/2013

For further info contact Roy Hyde at 480-831-1268 FAX 480-831-1314

ATC009



615 W. Knox Road
Tempe, AZ 85284
Ph: 480-831-1268

FAA Repair Station #
Z6AR209Y
Fx: 480-831-1314

COMPONENT TEARDOWN/CONDITION REPORT

Customer 10824 AJ WALTER AVIATION / RECOVERY
Nomenclature OUTBOARD GIMBAL ASSY MFG

WORK ORDER# W0075438
CUST-PO# 196525

***** PARTS REPLACEMENT RECORD ***** Page 1 of 1

QTY	Item #	Part Number	Nomenclature
0	229	65B02051-8FAB	SLEEVE
1	228	65B02051-7FAB	SLEEVE
1		74268	ALMEN STRIP

ATC009