

1. Approving Civil Aviation Authority/ Country:
FAA/United States

2.

Authorized Release Certificate

FAA Form 8130-3, Airworthiness Approval Tag

3. Form Tracking Number:

R377925

4. Organization Name and Address:

AOG Accessories
2549 N.W. 74th Ave. Miami FL 33122 USA
Phone: 305-591-1899 Fax: 305-489-0176
FAA APPROVED REPAIR STATION NO. XB4R642M * EASA 145.5924

5. Work Order/Contract/
Invoice Number:

20547

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	GEARED ROTARY ACTUAT	755299D	1ea.	A8180	REPAIRED

12. Remarks: REPAIRED in accordance with CMM 27-81-32 Revision 24 Dated 2/16/2016

Full details of work carried out per work order no. 20547


Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the GEARED ROTARY ACTUAT is considered ready for release to service under EASA Part 145 approval no. EASA 145.5924.

EASA A.D.: No AD required.
EASA S.B.: No SB required.

FAA A.D.: No AD required.
FAA S.B.: No SB required.

14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

14b. Authorized Signature: 	14c. Approval/Certificate No.: XB4R642M
14d. Name (Typed or printed) Alfonso Ojeda	14e. Date (dd/mm/yy): 29/Oct/2021

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

TearDown/Inspection Form

AOG Accessories
2549 N.W. 74th Ave.
Miami FL 33122
USA
Phone: 305-591-1899 Fax: 305-489-0176
C.R.S. No.: XB4R642M

Work Order: 20547
Date: October/29/2021
Page 1 of 1

Sold To: AJ WALTER AVIATION, LTD THE HEADQUARTERS MAYDELL AVE SLINFOLD RH13OAS WEST SUSSEX UNITED KINGDOM	Ship To: AJ WALTER AVIATION, LTD THE HEADQUARTERS MAYDELL AVE SLINFOLD RH13OAS WEST SUSSEX UNITED KINGDOM
---	---

Part Number: 755299D	Serial: A8180	Manufacturer: UTC AEROSPACE
Description: GEARED ROTARY ACTUAT		Model: 755299D
Purchase Order: R377925	Service Performed: REPAIRED	
Data used: Manual Number: 27-81-32	Revision: 24	Date: 2/16/2016

1.- Trouble Reported: SHOP RESTORATION RE-ID UNIT Appearance: Normal Loose or Missing Parts: No Loose or Missing Parts.	Teardown/Inspection Data Inst.: Repair Only. Corrosion: No Corrosion Noted. Physical Damage: No damage found.
2. Teardown Disassembly: Only as Required for Repair. Painting: As required By Manual	Cleaning: Performed cleaning as required Assembly: As Required for Repair.
3. Test Operation: Tested I/A/W Mfg. Specs. Modifications: None	Was Complaint Verified: Yes Other problems found: None Noted.
4. Final Warranty Accepted: N/A FAA A.D.: No AD required. EASA A.D.: No AD required.	Final Test and Inspection: Final Inspection Normal. FAA S.B.: No SB required. EASA S.B.: No SB required.

5. Work Performed:
PN and SN verified against customer repair order and CMM configuration. Missing ID Plate on arrival. Unit pretested and failed. Unit disassembled cleaned, and inspected in accordance with ATA 27-81-32. Inspection revealed worn retaining rings, caution placard, ID plate requiring replacement, unit requires cleaning, adjustment. Unit was Repaired and Tested IAW OEM CMM 27-81-32 Revision # 24 Dated Feb 16, 2016. Replaced all defective, missing and worn parts listed above. A/C REG: P4-MAS.

Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect to the work performed is approved to return to service. Pertinent details of the work performed are on File at this Agency under Work Order No.: 20547

Inspector's Name: Alfonso Ojeda	Technician: Ricardo Mena
Signature: 	Date: October/29/2021
Inspector	Form: AOG 103 Original 03/17/2014