

1. Approving Civil Aviation  
Authority/Country:

2.

FAA/United States

4. Organization Name and Address:



900 N. Fiesta Blvd.  
Gilbert, AZ 85233  
480-831-1268 FAX 480-831-1314

Z6AR209Y

**AUTHORIZED RELEASE CERTIFICATE**  
FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

RW100476

5. Work Order/Contract/Invoice Number:

W0091775

6. Item:

7. Description:

1 LATERAL GUIDE  
ASSY

8. Part Number:

45212633-5

9. Quantity:

1

10. Serial Number:

SAS2818

11. Status/Work:

TESTED

12. Remarks:

TESTED UNIT IAW GODDRICH CMM 25-53-14, REV #26 DATED MAY 31/09.

\* AIR TRANSPORT COMPONENTS CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH PART 145 AND IN RESPECT TO THAT WORK THE AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA APPROVAL CERTIFICATE NO: EASA.145.5116. \*

13a. Certifies the items identified above were manufactured in conformity to:  
☐ Approved design data and are in a condition for safe operation  
☐ Non-approved design data specified in Block 12

13b. Authorized Signature:

13c. Approval/Authorization No:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14a. Authorized Signature:

14b. Name (Typed or Printed):  
JAMES ADAMS

14c. Approval/Certificate No:

Z6AR209Y

14e. Date (dd/mm/yyyy):

04/NOV/2015

**User/Installer Responsibilities**

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



900 N. Fiesta Blvd.  
Gilbert, AZ 85233  
Ph: 480-831-1268

FAA Repair Station #  
Z6AR209Y  
Fx: 480-831-1314

---

COMPONENT TEARDOWN/CONDITION REPORT

---

Customer 10138 INTERTRADE WORK ORDER# W0091775  
Nomenclature LATERAL GUIDE ASSY MFG CUST-PO# RW100476  
Part Number 452T2633-5 S/N SAS2818 A/C

Reason For Removal/Customer Instructions Modifications/S.B/A.D Compliance  
TEST AS REQUIRED IAW MFG SPECS.  
DUAL RELEASE REQUIRED.

Visual Inspection Prior To Teardown:  
NO VISUAL DEFECTS FOUND.

Preliminary Test Results:  
TESTED IAW CURRENT OEM/MFG SPECS.  
ALL TESTS PASSED.

Teardown And Inspection Findings:  
UNIT PASSED ALL TESTS WITH NO DEFECTS FOUND.

Corrective Action Taken:  
TESTED UNIT IAW GODDRICH CMM 25-53-14, REV #26 DATED MAY 31/09.

-----  
Final Disposition: TESTED

TECH GT GREG THOMPSON INSPECTOR JMA JAMES ADAMS DATE NOV/04/2015  
For further info contact Ry H. de at 480-831-1268 FAX 480-831-1314

ATC009