

1. Approving Competent Authority/Country
CIVIL AVIATION AUTHORITY
UNITED KINGDOM GB

2
AUTHORISED RELEASE CERTIFICATE
EASA FORM 1

3. Form Tracking Number

MAS/15157

4. Approved Organisation Name and Address

Marilake
aero systems



Peartree Business Centre
Cobham Road
Ferringham, Dorset, England BH21 7PT
Tel 00 44 (0) 1202 863747 Fax 00 44 (0) 1202 863748
Web www.marilake.com


5. Work Order/Contract/Invoice

R350807
016192100

6. Item	7. Description	8. Part Number	9. Qty	10. Serial No.	11. Status/Work
01	LIGHT	30-1883-6	1 EA	S/No 1750	Repaired
12. Remarks					


ALL WORK CARRIED OUT I.A.W. CMM 33-49-11 REV 3 - 15/08/05

TCCA APPROVAL NUMBER 811-14

THE WORK IDENTIFIED IN BLOCK 11 & DESCRIBED HEREIN HAS BEEN ACCOMPLISHED I.A.W. 14 CFR PART 43 & IN RESPECT TO THAT WORK THE ITEMS ARE APPROVED FOR RETURN TO SERVICE UNDER CERTIFICATE NO 5GFY384B
SIGNATURE 
NAME G. GIFFITHS DATE 21-12-18

13a. Certifies that the items identified above were manufactured in conformity to:

- ☐ approved design data and are in condition for safe operation
☐ non-approved design data specified in block 12

13b. Authorised Signature	13c. Approval/Authorisation Number	14a. <input checked="" type="checkbox"/> Part-145 A.50 Release to Service Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12 was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service	14b. Authorised Signature 	14c. Certificate/Approval Ref No. UK. 145.01186
13d. Name	13e. Date (dd/mm/yyyy)	14d. Name <u>G. GIFFITHS</u>	14e. Date (dd/mm/yyyy) 21-Dec-2018	

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s)

Where the user/installer performs works in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in Block 1 it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1
Statements in 13a and 14a do not constitute installation certification. In all cases aircraft maintenance record must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown



TECHNICAL REPORT

Ref No : M 123

OWNER : QAM

DATE : SEP 2016

ISS : 3

SHT 1 OF 1

OUR REFERENCE	016192
PURCHASE ORDER	R350807
FOR THE ATTENTION OF	VIVIENNE APPLEBY
COMPANY	AJ WALTER AVIATION LTD
DESCRIPTION	LIGHT
PART NUMBER	30-1883-6
SERIAL NUMBER	1750
MAS RELEASE NOTE NO	MAS15157

Reported Non Conformance

INOP

FINDINGS:

FAULT CONFIRMED

MAIN LAMP IS INOP

FOUR SPACERS & FOUR SHIMS ARE MISSING – THIS IS CONSIDERED CUSTOMER INDUCED DAMAGE

RECTIFICATION:

UNIT UNCASSED

LAMP & MISSING HARDWARE REPLACED

CONCLUSION:

UNIT RECASED, TESTED TO SPECIFICATION & RELEASED REPAIRED

NO MODS EMBODIED

Signed: 

Date: 21 December 2018

Distribution: Original – Customer, Copy to Customer File.