

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2.		3. Form Tracking Number: 256398			
4. Organization Name and Address: Aero Accessories & Repair, Inc. FAA CERT #77AR783B 15501 SW 29TH ST. SUITE#201 MIRAMAR, FL 33027 Ph: 954-266-1300, FAA Approval Holder: 77AR783B				5. Work Order/Contract/Invoice Number: 61022 T42280			
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:		
1	HYDRAULIC HAND PUMP ASSY.	71234	1	H11764G	OVERHAULED		

12. Remarks:

The component identified above was OVERHAULED in accordance with Federal Aviation Regulation and is approved for return to service with respect to the work performed. Pertinent details of the work accomplished are on the file at this agency under Form Tracking Number identified above.
Removed from A/C: 9V-SWA- MSN 34568
TSO: 0:00 CSO: 0
S/B and A/D: None applicable
OEM CMM: 29-20-65, Revision#: 10, Revision Date 6/9/2021

ORIGINAL

Certifies work specified in blocks 11/12 was carried out in accordance with EASA part 145, and with respect to that work, the component is considered ready for release to service under EASA part 145 Approval Number EASA 145-6467

13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		11a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service	
13b. Authorized Signature:	13c. Approval Authorization No.:	14b. Authorized Signature: 	14c. Approval/Certificate No.: 77AR783B
13d. Name (Typed or Printed):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed): Stephanie Sanchez	14e. Date (dd/mm/yyyy): 09-Nov-2023

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.
Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.
Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Aero Accessories & Repair, Inc.
FAA CERT #77AR783B
15501 SW 29TH ST. SUITE#201
MIRAMAR, FL 33027
Ph: 954-266-1300.

Work Order

Work Order #: 61022

Date Printed: 11/9/2023

Time: 9:40:28 AM

Page: 1

To:

AJW AVIATION LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, SLI RH13 0AS
UNITED KINGDOM

Ship To:

AJW AVIATION LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WS RH13 0AS
UNITED KINGDOM

Ref #: T42280

Phone #: 305 470 8007

Fax #: 441.403.710.936

Email: louise@ajw-group.com

Code: 45

Site: SH/DV

PN: 71234

Descr: HYDRAULIC HAND PUMP ASSY.

Qty: 1

Station: HYDRAULIC

Make:

Model:

Mfg: _

Repair Manual(s): 29-20-65 Rev. 10 Rev. Date: 6/9/2021

Entry Date: 10/24/2023

Need Date: 11/10/2023

Compl. Date: 11/9/2023 9:35

Warranty: No

Container:

Serial Numbers:

H11764G

RECEIVING INSPECTION

P/N and S/N verified on unit and customer RO has wrong S/N stated. Actual S/N H11764G. No external damage noted. See RO for work scope. Technician must verify.

PRELIMINARY INSPECTION

P/N 71234 verified IAW technical data referenced above.

S/N H11764G verified through ID Marking.

S/N H11764G stated in customer RO is incorrect.

Unit failed visual examination upon arrival. Leak on body.

No AD's applicable for unit at this time.

TSN: UNK CSN: UNK

TSO: UNK CSO: UNK

Tech: D.T. #116

HIDDEN DAMAGE

None noted.

Tech: D.T. #116

INITIAL FINDINGS

Unit failed functional test IAW technical data referenced above.

Reason: Leaking externally.

Customer Complaint: N/A.

Tech: D.T. #116

TEARDOWN FINDINGS

Unit disassembled, cleaned and inspected IAW technical data referenced above. Unit requires replacement of all packings, seals and retainers removed during disassembly.

Minor nicks, scratches, and dents do not affect fit, form, or function of the unit.

Unit will be overhauled.

Tech: D.T. #116

Authorized Signature: _____

Name: STEPHANIE SANCHEZ

Date: 11/9/2023



Aero Accessories & Repair, Inc.
FAA CERT #77AR783B
15501 SW 29TH ST. SUITE#201
MIRAMAR, FL 33027
Ph: 954-266-1300,

Work Order

Work Order #: 61022

Date Printed: 11/9/2023

Time: 9:40:29 AM

Page: 2

To:
AJW AVIATION LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, SLI RH13 0AS
UNITED KINGDOM

Ship To:
AJW AVIATION LTD.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WS RH13 0AS
UNITED KINGDOM

Ref #: T42280

Phone #: 305 470 8007

Fax #: 441.403.710.936

Email: louise@ajw-group.com

Code: 45

Site: SH/DV

PN: 71234

Descr: HYDRAULIC HAND PUMP ASSY.

Qty: 1

Station: HYDRAULIC

Make:

Model:

Mfg: _

Repair Manual(s): 29-20-65 Rev: 10 Rev. Date: 6/9/2021

Entry Date: 10/24/2023

Need Date: 11/10/2023

Compl. Date: 11/9/2023 9:35

Warranty: No

Container:

CORRECTIVE ACTION

Replaced all parts and corrected all findings listed in Teardown report. Unit was overhauled and tested IAW technical data referenced above.
Tech: D.T. #116

Authorized Signature: _____

Name: STEPHANIE SANCHEZ

Date: 11/9/2023



Aero Accessories & Repair, Inc.

FAA CERT #77AR783B
15501 SW 29TH ST. SUITE#201
MIRAMAR, FL 33027
Ph: 954-266-1300,

Packing Slip



SH42235

Aero Accessories & Repair, Inc.

FAA CERT #77AR783B
15501 SW 29TH ST. SUITE#201
MIRAMAR, FL 33027
Ph: 954-266-1300,

Customer: AJW AVIATION LTD.

Shipping Order: SH42235

Order: 61022

Terms: Not determined

Ship Via: FEDEX INTERNATIONAL PRIORITY

Ship Via Acc: 248185260

AWB: 704664356850

Page: 1

Date: 11/9/2023

Time: 10:24:37 AM

Ship To: AJW AVIATION LTD.

THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WS RH13 0AS
UNITED KINGDOM

Customer PO#: T42280

Order Total: 0

Item	Part Number/Description	Serial Number	Qty	CD
71234	HYDRAULIC HAND PUMP ASSY.	H11764G	1	OH