


1. Approving Competent Authority/Country CAA/UK		2.		AUTHORISED RELEASE CERTIFICATE CAA FORM 1		3. Form Tracking Number 86946097-10300	
4. Organisation Name and Address Meggitt SA Route de Moncor 4, CH-1752 Villars-sur-Glâne, Switzerland Phone: +41 (0)26 407 11 11 Fax: +41 (0)26 407 18 60				5. Work Order/Contract/Invoice Notification: 350566772 PO: R418876 Item:			
6. Item	7. Description	8. Part No.	9. Qty	10. Serial No.	11. Status / Work		
1	Engine Vibration Monitoring Unit	241-246-022-004	1	AK12798	INSPECTED / TESTED		
12. REMARKS This document has been issued according to an approved computer generated signature procedure. SN: (AK12798); MOD Strike: 1.2 Applicable Technical Docs: CMM 77-32-09 REV.5 DATED NOV 24/2022 For work carried out, refer to Service Breakdown Report for Service Order 45463495							
13a. Certifies that the items identified above were manufactured in conformity to ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in Block 12				14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part -145 and in respect to that work the items are considered ready for release to service			
13b. Authorised Signature		13c. Approval/Authorisation Number		14b. Authorised Signature  VM - CS COA - 14 V. De Campos		14c. Certificate/Approval Ref No. UK.145.01715	
13d. Name		13e. Date (dd mm yyyy)		14d. Name VICTOR DE CAMPOS		14e. Date (dd mm yyyy) 06DEC2023	

USER/INSTALLER RESPONSIBILITIES
This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1. Approving Competent Authority/Country FEDERAL OFFICE OF CIVIL AVIATION (FOCA) SWITZERLAND		2.		AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 86946097-10300	
4. Organisation Name and Address Meggitt SA Route de Moncor 4, CH-1752 Villars-sur-Glâne, Switzerland Phone: +41 (0)26 407 11 11 Fax: +41 (0)26 407 18 60				5. Work Order/Contract/Invoice Notification: 350566772 PO: R418876 Item:			
6. Item	7. Description	8. Part No.	9. Qty	10. Serial No.	11. Status / Work		
1	Engine Vibration Monitoring Unit	241-246-022-004	1	AK12798	INSPECTED / TESTED		
12. REMARKS This document has been issued according to an approved computer generated signature procedure. The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for release or return to service under certificate no. VM8Y694J. SN: (AK12798);MOD Strike:1.2 Applicable Technical Docs: CMM 77-32-09 REV.5 DATED NOV 24/2022 For work carried out, refer to Service Breakdown Report for Service Order 45463495							
13a. Certifies that the items identified above were manufactured in conformity to ☐ approved design data and are in a condition for safe operation ☐ non-approved design data specified in Block 12							
13b. Authorised Signature		13c. Approval/Authorisation Number		14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part -145 and in respect to that work the items are considered ready for release to service			
13d. Name		13e. Date (dd mmm yyyy)		14b. Authorised Signature  VM - CS COA - 14 V De Campos Electronic Signature on File			
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority specified in block 1.		14c. Certificate/Approval Ref No. CH.145.0251		14d. Name VICTOR DE CAMPOS			
				14e. Date (dd mmm yyyy) 06DEC2023			

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

EASA Form1 -MF/CAO/145 Issue 3

Service Breakdown Report

Sold to
A.J.WALTER AVIATION
The Headquarters
Maydwell Avenue, Slinfold
WEST SUSSEX
RH13 0AS
UNITED KINGDOM

Page 1 of 2
Date 03.11.2023
Service notification 350566772
Meggitt quality notification
Service order/Report No 45463495
Sales order 9953494307
Customer PO# R418876
Customer quality ref
Customer Part#

Equipment serviced here

Item	Part number/ Description	Serial number	Mod Status/Revision
1	241-246-022-004 EVM 246 - Engine Vibration Monitoring Unit Applicable Technical Docs:	AK12798	1,2 / - CMM 77-32-09 REV.5 DATED NOV 24/2022

Failure / complaint (as reported by customer)

For repair under T & M
RFR: PER FAILURE MSG ENGY, N2 SPEED SENSOR
A/C: @@AP-BMN@@
TSN/CSN: UNK
EASA/FAA/UK CAA

Findings

Service Rep EVM
Seal(s) ok, no physical damage has been noticed.
Incoming MR 1,2
No fault in memeory
Unit works within specifications.

Materials

Item	Qty	UOM	Part Number	Batch Number	Description	Cond
------	-----	-----	-------------	--------------	-------------	------

Work performed

Incoming Inspection (Admin)
Preliminary hidden damage inspection
SB/SIL/AD status check performed
Visual Inspection
Customer complaint not confirmed
Check connectors condition
Read & Analyze Internal Memory
Incoming ATP Technician
Incoming ATP Test System
Tested & Inspected IAW CMM listed above
Final ATP Technician
Final ATP Test System

Meggitt SA, Rte. de Moncor 4, PO Box, CH-1701, Fribourg, Switzerland

VAT Number: CHE-107.769.496 TVA Custom Account: 1065-1
GST 10-2364-0691-TQ0001 GST 890 368 079 RT0001 Customs 890 368 079 RM0001

Tel: +41 (0) 26 407 11 11
Fax: +41 (0) 26 407 17 00
www.meggitt.com

Service Breakdown Report



Sold to
A.J.WALTER AVIATION
The Headquarters
Maydwell Avenue, Slinfold
WEST SUSSEX
RH13 0AS
UNITED KINGDOM

Page	2 of 2
Date	03.11.2023
Service notification	350566772
Meggitt quality notification	
Service order/Report No	45463495
Sales order	9953494307
Customer PO#	R418876
Customer quality ref	
Customer Part#	

Final FOD check
Administration

Meggitt SA, Rte. de Moncor 4, PO Box, CH-1701, Fribourg, Switzerland

AT Number: CHE-107.769.496 TVA Custom Account: 1065-1
ST 10-2364-0691-TQ0001 GST 890 368 079 RT0001 Customs 890 368 079 RM0001

Tel: +41 (0) 26 407 11 11
Fax: +41 (0) 26 407 17 00
www.meggitt.com

TEST REPORT

Subject: ACCEPTANCE TEST REPORT
Item: Engine Vibration Monitoring Unit
Type: EVM-246
MFR: S3960
PNR: 241-246-022-004
Cust. PNR: CMS 69 958 116 00
Mod. Record: 1,2
SER: AK12798
DMF: 112013
Applicable Doc.: ATP-1206-04 rev 01
Software PNR: 299-500-000-015
Database PNR: 299-517-500-002
AU SER: AC85213
Operator: JM Simon
Test Result: PASS
Started: 31 Oct 2023 13:22:23
Finished: 31 Oct 2023 13:36:18
Report generated: 31 Oct 2023 13:36:18
Report Location: \\ngts\atr\atp1206_04r01_evm246/P-AK12798-20231031-133546.html
GTS Hostname: gtsxp0039
Comment:

Signature: _____

Department Approval: _____

Date of Approval: _____

31 OCT. 2023