

1. Approving Civil Aviation Authority / Country FAA / United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3. AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number 3210173541-F	
4. ORGANIZATION NAME AND ADDRESS: BARFIELD INC. 4101 N.W. 29TH STREET MIAMI FL 33142-5617				5. WORK ORDER, CONTRACT OR INVOICE NUMBER R289090 - 100000605872 / 100000605876	
6. ITEM		7. DESCRIPTION	8. PART NUMBER	9. QUANTITY	10. SERIAL NUMBER
001		3/2 WAY VALVE	S4-3400950-06	1	02455
11. STATUS / WORK		TESTED			
12. Remarks: DOC TYPE: CMM REF.DOC.: 29-10-13 REVISION: 7 DATE DOC.: 08/31/11 MOD./AMDT.ON ARRIVAL: / MOD./AMDT.ON DEPARTURE: / AD & SB: N/A EQUIPPED WITH PILOT VALVE; PN:S4-3401190, SN:02474. TSN/CSN UNK / UNK TSO/CSO UNK / UNK TSI/CSI 0 H / 0 C Barfield certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number : EASA 145 4239					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.		14a. ☒ 14 CFR 43.9 Return to Service Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:		13c. Approval / Authorization No.:		14c. Approval / Certificate No.:	
				XBIR995K	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14d. Name (Typed or Printed):	
				ERNESTO GONZALEZ	
14e. Date (dd/mm/yyyy): 12/MAY/2016					
User / Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					


LA# 292387

TEARDOWN REPORT

n° 3210173541

CUSTOMER	CUSTOMER	C000007464	AVTRADE LTD
	REPAIR ORDER	R289090	
	WARRANTY		
	EXECUTION ORDER NUMBER	100000605872	
AIRCRAFT	AIRCRAFT	AIRBUS	320
	SERIAL NUMBER		
ITEM RECEIVED	PART NUMBER	S4-3400950-06	
	SERIAL NUMBER	02455	
	DESCRIPTION	3/2 WAY VALVE	
	SERVICE REQUESTED	BC	BENCH TEST
ITEM DELIVERED	PART NUMBER	S4-3400950-06	
	SERIAL NUMBER	02455	
	DESCRIPTION	3/2 WAY VALVE	
	SERVICE RENDERED	BC	BENCH TEST
INSPECTED IN ACCORDANCE WITH	DOC.	29-10-13	REVISION 7
	TYPE	CMM	DATE 08/31/11

	TSN / CSN	TSO / CSO	TSI / CSI
HOURS	UNK	UNK	000000 H
CYCLES	UNK	UNK	000000 C
DATES			

REASON FOR REMOVAL	UNIT SEND FOR INSPECTION AND ADVICE		
	FAILURE CONFIRMED	☐ YES	☒ NO ☐ OTHER
REMARKS			
WARRANTY	☐ WARRANTY MANUFACTURER ☐ WARRANTY REPAIRER		
CREATED BY			DATE MAY 12 2016

 BARFIELD INC.
 4101 NW 29TH STREET
 MIAMI, FL, 33142
 USA

Phone : +1 (305) 894 5300 - Fax : +1 (305) 894 5301

Repair Station No. XBIR995K

TEARDOWN REPORT

n° 3210173541

Work Description**Shop findings**

- 1 PRELIMINARY INSPECTION.
EQUIPPED WITH PILOT VALVE:
PN:S4-3401190, SN:02474.

Corrective actions

- 1.1 NO UNUSUAL CONDITION NOTED.

Shop findings

- 2 UNIT RECEIVED FOR BENCH CHECK.

Corrective actions

- 2.1 UNIT PASSED BENCH CHECK.

(R) Reworked parts - (M) Missing parts upon arrival - (C) Parts provided by customer - (MC) Missing parts upon arrival and provided by customer
(B) Embodiement of Service Bulletin

BARFIELD INC.
4101 NW 29TH STREET
MIAMI, FL, 33142
USA

Phone : +1 (305) 894 5300 - Fax : +1 (305) 894 5301

Form 7.5.3-6

Page 2 of 2

Repair Station No. XBIR995K

Rev. 3, Issued Date : 8/07/2014