

1. Approving National Aviation Authority/Country: FAA / UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: PAI 125800	
4. Organization Name and Address: IS3R590L Perform Air International, Inc. • 463 S. Hamilton Ct. • Gilbert, AZ 85233						5. Work Order/Contract/Invoice Number: W/LK 1091095	
6. Item: 1	7. Description: CHECK VALVE	8. Part Number: 20C144-7	9. Eligibility: N/A	10. Quantity: 1	11. Serial/Batch Number: 2460	12. Status/Work: INSPECTED	
13. Remarks: Work Order: 125800 Mechanic Performing Work: Dan Blake Work Completion Date: 3/14/2011		Technical Data: 28-22-06		Revision Number: Initial		Revision Date: 4/1/1986	
A.D. Review accomplished.		Cust Part Number: N/A		Cust Serial Number: N/A			
OEM ALLEN AIRCRAFT PRODUCTS							
All work done in accordance with current manual. See teardown report for details of work accomplished. Certifies that the work specified in Blocks 12/13 was carried out in accordance with EASA part 145 and, with respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number 145.4741.							
14. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation ☐ Non-approved design data specified in Block 13		19. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 13 Certifies that unless otherwise specified in block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.					
15. Authorized Signature:		16. Approval/Authorization No.:		20. Authorized Signature: 		21. Approval/Certificate No: IS3R590L	
17. Name (Typed or Printed):		18. Date:		22. Name (Typed or Printed): Frank Layaoen		23. Date (m/d/y): Mar 14 2011	
User/Installer Responsibilities							
It is important to understand that the existence of this Document alone does not automatically constitute authority to install the part/component/assembly.							
Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness accepts parts/components/assemblies from the airworthiness authority of the country specified in Block 1.							
Statements in Blocks 14 and 19 do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certificate issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

Perform Air International, Inc.
463 South Hamilton Court
Gilbert, Arizona 85233
Tel. (480) 610-3500
Fax. (480) 610-3501
FAA Repair Station IS3R590L



Date: 3/14/2011

Customer: GECAS - AMS

Information from Repair Order / Purchase Order

Repair Order#: WLK1091095 Mfg P/N from RO/PO: 20C144-7 Mfg S/N from RO/PO: 2460
Nomenclature: CHECK VALVE RO/PO Disposition: Inspect Warranty Request: No
Reason for Removal Unit sent for bench test and cosmetic clean up if required do not proceed with repair without quote approval.

Information for Part Received

Work Order#: 125800 Mfg P/N Received: 20C144-7 Mfg S/N Received: 2460
Date Received: 3/8/2011
Preliminary Inspection: AD review accomplished. See customer discrepancy. Visually inspected and tested unit IAW CMM 28-22-06 dated 04/01/1986. Passed tests, no defects noted. No warranty.

Information for Part Shipped Back

Mfg P/N Out: 20C144-7 Mfg S/N Out: 2460
Customer P/N Out: N/A Customer S/N Out: N/A
Status: INSPECTED Warranty: None Manual Ref#: 28-22-06
Warranty Comments: None

Teardown Procedure: None

Repair Procedure: None

Test Procedure: Unit passed tests IAW CMM 28-22-06 Rev. Initial, dated 04/01/1986. No defects noted.

Modifications Incorporated: None

Mechanic: Dan Blake

Certificate #: 3310735

Date Repaired 3/11/2011

Inspector: Frank Layaoen

Date Inspected: 3/14/2011

Stamp: 