

**Combined Inventory
Receipt & Dispatch
Check Sheet**

26-36x19x14

THIS DOCUMENT MAY ONLY BE COMPLETED BY A
PERSON THAT HAS RECEIVED TRAINING AND BEEN
ISSUED WITH AN INSPECTORS STAMP



B&H Warehouse Reference	Job Number	Date Received
AW565875		31.07.2023

A visual inspection has been performed on this unit and the following information checked:

	RECEIPT			DISPATCH		
	Yes	No	N/A	Yes	No	N/A
EASA Form (8130) / Authorised Release Certificate	☒	☐	☐	☐	☐	☐
Trace Documentation	☒	☐	☐	☐	☐	☐
OEM Certification	☐	☐	☒	☐	☐	☐
DG Declaration	☐	☐	☒	☐	☐	☐
MSDS (Material Safety Data Sheet)	☐	☐	☒	☐	☐	☐
Shelf Life Applicable	☐	☐	☒	☐	☐	☐
Material Certification / ATA 106	☐	☐	☒	☐	☐	☐
US (unserviceable) Tag	☐	☐	☒	☐	☐	☐
Reason for Removal Stated on Tag	☐	☐	☒	☐	☐	☐
Packing Slip	☐	☐	☒	☐	☐	☐
Original Certificates Returned	☐	☐	☒	☐	☐	☐
Unused Statement	☐	☐	☒	☐	☐	☐
Physical Checks to be completed	RECEIPT			DISPATCH		
	Yes	No	N/A	Yes	No	N/A
Part Number on Unit Matches Paperwork	☒	☐	☐	☐	☐	☐
Serial Number on Unit Matches Paperwork	☒	☐	☐	☐	☐	☐
Description on Unit Matches Paperwork	☒	☐	☐	☐	☐	☐
All Paperwork carries the same part & serial number	☒	☐	☐	☐	☐	☐
Blanks fitted to ALL ports	☒	☐	☐	☐	☐	☐
FOD evident in ports / connectors	☐	☐	☒	☐	☐	☐
Static Sensitive	☐	☐	☒	☐	☐	☐
Warranty labels INTACT	☐	☐	☒	☐	☐	☐
Following tasks MUST be completed on Receipt AND Dispatch	RECEIPT			DISPATCH		
	Yes	No	N/A	Yes	No	N/A
Interior packaging sufficient to secure unit and weight of unit	☒	☐	☐	☐	☐	☐
Component wrapped in static sensitive bubble/pouch	☐	☐	☒	☐	☐	☐
Exterior packing condition acceptable for weight of unit	☒	☐	☐	☐	☐	☐
External Damage customer to inspect photo's	☐	☐	☒	☐	☐	☐
Photos Taken – Package Exterior	☒	☐	☐	☐	☐	☐
Photos Taken – Item and packaging	☒	☐	☐	☐	☐	☐
Photos Taken – Component(s)	☒	☐	☐	☐	☐	☐
Photos Taken – Data Plates and Connectors	☒	☐	☐	☐	☐	☐
FirstTrac Updated	☒	☐	☐	☐	☐	☐
Other (Specify)	☐	☐	☒	☐	☐	☐
Customer advised / Pre alert sent	☐	☐	☒	☐	☐	☐
Completed by (Trained Inspector Stamp)	☒	☐	☐	☐	☐	☐



1. Approving Competent Authority / Country
AESA
SPAIN

2. AUTHORIZED RELEASE CERTIFICATE
EASA FORM 1

3. FORM TRACKING NUMBER.
MI/23764449

4. ORGANIZATION NAME AND ADDRESS



Adolfo Suarez Madrid - Barajas Intl.
Airport - Zona Industrial No. 2
28042 MADRID - SPAIN
www.iberiamaintenance.com

5. WORK ORDER / CONTRACT / INVOICE
7200693562

6. ITEM	7. DESCRIPTION	8. PART N°	9. QTY	10. SERIAL No.	11. STATUS / WORK
1	CENTERING SPRING ROD YAW DAMPER	D2727000700600	1	06-8296	INSPECTED/TESTED

12. REMARKS

WORKS PERFORMED I.A.W. CMM:27-26-41 REV.26 JAN 2023

Customer: AJW RO: R412123

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate No.LLAY037F.

TCCA Approval Number: 898-27

Records of works performed are on file at this maintenance organization under Work Order stated in block 5

3a. Certifies that the items identified above were manufactured in conformity to:

☐ approved design data and are in condition for safe operation.

☐ non-approved design data specified in block 12.

14a. ☒ Part 145.A.50 Release to Service. ☒ Other regulation specified in block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with part 145 and in respect to that work the items are considered ready for release to service.

13b. AUTHORIZED SIGNATURE	13d. APPROVAL/AUTHORISATION NUMBER	14b. AUTHORIZED SIGNATURE Nº. DE NÓMINA 664834	14c. CERTIFICATE/APPROVAL REF. No. ES.145.011
13c. NAME	13e. DATE (dd/mm/yyyy)	14d. NAME: IVÁN DANIEL ORTEGA	14e. DATE (dd/mm/yyyy): 26/JUL/2023

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer works in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures

that his/her airworthiness authority accepts items from their airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national

1. Approving Competent Authority / Country :
CAA UK

AUTHORISED RELEASE CERTIFICATE
CAA FORM 1

3. FORM TRACKING NUMBER.
MI/23764450

4. ORGANIZATION NAME AND ADDRESS



Adolfo Suarez Madrid - Barajas Intl.
Airport - Zona Industrial No. 2
28042 MADRID - SPAIN
www.iberiamaintenance.com

5. WORK ORDER / CONTRACT / INVOICE
7200693562

6. ITEM	7. DESCRIPTION	8. PART N°	9. QTY	10. SERIAL No.	11. STATUS / WORK
1	CENTERING SPRING ROD YAW DAMPER	D2727000700600	1	06-8296	INSPECTED/TESTED

12. REMARKS

WORKS PERFORMED I.A.W. CMM:27-26-41 REV.26 JAN 2023
Customer: AJW RO: R412123

Records of works performed are on file at this maintenance organization under Work Order stated in block 5

~~13a. Certifies that the items identified above were manufactured in conformity to:~~

- ☒ approved design data and are in condition for safe operation
☐ non-approved design data specified in block 12

14a. ☒ Part 145.A.50 Release to Service ☐ Other regulation specified in block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with part 145 and in respect to that work the items are considered ready for release to service.

13b. AUTHORIZED SIGNATURE	13d. APPROVAL/AUTHORISATION NUMBER	14b. AUTHORIZED SIGNATURE Nº. DE NÓMINA 664834	14c. CERTIFICATE/APPROVAL REF. No. UK.145.01413
13c. NAME	13e. DATE (dd/mm/yyyy)	14d. NAME: IVÁN DANIEL ORTEGA	14e. DATE (dd/mm/yyyy): 26/JUL/2023

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer works in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures

that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national

WORK SHOP REPORT

MAINTENANCE ORGANIZATION EASA PART 145 APPROVAL CERTIFICATE Nº ES.145.011		FAA AIR AGENCY CERTIFICATE NUMBER ILAY037F	
IBERIA WORK ORDER		7200693562	
CUSTOMER		AJ WALTER AVIATION	
CUSTOMER REPAIR ORDER		R412123	
DENOMINATION		CENTERING SPRING ROD YAW DAMPER	

INCOMING DATA		OUTGOING DATA	
INCOMING DATE:	23.JUN.2023	OUTGOING DATE:	26.JUL.2023
INCOMING P/N:	D2727000700600	OUTGOING P/N:	D2727000700600
INCOMING S/N:	06-8296	OUTGOING S/N:	06-8296
MOD IN:		MOD OUT:	
TASK REQUESTED:	INSPECTED/TESTED	STATUS/WORK PERFORMED:	INSPECTED/TESTED
REASON FOR REMOVAL:	IAW TO: RO		
CMM NUMBER:	27-26-41 REV.26 JAN 2023		
AIRCRAFT TAIL NUMBER:	Not reported		
ENGINE SERIAL NUMBER:	Not reported		
WARRANTY REQUESTED:	NO.	WARRANTY STATUS:	Not applicable
WARRANTY COMMENTS:	Not applicable		

EXTERNAL CONDITION / INCOMING INSPECTION:

Equipment Identification Data	☒ Yes ☐ No
Documentation	☒ Yes ☐ No
Correct config and complete	☒ Yes ☐ No
External misused (Burned, forced,	☐ Yes ☒ No

CORRECTLY PACKED AT INCOMING: YES
TYPICAL SEQUENTIAL TASKS:

Visual Incoming inspection	☒ Yes ☐ No ☐ N/A	I.A.W. CMM27-26-41 REV.26 JAN 2023
Incoming test	☒ Yes ☐ No ☐ N/A	I.A.W. CMM27-26-41 REV.26 JAN 2023
Disassembly	☐ Yes ☒ No ☐ N/A	
Cleaning	☒ Yes ☐ No ☐ N/A	I.A.W. CMM27-26-41 REV.26 JAN 2023
NDT Check	☐ Yes ☐ No ☒ N/A	
Assembly	☐ Yes ☐ No ☒ N/A	
FOD Check inspection	☒ Yes ☐ No ☐ N/A	I.A.W. CMM27-26-41 REV.26 JAN 2023
Final Test	☒ Yes ☐ No ☐ N/A	I.A.W. CMM27-26-41 REV.26 JAN 2023

TYPE OF FAULT:NOT FOUND FAULTY

<http://www.iberiamaintenance.com>**WORK SHOP REPORT****SHOP FINDINGS AND WORKS PERFORMED:**

SHOP FINDING	WORK PERFORMED
DIRTY	INSPECTION AND TEST
	FINAL TEST OK

SERVICE BULLETINS: N/A

PARTS REPLACED: N/A

SUBASSYS REPLACED: N/A

REMARKS:N/A

**INVOICE NUMBER: INV23-2123**

DATE: 28/07/2023

RO: 412123

PICKUP ADDRESS IBERIA LAE OPERADORA CAMINO DE LA MUÑOZA S/N ALMACÉN DE ENVÍOS 28042 MADRID SPAIN	DELIVERY ADDRESS B&H WORLDWIDE S PTE LTD 115 AIRPORT CARGO ROAD 02-06 SG-918466 SINGAPORE
---	--

Part Number	Qty	Description	S/N	UNIT VALUE (for customs only)
D2727000700600	1	ROD END HS CODE 8807.30.00.99 INCOTERM DAP	06-8296	1.520,20 USD
				TOTAL VALUE 1.520,20 USD

DOCUMENTO DE ACOMPAÑAMIENTO DE EXPORTACIÓN

TIPO DE DECLARACIÓN (1)		MRN	
EX	A	Otro ICE(S32)	
Formularios (3)		Decl. Seg.(500)	
001	001	23ES002861159434B0	
Partidas (5)		Fecha de expedición: 28-07-2023	
1		Aduana: ES002861	
Número de referencia (7)			

Cód.método de pago de los costes de transporte(529)		Cód. P. exped/export(15)	Cód. país de destino(17)
---		a ES	a SG
Códigos de los país(es) de paso (S13)			
Represent. pers. que presenta decl. sumaria(14b) N°			
		Masa bruta (kg) (35)	
		2.000	
Número de precinto (S28)			

Marcas y numeración - Nº contenedor(es) - Número y clase

Partida N°(32) Número y clase de bultos, partes, marcas y número de los bultos (31/1)		Descripción de las mercancías (31/2)	
Expedidor/Exportador (2)		Destinatario (8)	
Identidad medio transporte a la partida (18)		Cód. mercancías (33)	
N° de referencia único del envío (7)		Declaración sumaria/documento precedente (40)	
Documentos/certificados presentados (44/1)		N° contenedor(es) (31/3)	
Indicaciones especiales (44/2)		Número de precinto (52b)	
UNDG (44/4)		Régimen (37)	Cód. exp. (15a)
Cód. método de pago de los costes de transportes (52a)		Cód. dest. (17a)	Masa bruta (kg) (35)
		Tipo de declaración (1)	Valor estadístico (46)
001 RTDAS 1 BX CAJA		ROD END R412123 P/N D2727000700600 S/N 06-8296	
		88073000 0000 0000	
		DUA 23ES0028613158024100002	
N380 FACTURA COMERCIAL INV23-2123 20230728			
9999 R412123			
9999 P/N D2727000700600			
9999 S/N 06-8296			
1201 23ES0028613158024100002 20230615			
N740 CONOCIMIENTO AEREO 1206010374			
C601 ESIPO02022000846			
Y901 N/A			
		31 51 -- --	
		4687.540	
		2.000	
		2.000	

Fecha de llegada:
Examen de los precintos:
Observaciones:

DE: COMPONENTS CUSTOMER SUPPORT DEPT.
IBERIA LAE OPERADORA
CIF: A85850394
NUEVA ZONA INDUSTRIAL La Muñoza
Telefono: 915873194

A: Departamento de envios:
Nueva Zona Industrial La Muñoza
Almacenes
Telefono: 915873322
Mail: envios@iberia.es

PARA ENVIAR A: B&H WORDLDWIDE S Pte LTD

115 AIRPORT CARGO ROAD #02-06
SG-819466
SINGAPORE

NOTA IMPORTANTE: Las partidas abajo mencionadas son para uso de la Compañia

CANTIDAD	PART NUMBER	SERIAL NUMBER	DENOMINACION	PRICE
1	D2727000700600:FAP	06-8296	CENTERING SPRING ROD YAW DAMPER	
FABRICANTE :				

CUSTOMER PROPERTY, REPAIR ORDER: R412123

Envio mediante transportista : DHL Express account# 960301029 .

Comunicar datos de envío al cliente, y al departamento de soporte a clientes de componentes mediante correo electrónico a la dirección de mail: Ibecomponentes@iberia.es

Número de bultos (Number of pieces)	Peso Neto (Net weight in Kgs)	Dimensiones (CMS)