

1. Approving Civil Aviation Authority/Country FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number: 017293-1	
4. Organization Name and Address: Icon Aerospace, LLC 2617 Executive Point Dr Monroe, NC 28110				5. Work Order/Contract/Invoice Number: W154827			
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:		
1	SENSOR, OV TEMPERATURE	129694-2	1	1619	OVERHAULED		
12. Remarks: OVERHAULED in Accordance with HONEYWELL CMM 36-14-03 Rev.:7 Date:12/Jan/2022							
FULL DETAILS OF WORK CARRIED OUT PER WORK ORDER NUMBER: W154827							
COMPLIANCE WITH MANDATORY AIRWORTHINESS DIRECTIVES (ADs): N/A							
COMPLIANCE WITH SERVICE BULLETINS (SBs/EOs): N/A							
RMKS: MSN: 29924 AND LAST OPERATOR: BLUE PANORAMA							
This repair/modification/overhaul/inspection was performed with personnel who were part of a current drug and alcohol testing program as required by 14CFR120. Certifies that the work specified in blocks 11/12 was carried out in accordance with EASA Part-145, and in respect to that work, the component is considered ready for release to service under EASA Part 145 Approval Number EASA.145.6295							
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.							
14a ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12. Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.							
13b. Authorized Signature:		13c. Approval/Authorization No.:		14b. Authorized Signature:		14c. Approval/Authorization No.:	
						68IR700B	
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyy):		14d. Name (Typed or Printed):		14e. Date (dd/mm/yyy):	
				MATTHEW S. JACKSON		08/Jul/2022	
User/Installer Responsibilities							
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							



FAA REPAIR STATION 68IR700B
EASA REFERENCE 145.6295
2617 Executive Point Dr
Monroe, NC 28110
Ph: 704.821.4266 Fax:
Email: quotes@iconaerospace.com

Page 1

WORK ORDER

W154827

Date Released: 08/Jul/2022

TEARDOWN REPORT

AERO TRADE, LLC. dba / SETNA io
dba / SETNA io

CHICAGO, IL 60622

Contact: EVA HALACHEVA

Contact Ph: 312-549-4459

Contact Fax:

Cust RO#: 017293-1

P/N: 129694-2

S/N: 1619

Desc: SENSOR, OV
TEMPERATURE

Mfgr: HONEYWELL

Manuals

Loc	ATA	Revision
HW-067	36-14-03	7 12/Jan/2022

Work Requested UNIT RECEIVED FOR OVERHAUL AS PER O.E.M SPECS

FINDINGS

RECEIVING INSPECTION:

VERIFIED UNIT DATA PLATE, NO DISCREPANCIES FOUND.

PRELIMINARY INSPECTION:

FAILED

HIDDEN DAMAGE:

NONE

CONTINUED INSPECTION:

TESTED. UNIT FAILED FUNCTIONAL TEST. FOUND UNIT DIRTY. UNIT IS OUT OF CALIBRATION AND IS LEAKING.
DISASSEMBLY IS REQUIRED

CORRECTIVE ACTION: UNIT CONDITION OVERHAULED

CALIBRATED UNIT. REPLACED PART(S) AS REQUIRED. CLEANED AND REASSEMBLED UNIT. ALL WORK PERFORMED
AS PER O.E.M SPEC'S.

SB'S, AD'S AND RMK'S:

MSN: 29924 AND LAST OPERATOR: BLUE PANORAMA

CERTIFICATION

SERVICE PERFORMED: ☒ OVERHAULED

PARTS AND MATERIALS

QTY	PART NUMBER	DESCRIPTION	COND
1	O-RING	O-RING KIT	FN
1	S8990-611	PACKING	FN

MAINTENANCE RELEASE

The component identified above was serviced as specified above in accordance with the current regulations of the Federal Aviation Administration and is approved for return to service. Other pertinent details of the repair are on file at this repair station.

APPROVED FOR RETURN TO SERVICE BY:

MATTHEW S. JACKSON

DATE: 08/Jul/2022



FAA REPAIR STATION 68IR700B
EASA REFERENCE 145.6295
2617 Executive Point Dr
Monroe, NC 28110
Ph: 704.821.4266 Fax:
Email: quotes@iconaerospace.com

WO Packing List

Ship Doc : I212847
Shipped : 08/Jul/2022
of Items : 1
Page : 1 of 1

Bill To: AERO TRADE, LLC. dba / SETNA io
dba / SETNA io
2900 W. Chicago Ave
CHICAGO, IL 60622

Ship To: C/O AERO TRADE, LLC. dba / SETNA io
dba / SETNA io
2900 W. Chicago Ave
CHICAGO, IL 60622

Customer : AEROTRADE	Our WO : W154827	Ship Date : Jul/08/2022
Terms : NET 30	Sales : AMBER	AWB : 777339558659
FOB : ORIGIN	Person : 017293-1	Weight : 5.00
Ship Via : FEDEX G	Cust PO :	No. Boxes : 0
Ship Acct : 723157900	Attention : INVOICES/ACCOUNTIN	Dimensions : 18X12X12
Insure : N	Phone :	Customer# :
Resale :	Email : invoices@setnaio.com, ap@setnaio.com	

Item	Part Number/Description	CD	UM	Qty	B/O	Shipped/Initials
1	P/N: 129694-2 DESC: SENSOR, OV TEMPERATURE S/N: 1619	OH	EA	1	0	

Picture Taken: ☐