

1. Approving Competent Authority/Country

FOCA / Switzerland

4. Organisation Name and Address:



SR Technics Malaysia Sdn Bhd
Lot 3, Jalan Keluli 15/16, Seksyen 15,
40200 Shah Alam Selangor Darul Ehsan Malaysia

6. Item 7. Description

01 FUSE

8. Part No:

12. Remarks

Counters:
Time since test (TST):

0 Flighthours (FH).

Equi-No:

13036723

Ref.Doc.:

CMM 32-31-04

Rev.: 23

Rev.Date: 29.Jul.2016

9. Qty. 10. Serial No.

1

2-8020-25

1773

REPAIRED

11. Status/Work

3769478

5. Work Order/Contract/Invoice

3. Form Tracking Number

0052171206

Pertinent details of work performed are electronically on file at this agency / For detailed shopfindings see attached shop report

13a. Certifies that the items identified above were manufactured in conformity to:

☐ approved design data and are in a condition for safe operation
☐ non-approved design data specified in block 12

13b. Authorised Signature

13c. Approval/Authorisation Number

13d. Name

13e. Date (dd mm yyyy)

14a. (X) Part-145.A.50 Release to Service

() Other regulation specified in block 12
Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12 was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

14b. Authorised Signature

Shafiq
SR Technics
507545-00

14c. Certificate/Approval Ref. No.

CH.145.0200

14d. Name

Mohammad Shafiq Abdul Hamid

14e. Date (dd mm yyyy)

23 Dec 2020

USER/INSTALLER RESPONSIBILITIES

This Certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the national regulations by the user/installer before the aircraft may be flown. It is essential that the user/installer ensures that his/her airworthiness authority accepts items from the air worthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance record must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1. Approving Civil Aviation Authority/Country: FAA / United States		2.		3. Form Tracking Number: 0052171206	
4. Organisation Name and Address: SR Technics SR Technics Malaysia Sdn Bhd Lot 3, Jalan Keluli 15/16, Seksyen 15, 40200 Shah Alam Selangor Darul Ehsan Malaysia FAA Repair Station No: 33SY148B				5. Work Order/Contract/Invoice Number: 3769478	
6. Item: 01	7. Description: FUSE	8. Part Number: 2-8020-25	9. Quantity: 1	10. Serial Number: 1773	11. Status/Work: REPAIRED
12. Remarks: Counters: Time since test (TST): O Flighthours (FH).					
Equi-No: 13036723		Ref.Doc.: CMM 32-31-04		Rev.Date: 29.Jul.2016	
Pertinent details of work performed are electronically on file at this agency / For detailed shopfindings see attached shop report					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation. ☐ Non-approved design data specified in Block 12		14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulations specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, Part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:		13c. Approval/Authorisation Number:		14b. Authorized Signature: 	
13d. Name:		13e. Date: (dd/mm/yyyy)		14c. Approval/Certificate No.: 33SY148B	
				14d. Name: Mohammad Shafiq Abdul Hamid	
				14e. Date: (dd/mm/yyyy) 23/Dec/2020	
USER/INSTALLER RESPONSIBILITIES					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Block 13a and 14a do not constitute installation certification. In all cases, the aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					
FAA Form 8130-3 (Issue 02-14)					

1 Approving Competent, Authority/Country Malaysia		2 Department of Civil Aviation Malaysia		3 Form Tracking Number 0052171206			
4 Approved Organisation Name and Address SR Technics SR Technics Malaysia Sdn Bhd Lot 3, Jalan Keluli 15/16, Seksyen 15, 40200 Shah Alam Selangor Darul Ehsan Malaysia				5 Work order/Contract/Invoice 3769478			
6 Item	7 Description	8 Part No.	9 Eligibility*	10 Qty.	11 Serial/Batch No.	12 Status/Work	
01	FUSE	2-8020-25	737N	1	1773	REPAIRED	
13 Remarks Counters: 0 Flighthours (FH). Time since test (TST): Equi-No: 13036723 Ref.Doc.: CMM 32-31-04 Rev.: 23 Rev.Date: 29.Jul.2016							
14 Pertinent details of work performed are electronically on file at this agency / For detailed shopfindings see attached shop report Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation. ☐ Non-approved design data specified in block 13.				19 ☒ MCAR Reg.30; Release to Service ☐ other regulations specified in block 13 Certifies that unless otherwise specified in block 13, the work identified in block 12 and described in block 13 was accomplished in accordance with Part 145 and in respect to that work, the items are considered ready for release to service.			
15 Authorized Signature		16 Approval/Authorisation Number		20 Authorized Signature 		21 Certificate/Approval Ref. No. AMO/2017/13	
17 Name		18 Date (DD/MMM/YYYY)		22 Name & Authorisation Number Mohammad Shafiq Abdul Hamid / 507545		23 Date (DD/MMM/YYYY) 23/Dec/2020	

Form AN 29A / SRT

* Installer must cross-check eligibility with applicable technical data

USER / INSTALLER RESPONSIBILITIES

NOTE:

- 1 It is important to understand that the existence of the document alone does not automatically constitute authority to install the part/component/assembly.
- 2 Where the user / installer works in accordance with the national regulations of an Airworthiness Authority different from the Airworthiness Authority specified in Block 1, it is essential that the user / installer ensures that his/her Airworthiness Authority accepts parts/ components / assemblies from the Airworthiness Authority specified in Block 1.
- 3 Statements 14 and 19 do not constitute installation certification. In all cases the aircraft maintenance record must contain an installation certification issued in accordance with the national regulations by the User / installer before the aircraft may be flown.



SHOP REPORT

SR Technics Malaysia Sdn Bhd Lot 3, Jalan Keluli 15/16, Seksyen 15, 40200 Shah Alam Selangor Darul Ehsan Malaysia		CERTIFICATE NO 0052171206
		WORKORDER 3769478

DESCRIPTION FUSE	PART NO 2-8020-25	SERIAL NO 1773	A/C REGISTRATION B737_GMF	REMOVAL TAG 11873519	DATE REMOVED
----------------------------	-----------------------------	--------------------------	-------------------------------------	--------------------------------	--------------

REASON OF REMOVAL / ACTION REQUEST: BR404048142-3 02.10.2020/Philip.D: *** ON HOLD // UNIT REMOVED FROM GMF *** Service Basis : T&M CCL RFR: SEND FOR RECERTIFICATION	☐ SCHEDULED ☒ UNSCHEDULED	STATUS/WORK: REPAIRED	WARRANTY ☐ YES ☒ NO
---	---	---------------------------------	--

SHOPFINDING:

Equipment no: 13036723

0008 FAULT NOT CONFIRMED, SECONDARY FAULT

REASON FOR REMOVAL : SEND FOR RECERTIFICATION.
PERFORMED PRELIMINARY / HIDDEN DAMAGE INSPECTION ACC. WITH:
- RSQM SECTION 7.2.5 AND 7.2.7
- MOE (CH.145.0200) SECTION 2.9.2
- MOE (SRTMY.MOE.01) SECTION 2.9.2
FOUND UNREADABLE ID PLATE FIG. (1-60) AND RE-ENGRAVED.
CAP AND PLUG REPLACED.
UNIT TESTED IN ACCORDANCE WITH CMM 32-31-04 REV.23 DATED ON 29 JUL 2016,
FOUND ALL RESULT WITHIN LIMIT AND SATISFACTORY.

MODIFICATION BY SHOPVISIT:

REPLACED OR USED CONSUMABLE PARTS:

PARTNAME	PART NO	QUANTITY	BATCH
CAP	MS21914-10	1 EA	0000873210
CAP	MS21914V8P	1 EA	0000935766

REPORTED BY:

Abdul Hamid Mohammad Shafiq / 507545

DATE OF CERTIFICATE:

23/Dec/20

DATE PRINTED:

23/Dec/20