

1. Approving Civil Aviation Authority/Country: FAA/United States	2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG					3. Form Tracking Number: 006717
4. Organization Name and Address:  SETNIX, LLC 402 W. FAIRMONT DRIVE TEMPE, AZ 85282 CRS # OARR954D		5. Work Order/Contract/Invoice Number: IRO12585				
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:	
01	SOLENOID VALVE	692546-4	1 EA	828	TESTED	
12. Remarks: TESTED REFERRING OM 49-50-43, REV 3, DATED 30 JAN 2020. ALL INFORMATION IS ON FILE AT THE REPAIR STATION UNDER WO 006717. REMOVED FROM APU SIN: P-7452 Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number:"EASA 145-EASA.145.6982".						
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ operation. Non-approved design data specified in Block 12.						
13b. Authorized Signature:		13c. Approval/Authorization No.:		14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14b. Authorized Signature:  14c. Approval/Certificate No.: OARR954D		
14d. Name (Typed or Printed): Weston A Flyte		14e. Date (dd/mm/yyyy): 03/Oct/2023				
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						



Component Identification and Disposition Report

Part No: 692546-4	Nomenclature: SOLENOID VALVE	Customer: KILLICK AEROSPACE
Serial No: 828	W.O. 006717	Date: 27 Sep 2023

1.0 Origin. (Check one)

Part is: From original work order ☒ If not from original W.O., obtained where N/A

2.0 Cleaning Process (check all applicable)

Part was: Degreased ☒ Paint Removal ☐ Glass ☐ Plastic ☐ N/A ☐

3.0 Inspection Process (check all applicable)

Part was: Visual ☒ Dimensional ☐ MPI ☐ FPI ☐ Bench Check ☒
 Removed to facilitate maintenance ☐ Identification only ☐ N/A ☐

Inspection process results: Pass ☒ Fail ☐

Findings UNIT RECEIVED AS S/N N/A. IDENTIFIED AS S/N 828, PREVIOUSLY MARKED ON UNIT.

NDT Technician (If NDT'd) N/A

4.0 Disassembly (check one)

Part was: Completely disassembled ☐ Partially disassembled ☐ N/A ☒

Findings N/A

No defects noted ☐

Technician N/A

5.0 Corrective Action

This component was TESTED IAW ATA 49-50-43

Revision 3 Dated 30 Jan 2020

No corrective action required ☒

Technician ANDREW/WESTON

6.0 Setnix internal use only:

Return to Service ☒ Technician WESTON

Note: If repairs have been performed, an inspector must review the repair(s) and countersign before returning item to service.

Inspector *Weston*

Dated 03 Oct 2023

**LIMITED**

Page: 1

AJ Walter Aviation Ltd.
The Headquarters,
Maydwell Ave
West Sussex
Slinfold RH13 0AS
United Kingdom

AWB: 602328673403

[illegible]