Combined Inventory Receipt & Dispatch Check Sheet

THIS DOCUMENT MAY ONLY BE COMPLETED BY A PERSON THAT HAS RECEIVED TRAINING AND BEEN ISSUED WITH AN INSPECTORS STAMP



B&H Warehouse Reference	Job Number	Date Received
FW514427		10/01/2023

A visual inspection has been performed on this unit and the following information checked:

		RECEIPT			DISPATCH	
	Yes	NO	N/A	Yes	NO	N/A
EASA Form (8130)/Authorised Release Certificate	\square					
Trace Documentation						
OEM Certification		X	Ò			
DG Declaration		\boxtimes				
MSDS (Material Safety Data Sheet)		X				
Shelf Life Applicable		\boxtimes				
Material Certification / ATA 106		\boxtimes				
US (unserviceable) Tag		\boxtimes				
Reason for Removal Stated on Tag		X				
Packing Slip	\square					
Original Certificates Returned	✓					
Unused Statement		\boxtimes				
NIS - Non-Incident Statement		X				
Physical checks to be completed		RECEIPT			DISPATCH	
	Yes	NO	N/A	Yes	NO	N/A
Part Number on Unit Matches Paperwork	<u> </u>					
Serial Number on Unit Matches Paperwork	Ø					
Description on Unit Matches Paperwork	☑					
All Paperwork carries the same part & serial number	✓					
Blanks fitted to ALL ports	Ø					
FOD evident in ports / connectors		×				
Static Sensitive	Ø					
Warranty labels INTACT		X				
Unused Statement	. 🗆	☒				
Following tasks MUST be completed on Receipt AND Dispatch	Yes	RECEIPT NO	N/A	Yes	DISPATCH NO	N/A
Interior packaging sufficient to secure unit and weight of unit	V					
Component wrapped in static sensitive bubble/pouch	Ø		n –			
Exterior packing condition acceptable for weight of unit	Ø	ā	l i			
External Damage customer to inspect photo's		\boxtimes	П	Ä		
Photos Taken - Package Exterior	Ø					
Photos Taken - Item and packaging	<u> </u>					
Photos Taken - Component(s)	<u> </u>					
Photos Taken - Data Plates and Connectors	<u> </u>					
FirstTrac Updated	Ø					
Other (Specify)		\boxtimes				
Customer advised / Pre alert sent		\boxtimes				
Completed by (Trained Inspector Stamp)	<u> </u>					
Inspected By	Agatheite Gomez			<u> </u>		

Approving Civil Aviation 2. Authority/Country Transport Canada	AUTHORIZED RELEASE	E CERTIFICATE	3. Form Tracking Number. WO133885
4. Organization Name and Address.			
AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7	N N	A)W technique	5. Work Order, Contract or Invoice Number: T39926-1
Canada			-
6. Item: 7. Description:	8. Part Number:	9. Quantity: 10. Serial/Batch Number:	er: 11. Status/Work:
1 SMOKE DETECTOR	473597-5	1.00 11346A	REPAIRED
12. REMARKS		_	
Repaired as per CMM 26-10-66 Rev.14 Feb.10/21. For additional information refer to tear down report.	4 Feb,10/21. down report.		
		Maintenance pe	EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17
13a. Certifies the items identified above were manufactured in conformity to: Approved design data and are in a condition for safe operation.	e manufactured in conformity to: andition for safe operation.	14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.	ed in Block 12, the work identified in Block in accordance with Canadian Aviation
Non-approved design data specified in Block 12	in Block 12	X CAR 571.10 Maintenance Release	
		Other regulation specified in Block 12	
13b. Signature:	13c. Approved Organization Number	14b. Signature	14c. Approval Organization Number 33-12
13d. Name (Typed or Printed):	13e. Date	14d. Name (Typed or Printed)	14e. Date (dd/mmm/yyyy)
		Jacques Moisan	03/Jan/2023
	Installer Re	Installer Responsibilities	and the second second proper segment of the second
This certificate does not constitute authority to install the part.	to install the part.		
Installers working in accordance with the nat country specified. Statements in blocks 13a or 14a do not cons applicable national regulations before the air	tional regulations of a country other than specified in stitute installation certification. In all cases, the technic rcraft may be flown.	Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.	rtifications from the tification issued in accordance with the

AJW.TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H45 2B7, Canada www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO133885 Date Printed: 1/3/2023 Customer RO: T39926-1

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: SMOKE DETECTOR

Phone:

P/N: 473597-5

Qty: 1

Email:

S/N: 11346A

Mfg: KIDDE TECHNOLOGIES

TSN: UNK

TSO: UNK

TSR: UNK

CSN: UNK

CSO: UNK

CSR: UNK

P/N Out: 473597-5

S/N Out: 11346A

Symptoms:

CODE:

TEST AND RECERTIFY

DETAILS:

Test and recertify.

If fails test, quote for repair.

Faults:

CODE:

DISASSEMBLY / INSPECTION FINDINGS

DETAILS:

During disassembly and inspection of the unit the following anomalies were found:

Unit out of calibration.

CODE:

CLEANING

DETAILS:

Cleaning is required due to unit contaminated.

CODE:

REPAIR

DETAILS:

The following repair(s) will be performed:

Unit to be calibrated per specs.

Unit to be cleaned.

Repaired as per CMM 26-10-66 Rev.14 Feb,10/21.

Corrective Actions:

CODE:

REPAIRED

DETAILS:

Unit calibrated per specs.

Unit cleaned.

Repaired as per CMM 26-10-66 Rev.14 Feb,10/21.

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 287, Canada www.ajw-group.com

Ship Via:

WO Packing Slip

WO #: WO133885

Date: 1/3/2023

Time: 6:03:55 AM

Cust Ref #: T39926-1

SM #: SH152764



To:

A J Walter Aviation Ltd. THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, WEST SUSSEX RH13 0AS **UNITED KINGDOM**

Ship To:

B AND H WORLDWIDE INC DORAL 1523 NW 82nd Avenue **DORAL, FL 33126** USA

Order Date: 11/24/2022

Prepared By: SYSDBA Customer #: AJW01

Buyer:

Ship Via Acc: