

1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: PAZ-57382	
4. Organization Name and Address: PAZ AVIATION, INC. 7455 West 2nd. Court Hialeah, FL 33014 XPZR185L					
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	ROTARY ACTUATOR	D97C00-624	1	A93345	TESTED
12. Remarks: Unit TESTED in accordance with CMM ATA 28-09-04, Revision 4, Issued 3/20/2015. S/B and A/D's: FAA/EASA AD Notes Inspected - None Applicable. Full details of work carried out held on Work Order 57382					
Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and with respect to that work the aircraft component is considered ready for release to service under EASA Acceptance Certificate Number EASA.145.5301.					
13a. Certifies the items identified above were manufactured in conformity to:					
☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.					
13b. Authorized Signature: N/A		13c. Approval/Authorization No.: N/A		14c. Approval/Certificate No.: XPZR185L	
13d. Name (Typed or Printed): N/A		13e. Date (dd/mm/yyyy): N/A		14e. Date (dd/mm/yyyy): 20/JAN/2022	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.					
Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.					
Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

PAZ AVIATION, INC.

FAA #: XPZR185L

Work Order #: 57382

Work Order Date: 12/17/2021

Customer #: 1285

RO#: R51349

Shop #: 2

Core Return?: ☐

Desc: ROTARY ACTUATOR

S/N: A93345

MFG: ZODIAC AEROSPA

ATA: 28-09-04

P/N: D97C00-624

MDL:

Book#: 1515

Rev #: 4

Work Req: BENCH CHECK

Trouble Reported: NONE

Rec Inspection: NO VISUAL DAMAGE

Special Instructions: NONE

Preliminary FAA/EASA AD Notes Inspected - None Applicable

Inspection: VERIFIED P/N AND S/N

Hidden NONE

Damage:

Technician: GD158

Date: 01/19/2022

Inspector: A.Y

Pre Test?: Yes ☒ No ☐ Pre Test Passed?: Passed ☒ Failed: ☐

Failed Detail:

Teardown VISUALLY INSPECTED AND PERFORMED ALL FUNCTIONAL TEST IAW PAGES 1001

Findings: THROUGH 1010

AS PER C.M.M. UNIT PASSED FUNCTIONAL TEST AND VISUAL INSPECTION.
NO TEARDOWN PERFORMED.

Workscope Recommended: 04-BENCH CHECK

Technician: GD158

Date: 01/19/2022

Inspector: A.Y

Corrective VISUALLY INSPECTED AND TESTED.

Action: UNIT PASSED ALL FUNCTIONAL TEST I.A.W. MFR SPECIFICATIONS AS
STATED ON C.M.M. A.T.A. 28-09-04 REV.# 4 DATED 03/20/2015

AD Notes\SB's: FAA/EASA AD Notes Inspected - None Applicable

Technician: GD158

Date: 01/20/2022

Inspector A.Y

Final Test:

Technician GD158

Date: 01/20/2022

Inspector A.Y

Final

Technician: Gilberto Delgado

Date: 01/20/2022

Inspector: HUMBERTO ZAMORA

Date: 01/20/2022

The appliance\component identified above was serviced in accordance with current regulations of the Federal Aviation Administration, is approved for return to service and is certified as airworthy.

PAZ AVIATION, INC.

FAA #: XPZR185L

Cust# 1285 Cust Name: MIDAMERICAN AEROSPACE, LTD.

P/N: D97C00-624

Desc: ROTARY ACTUATOR

Work Order #: 57382

Work Order Date: 12/17/2021

MDL:

S/N: A93345

Parts Used: