



62014979

1. Approving Competent Authority / Country LBA / Germany		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 22137071 00000001	
4. Organisation Name and Address:  Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany					
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status / Work
01	RECEIVER MMR GLU-920		1		REPAIRED
12. Remarks A.J. Walter (Aviation) Ltd. T42497 TP R MK-No. 10 Pack Code 00 Resp. Workshop 33434021 Workshop Station HAM305					
Return to Service in Accordance with 14 CFR part 43 The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for release or return to service under FAA Certificate No.: DLAY225D TCCA Approval No.: 897-08					
Further details of work performed are attached either in a Workshop Report reference number see blocks 3 and 5 or in other applicable documents					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☒ Part-145.A.50 Release to Service ☒ Other Regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in block 12, was accomplished in accordance with Part- 145 and in respect to that work the items are considered ready for release to service.					
13b. Authorised Signature		13c. Approval / Authorisation Number		14c. Certificate / Approval Ref. Number	
		529197		DE.145.0001	
13d. Name		14d. Name		14e. Date (dd mmm yyyy)	
		Marc Rudolf		16 Nov 2023	

EASA FORM 1 - Issue 3

USER/INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that neither airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

LHT Form 30800 I-23 (HAM TQ A)




62014979

1. Approving Competent Authority / Country CAA UK		2. AUTHORISED RELEASE CERTIFICATE CAA FORM 1		3. Form Tracking Number 22137071 00000001	
4. Organisation Name and Address Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany				5. Work Order / Contract / Invoice 62014979	
6. Item 01	7. Description RECEIVER MMR GLU-920	8. Part No. 822-1152-122	9. Qty. 1	10. Serial No. 16G9PC	11. Status / Work REPAIRED
12. Remarks ATA 3436 TP R MK-No. 10 Pack Code 00 Resp. Workshop 33434021 Workshop Station HAM305 A.J. Walter (Aviation) Ltd. T42497 Opr. Hours Cycle Opr. Day TT UNKNOWN UNKNOWN UNKNOWN TSO UNKNOWN UNKNOWN UNKNOWN TSC UNKNOWN UNKNOWN UNKNOWN TSF 0 0 0					
TASK PERFORMED IN ACCORDANCE WITH CMM 34-70-09 REV. 52 / CMLS 34-70-09 ISSUE 071					
☒ Further details of work performed are attached either in a Workshop Report reference number, see block 3 and 5 or in other applicable documents.					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation ☒ Part -145 A.50 Release to Service Certifies that unless otherwise specified in block 12, the work, identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.					
13b. Authorised Signature		13c. Approval / Authorisation Number		14c. Certificate / Approval Ref. Number	
13d. Name		13e. Date (dd mmm yyyy)		14d. Name	
				UK.145.01408	
				14e. Date (dd mmm yyyy) 16 Nov 2023	
USER / INSTALLER RESPONSIBILITIES					

Note: This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Workshop Report

Customer Order No. T42497	 Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany	62014979 Certificate Ref. No.	
Part No. as received 822-1152-122	Serial No. as received 16G9PC	Work Order/Contract/Invoice 62014979	
Part No. as dispatched 822-1152-122	Serial No. as dispatched 16G9PC	Description RECEIVER MMR GLU-920	
Reason for removal Removed in serviceable condition.		Responsible Workshop 33434021	
Findings No detailed reason for removal stated. No fault logged in OMS BITE data. Forward power supply (A4): capacitors C2, C12, C15, C40, C54 and diode CR20 defective. Visual inspection performed. Paint chipped off from side covers and scratches on chassis assy, which does not affect form, fit and function of unit.		Modification Status according to Mod-Label 01 02 03 04 05 06 07 08 09 10 11 12 13 17 18 19 20 27	
Action Forward power supply (A4): capacitors C2, C12, C15, C40, C54 and diode CR20 replaced. Unit tested: final test passed.			
The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.		Name 529197, Marc Rudolf	
		Date (dd mm yyyy) 16 Nov 2023	

RFID-Smartlabel

62014979



Ident-Tag Barcode

Ident-Tag



Lufthansa Technik

Form Tracking Number
22137071 00000001

Work Order / Contract / Invoice

Description
RECEIVER MMR GLU-920

Part. No.
822-1152-122

Eligibility

Quantity
1

Status / Work
REPAIRED

Serial-/Batch No.
16G9PC

Remarks

TP R MK-No. 10
FSCM 4V792 ATA 3436

Resp. Workshop 33434021 Workshop Station HAM305

Packaging Code: 00

Installed on (Information is only required in case of installation only)

PNR NHA

SNR NHA

Position/FIN No. NHA

Station

A/C-Registration

Removed

PNR¹

SNR¹

Position/FIN No.¹

Station¹

A/C-Registration¹

Unit Barcode No.

Removed from NHA (Information is only required in case of part change on next higher assy)

PNR NHA

SNR NHA

Position/FIN No. NHA

Reason for Removal¹

☐ 22 Unscheduled

Complaint No.¹ or WO-Reference¹

☐ 11 Scheduled

Failure Description¹ (Please write in capital letters only)

CCI-ID²

Special Investigation Tag exists ☐ Yes

Stamp or ID Number + Signature^{1/2}

Date¹

Please send back to: (unless other return location is agreed)

LUFTHANSA TECHNIK AG
c/o Lufthansa Technik Logistik Services GmbH
Warenannahme / Goods Receiving
Weg beim Jaeger 193
22335 HAMBURG-FUHLBUETTEL
Deutschland

(LTLS-Information: Use this box for ZID)

¹ Mandatory entries without using CCI-Mask

² Mandatory entries using CCI-Mask