1. Approving Civil Aviation Authority/Country

Transport Canada

2.

AUTHORIZED RELEASE CERTIFICATE

FORM ONE

3. Form Tracking Number.

WO9285

4. Organization Name and Address.

AJW Technique Inc
7055, rue Alexander Fleming
Saint-Laurent QC H4S-2B7
Canada

AJW technique

5. Work Order, Contract or Invoice Number:

T18936-1

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	Drain Mast Controller	Z220H0001110	1.00	00330	REPAIRED

12. REMARKS

Repaired and tested as per cmm 30-44-01 rev.8 dated aug.06/2012.
For more information, refer to tear down report.

PRINTED FROM ELECTRONIC FILE

EASA Approval No.: EASA.145.7260
Maintenance performed in accordance with FAR 43.17

13a. Certifies the items identified above were manufactured in conformity to:

- ☐ Approved design data and are in a condition for safe operation.
- ☐ Non-approved design data specified in Block 12

14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.

- ☒ CAR 571.10 Maintenance Release
- ☒ Other regulation specified in Block 12

13b. Signature:	13c. Approved Organization Number	14b. Signature	14c. Approval Organization Number
		Jean Francois Proulx 075	**33-12**
13d. Name (Typed or Printed):	13e. Date	14d. Name (Typed or Printed)	14e. Date (dd/mmm/yyyy)
		Jean Francois Proulx	24/Dec/2014

Installer Responsibilities

This certficate does not constitute authority to install the part.

Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified.
Statements in blocks 13a or 14a do not constitute installation certification. In all cases,the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

AJW technique

7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7
www.ajw-aviation.com

Tear Down/Inspection Report

Work Order #: WO9285
Date Printed: 24/12/2014
Customer RO: T18936-1
Page: 1

To:
A J WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Phone #: **Fax #:** **Email:**

Code: AJW01 **PN:** Z220H0001110 **Serial # :** 00330 **Qty:** 1

Descr: Drain Mast Controller **Mfg:** AIRBUS

TSN: 0 **TSO:** 0 **TSR:** 0 **CSN:** 0 **CSO:** 0 **CSR:** 0

P/N Out: Z220H0001110 **Serial # out:** 00330

Symptoms:

CODE: TEST AND RECERTIFY
DETAILS: Please test and recertify.

Faults:

CODE: QUOTE
DETAILS: PRELIMINARY INSPECTION (VISUAL):

PART MISSING: NO
DAMAGE FOUND (CID): NO
HRS/CYCLE RECEIVED: N/A

ADDITIONAL REQUIREMENT:

AD, SB, MOD, SIL NO
ADD.CUST. REQUEST NO

WARRANTY REQUESTED? NO

TEST ARRIVAL:

INITIAL TEST FAIL? YES

REASON FOR REMOVAL CONFIRMED: UNKNOWN

DISASSEMBLY/INSPECTION:

ANY ANOMALIES FOUND DURING DISASSEMBLY/INSPECTION NO

WORK TYPE: TEST/REPAIR

WORKSCOPE:

CALIBRATION NO

Form created with Quantum Control(tm) technology. Product Licensed to: AJW Technique Inc.

CLEANING		YES
OUT OF SCOPE		NO
OVERHAUL		NO
PAINTING		NO
PCBR		NO
REPAIR		YES
REWORK	NO	
TIME CONTROLLED/TX		NO
RE-QUOTE:		NO

CODE: INITIAL TEST FAILURE

DETAILS: Initial test failure is attributed to Heater values out of specs.

CODE: CLEANING

DETAILS: Cleaning is required due to unit dirty.

CODE: REPAIR

DETAILS: The following repair(S) will be performed:
Heater values to be adjusted per cmm specs.
Unit to be cleaned.

Corrective Actions:

CODE: REPAIRED

DETAILS: Heater values adjusted per cmm specs.
Unit cleaned.
Repaired and tested as per cmm 30-44-01 rev.8 dated aug.06/2012.