

1. Approving Civil Aviation Authority/Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE		3. Form Tracking Number. WO151354	
4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada				5. Work Order, Contract or Invoice Number: T42736	
6. Item 7. Description:		8. Part Number:		9. Quantity:	10. Serial/Batch Number:
1 VOR/MB NAVIGATION RECEIVER VOR-90i		822-0297-001		1.00	131772
11. Status/Work: INSPECTED/TESTED					
12. REMARKS Inspected and tested serviceable per CMM 34-55-94 Rev 26 dated 18 May 2021. For additional information refer to Tear Down/Inspection Report.					
EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17					
14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		13b. Signature 		14c. Approval Organization Number 33-12	
13c. Approved Organization Number		14d. Name (Typed or Printed) Ericson Digo		14e. Date (dd/mm/yyyy) 01/Dec/2023	
13d. Name (Typed or Printed):		13e. Date			
Installer Responsibilities					
This certificate does not constitute authority to install the part. Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.					

AJW TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada
www.ajw-group.com

Tear Down/Inspection Report

Work Order: WO151354

Date Printed: 12/1/2023

Customer RO: T42736

Page: 1

To:
A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: VOR/MB NAVIGATION RECEIVER VOR-900

Phone:

P/N: 822-0297-001

Qty: 1

Email:

S/N: 131772

Mfg: ROCKWELL COLLINS

TSN: UNK

TSO: 0

TSR: 0

CSN: UNK

CSO: 0

CSR: 0

P/N Out: 822-0297-001

S/N Out: 131772

Symptoms:

CODE: REASON FOR REMOVAL

DETAILS: TEST AND RECRT

Faults:

CODE: NORMAL ON TEST

DETAILS: Passed test on arrival. Normal on test.

CODE: DISASSEMBLY / INSPECTION FINDINGS

DETAILS: During disassembly and inspection of the unit, found dust accumulation in the unit (see picture).

CODE: CLEANING

DETAILS: Cleaning is required due to dust contamination.

CODE: INSPECT / TEST

DETAILS: The following tasks will be performed:

- inspection
- test on arrival
- cleaning
- check for intermittent connections
- test per CMM

Corrective Actions:

CODE: INSPECTED/ TESTED

DETAILS: Unit inspected, tested on arrival, cleaned, checked boards/connectors, and tested.
Inspected and tested serviceable per CMM 34-55-94 Rev 26 dated 18 May 2021.

AJW TECHNIQUE

100-7055 Alexander-Fleming, Saint-Laurent, QC, H4S 2B7, Canada
www.ajw-group.com

WO Packing Slip

WO #: WO151354

Date: 12/1/2023 Time: 12:10:12 PM

Cust Ref #:T42736

SM #: SH171427



SH171427

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Ship To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD
WEST SUSSEX RH13 0AS
UNITED KINGDOM

Order Date: 11/15/2023

Ship Via:

Ship Via Acc:

Prepared By: SYSDBA

Customer #: AJW01

Buyer:

Part Number/Description

Qty

822-0297-001 VOR/MB NAVIGATION RECEIVER VOR-900

1

Loc/Whse:

Serial #: 131772



DOCKED