

1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: 33279							
4. Organization Name and Address: SAFE FUEL SYSTEMS 860 West 84th Street Hialeah, FL 33014 UNITED STATES		5. Work Order/Contract/Invoice Number: RTMR338931		6. Item: 7. Description: 8. Part Number: 9. Quantity: 10. Serial Number: 11. Status/Work:							
1		TANK ISOLATION VALVE ASSEMBLY		HTE900209-001		1		25130487		REPAIRED	
12. Remarks: In accordance with manual No. 28-23-45 Revision: 2 Revision Date: MAR 31 2002 The component identified above was REPAIRED in accordance with current Federal Aviation Administration regulations and found to be airworthy for return to service. Pertinent details of the work performed are only on file at our facility under the work order stated above. CHECKED FOR ADS AND FOUND NONE APPLICABLE Certifies that the work specified in Block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release under EASA Part-145 Approval Number: "EASA 145-145.5667".											
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.											
14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.											
13b. Authorized Signature:		13c. Approval/Authorization No.:		14b. Authorized Signature:		14c. Approval/Certificate No.:					
						FAA #SLGR312X					
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14d. Name (Typed or Printed):		14e. Date (dd/mm/yyyy):					
ANDRES ANGEL				ANDRES ANGEL		17/AUG/2018					
User/Installer Responsibilities											
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.											



SAFE FUEL SYSTEMS

860 West 84th Street

Hialeah, FL 33014

UNITED STATES

Email: quotes@safefuelsystems.com

www.safegroup.us

Phone: 954.929.7233

Fax: 954.929.7235



TEARDOWN REPORT

W/O No. 33279 / Page: 2 of 2

Repair/Service WORK ORDER No. 33279

Teardown/Hidden Dmge

PARTIALLY DISASSEMBLED, CLEANED AND INSPECTED. THE FOLLOWING WAS FOUND: LEAKAGE THROUGH SEALS. UNIT REQUIRES LISTED ITEMS PLUS O-RINGS FOR REPAIR IN ACCORDANCE WITH MANUFACTURER'S CMM.

Corrective Action

REPLACED ITEMS LISTED ABOVE. UNIT WAS ASSEMBLED, TESTED AND FINALED.

The component identified above was REPAIRED in accordance with current Federal Aviation Administration regulations and found to be airworthy for return to service. Pertinent details of the work performed are only on file at our facility under the work order stated above.

Authorized Signature

Name

Andres J. Angel

Date:

17 AUG 2018