

1. Approving Competent Authority / Country CAA/UK		2. AUTHORISED RELEASE CERTIFICATE CAA FORM 1				3. Form Tracking Number: WAV2206851	
4. Organization Name and Address: Avia Technique SK AeroSafety Group		Avia Technique Ltd. Unit 1,3,4, 6 Fishponds Estate Fishponds Road Wokingham, Berkshire, United Kingdom RG41 2QJ Ph: +441189789789, Fax: +441189794511				5. Work Order / Contract / Invoice Number: WAV2206851 R394519	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:		
1	Reheater	755C0000-01	1.00	81210-53794	Overhauled		
12. Remarks: CMM: 21-52-08 Revision: 12 Avia Technique have checked and verified compliance with all applicable AD's and SB's.							
"The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect to that work, the items are approved for return to service under certificate no. 18QY183X"							
13a. Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12							
14a. ☒ Part-145 A.50 Release to Service		14. ☒ Other regulation specified in Block 12					
Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.							
13b. Authorised Signature:		13c. Certificate /Approval Ref No.:		14c. Certificate /Approval Ref No.:			
		UK.145.00846		UK.145.00846			
13d. Name		13e. Date (dd/mm/yyyy):		14e. Date (dd/mm/yyyy):			
				19/May/2022			
14d. Name Robert West							
USER / INSTALLER RESPONSIBILITIES							
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.							

1. Approving Competent Authority / Country EASA		2.		AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number: WAV2206851			
4. Organization Name and Address:  Avia Technique SK AeroSafety Group				Avia Technique Ltd. Unit 1,3,4, 6 Fishponds Estate Fishponds Road Wokingham, Berkshire, United Kingdom RG41 2QJ Ph: +441189789789, Fax: +441189794511				5. Work Order / Contract / Invoice Number: WAV2206851 / R394519	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:				
1	Reheater	755C0000-01	1.00	81210-53794	Overhauled				
12. Remarks: CMM: 21-52-08 Revision: 12 Avia Technique have checked and verified compliance with all applicable AD's and SB's.									
13a. Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12								14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.	
13b. Authorised Signature:		13c. Certificate /Approval Ref No.:		14b. Authorised Signature: 		14c. Certificate /Approval Ref No.: EASA.UK.145.00846			
13d. Name		13e. Date (dd/mm/yyyy):		14d. Name Robert West		14e. Date (dd/mm/yyyy): 19/May/2022			
USER / INSTALLER RESPONSIBILITIES									
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.									



Avia Technique Ltd.
Unit 1,3,4, 6 Fishponds Estate
Fishponds Road
Wokingham, Berkshire, United Kingdom
RG41 2QJ
Ph: +441189789789, Fax: +441189794511

Tear Down/Inspection

Work Order #: WAV2206851

Date Printed: 09/05/2022

Page: 1

To:

A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

Ship To:

A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

Reference: R394519
Date Received: 28/04/2022
Part Number: 755C0000-01
Description: Reheater
Serial Number: 81210-53794

Customer Remarks:

Overhaul

Results from inspection:

Faults:

Unit's protective coating is deteriorated and requires recoat.

Unit's corrosion protection is deteriorated and requires recoat.

Corrective actions:

Overhaul with reference to the correct CMM Rev

Overhaul, Clean and apply corrosion protection. Test and Certify with reference to the correct issue of the CMM.

Inspection report generated by: Luke Houghton