

EASA FORM 1

1. Approving Competent Authority / Country EASA		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number W79337	
4. Organisation Name and Address Rotable Repairs Ltd 20 Progress Road, Leigh-on-Sea, Essex, SS9 5PR Tel: +44 1702 529888 Fax: +44 1702 521632 E-mail: info@rotablerepairs.com				5. Work Order/Contract/Invoice W79337 R395394 A J WALTER AVIATION LTD	
6. Item 1		7. Description BRAKE UNIT		8. Part No 2-1578-7	
9. Qty 1		10. Serial No. 20192		11. Status/Work REPAIRED	
12. Remarks Work order W79337 describing the work performed is held on file at this Air Agency. All Work Carried Out in Accordance with Manual: 32-41-82 Revision No: 6 Dated: 30 MAY 2022 Manufacturer: Safran/Collins No modifications carried out at this shop visit. Unit repaired only and released with original part life heat pack re-fitted. Wear pin 0.840" (approx 28% life) remaining.					
14a. ☒ Part 145A.50 Release to Service ☐ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part 145 and in respect to that work the items are considered ready for release to service.					
14b. Authorised Signature 				14c. Certificate/Approval Ref. No. EASA. UK.145.00819	
14d. Name P. J. J. J. J. J.				14e. Date (dd/mm/yyyy) 24/Aug/2022	

USER/INSTALLER RESPONSIBILITIES

This Certificate does not automatically constitute authority to install the item(s)

Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the Airworthiness Authority of the country specified in block 1.

Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.


1. Approving Competent Authority / Country CAA / United Kingdom		2. CAA FORM 1		3. Form Tracking Number W79337	
4. Organisation Name and Address Rotable Repairs Ltd 20 Progress Road, Leigh-on-Sea, Essex, SS9 5PR Tel: +44 1702 529888 Fax: +44 1702 521632 E-mail: info@rotablerepairs.com				5. Work Order/Contract/Invoice W79337 R395394 A J WALTER AVIATION LTD	
6. Item 1		7. Description BRAKE UNIT		8. Part No 2-1578-7	9. Qty 1
				10. Serial No. 20192	11. Status/Work REPAIRED
12. Remarks Work order W79337 describing the work performed is held on file at this Air Agency. All Work Carried Out in Accordance with Manual: 32-41-82 Revision No: 6 Dated: 30 MAY 2022 Manufacturer: Safran/Collins No modifications carried out at this shop visit. Unit repaired only and released with original part life heat pack re-fitted. Wear pin 0.840" (approx 28% life) remaining. The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR and part 43 and in respect to that work, the items are approved for return to service under FAA certificate no RXWY824X					
14a. ☒ Part 145A.50 Release to Service ☒ Other regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part 145 and in respect to that work the items are considered ready for release to service.					
14b. Authorised Signature 				14c. Certificate/Approval Ref. No. UK 145.00819	
14d. Name P. F. C. WALTER				14e. Date (dd/mm/yyyy) 24/Aug/2022	

USER/INSTALLER RESPONSIBILITIES

This Certificate does not automatically constitute authority to install the item(s)

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in block(s) 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Organisation Name and Address: Rotable Repairs Ltd 20 Progress Road Leigh-on-Sea, Essex, SS9 5PR P:+44 (1702) 529888 F:+44 (1702) 808753 info@rotablerepairs.com			Customer Order No R395394		RRL W/O Ref No. W79337
			Company Name A J WALTER AVIATION LTD		Open Date: 08-Jun-2022
Part Number: 2-1578-7	Description: BRAKE UNIT	Outboard SN 20192	Inboard SN	Qty: 1	
Manufacturer:	Position:	Owner: A J WALTER AVIATION LTD	From A/C	Landings:	
Warranty Claim: Yes ☐ No ☒ Accepted: Yes ☐ No ☒		Man Hours:	Sub Order Issue:	Date Out:	
Work Requested: REPAIR					
Details: Corrective Actions:					
REPAIRED Unit dismantled, cleaned, inspected and NDT inspected all tests passed satisfactory, re-assembled, tested, inspected and released in accordance with CMM procedures.					
Authorised Signature:  RRL 7		Name: 		Date: 24-Aug-2022	

Deliver To:

A J WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
WEST SUSSEX
SLINFOLD RH13 0AS
UNITED KINGDOM

Cust Ref: R395394

Ship Created: 24/08/2022

SO / WO No. W79337

Ship Via: NONE

Cust Ship Account:

A/W Bill No:

Part No. / Description	Serial No.	Qty	S/L	Job No. / Ref No.
2-1578-7 BRAKE UNIT	20192	1	36	W79337

Packed By:

Released By:

Weight (Kg):

Dims (CM):

Boxes in Shipment

Signed By:

Print Name:

For :

NONE

Date/Time:

Vehicle Reg:

For the above items in good condition

Rotable Repairs Ltd | 20 Progress Road | Leigh-on-Sea | Essex | United Kingdom | SS9 5PR

P:+44 1702 529888 F:+44 1702 808753 info@rotablerepairs.com www.rotablerepairs.com

SHIP:



Deliver To:

A J WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
WEST SUSSEX
SLINFOLD RH13 0AS
UNITED KINGDOM

Cust Ref: R395394

Ship Created: 24/08/2022

SO / WO No. W79337

Ship Via: NONE

Cust Ship Account:

A/W Bill No:

Part No. / Description	Serial No.	Qty	S/L	Job No. / Ref No.
2-1578-7 BRAKE UNIT	20192	1	36	W79337

Packed By:

Released By:

Weight (Kg):

Dims (CM):

Boxes in Shipment

Signed By:

Print Name:

For:

NONE

Date/Time:

Vehicle Reg:

For the above items in good condition

Rotable Repairs Ltd | 20 Progress Road | Leigh-on-Sea | Essex | United Kingdom | SS9 5PR
P:+44 1702 529888 F:+44 1702 808753 info@rotablerepairs.com www.rotablerepairs.com

SHIP:

