

1. Approving Competent Authority/Country CAA/UNITED KINGDOM		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number. 166942	
4. Organisation Name and Address. MUIRHEAD AEROSPACE LIMITED T/A MUIRHEAD AVIONICS Muirhead Aerospace Ltd 3 The Square Heathrow Southall Lane, Southall, Middlesex UB2 5NH UNITED KINGDOM				5. Work Order/Contract/Invoice Work Order No: GA12448 Customer Order No: R301044	
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
1	NAV CONTROL PANEL	G7505-01	1	187	Repaired
12. Remarks EMBODIED SB G7504-01-34-06 REV. 00 DATED JULY 02, 2013 Manual ID: A46704-01 , Revision #: 17, Revision Date: 07/10/2013 14 CFR 43.9 Return to Service The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. H9EY443N					
Repair report attached reference GA12448 TCCA Approval Ref: 807-07 Date(m/d/y): Sep/23/2016 Signed: 					
13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in a condition for safe operation. ☐ non-approved design data specified in block 12					
13b. Authorised Signature:		13c. Approval/Authorisation No.		14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.	
13d. Name		13e. Date (dd mmm yyyy)		14b. Authorised Signature  14c. Certificate/Approval Ref No. UK.145.00592	
USER/INSTALLER RESPONSIBILITIES This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.		14d. Name 		14e. Date (dd mmm yyyy) 23 Sep 2016	



Muirhead Aerospace Limited

Contact Name: Customer Services

Telephone: +44 (0)20 8843 6972

Fax: +44 (0)20 8843 6902

Tear Down/Inspection

Work Order #: GA12448

Date Printed: 23-Sep-16

Work Type: Repaired

Page: 1

To:

ATTN: REBECCA HAYTER
AJ WALTER (AVIATION) LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD
WEST SUSSEX RH13 0AS

Ship To:

AJ WALTER (AVIATION) LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD
WEST SUSSEX, RH13 0AS UK

Cust.PO Ref.: R301044

Cust.Phone: 01403 798102

Cust.Email:

Cust.Code: 200382

Cust.Fax:

Station: SOUTH

Part No. In: G7505-01

Description: NAV CONTROL PANEL

Qty: 1

Part No. Out: G7505-01

Serial No: 187

Previous WO No:

TSO: 0

TSN: 0

TSR: 0

CSO: 0

CSN: 0

CSR: 0

Documentation: A46704-01

Location: SOU

ATA No:

Rev. & Date: 17 07-Oct-2013

Symptoms:

REPORT

Visual inspection - Unsatisfactory

Functional test - Unsatisfactory

Unit inspected and tested - Initial inspection shows Auto/Man button and front panel damaged -

Also noted test button, 3, 5, 7, 8, CLR and mode up/down all U/s - Unit requires replacement front panel IAW Mod J - Front panel assy replaced IAW SB G7505-01-34-06

Unit assembled and tested to full spec - Satisfactory

Inspection Signature:

Stamp:

Inspect. Print Name:

R. G. Gammie

An AMETEK Aerospace & Defense Company