

1. Approving Civil Aviation Authority/Country:

2.

3. Form Tracking Number:

FAAUNITED STATES

AUTHORIZED RELEASE CERTIFICATE
FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

F41549

4. Organization Name and Address:

VSE Aviation Services, Inc.

3361 Enterprise Way, Miramar, FL. 33025, Fax:954/430-6601, 954/430-6600

Repair Station: 9QAR940B

5. Work Order/Contract/Invoice Number:

F41549 / R377124

6. Item

7. Description:

8. Part Number:

1

ENG STARTER

3505436-7

9. Quantity:

1.00

10. Serial Number:

2301

11. Status/Work:

OVERHAULED

12. Remarks:

This Item was Overhauled I/AW Manual # CMM 80-11-13, Revision # 14 Revision Date 2/10/2020

NO APPLICABLE ADS AND NO SBS INSTALLED.

Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the product/article is considered ready for release to service under EASA Part 145 Approval no. EASA.145.6610

13a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in a condition for safe operation.

☐ Non-approved design data specified in Block 12

14a. ☒ 14 CFR 43.9 Return to Service

☒ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval Authorization No.:

14b. Authorized Signature:

14c. Approval/Certificate No.:

13d. Name (Typed or Printed):

13e. Date (dd/mm/yyyy):

14d. Name (Typed or Printed):

NELSON NAVARRO

14e. Date (dd/mm/yyyy):

10-Jun-2021

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

WORK ORDER FORM 100

Page No. 1

VSE Aviation Services, Inc.

3361 Enterprise Way
Miramar, FL. 33025
Fax: 954/430-6601
954/430-6600

**FAA CRS No: 9QAR940B****Work Order #: F41549**

Step: SH-SHIPPING

Department: Shop FLA

Location: FLA PNE

Customer: **AJW001 / AJ WALTER AVIATION**Cust RO#: **R377124**Mfg: **HONEY*******NO PMA PARTS*****

Warranty Code: 00

Goodthru AD#:

Outgoing: **3505436-7 / ENG STARTER**

S/N: 2301

Incoming P/N: 3505436-7

Incoming S/N: 2301

Incoming work Req: RE

Outgoing Work Req: OVERHAULED

Repair Manuals: F0160

RevDate: 2/10/2020

Rev#: 14

ATA: 80-11-13

Tools:

REASON FOR REMOVAL: Date Recvd: 8/4/2020 Date Reqrd 8/16/2020 Date Estmtd: 8/16/2020

DEFECT-STARTER CHIP DETECTOR WITH PARTICLES LAGER THAN 2.5MM.PLEASE REPAIR UNDER T&M - QUOTE AND HOLD.

PRELIMINARY INSPECTION: DATE:5/AUG/2020 INSPECTOR:NFN

VERIFIED PN, SN WITH RO AND ID PLATE. UNIT RECEIVED WITH NICKS AND SCRATCHES THAT WILL NOT AFFECT FIT, FORM OR FUNCTION. UNIT RECEIVED WITHOUT DRAIN PLUG.

PRE TEST (Yes/No): N DATE:5/AUG/2020 INSPECTOR:NFN

UNABLE TO PRETEST UNIT DUE TO CONDITION RECEIVED, MISSING DRAIN PLUG DISASSEMBLY REQUIRED FOR FURTHER EVALUATION.

HIDDEN DAMAGE:

NONE NOTED

TEARDOWN FINDINGS:

UNIT DISASSEMBLED AND INSPECTED AS REQUIRED FOR OVERHAUL AND FOUND THE FOLLOWING: FOUND WORN SEALS, BEARINGS, WASHER KEY AND PACKINGS. UNIT RECEIVED WITHOUT DRAIN PLUG AND IS REQUIRED. UNIT REQUIRES CLEANING, NDT AND BALANCING. OVERHAUL QUOTE

TECHNICIAN: HDT

DATE: 5/AUG/2020

INSPECTOR: LAV

FINAL INSPECTION BEFORE ASSEMBLY DATE:06/10/21 INSPECTOR:NFN

CORRECTIVE ACTION:

THIS UNIT WAS DISASSEMBLED, CLEANED, INSPECTED, REPAIRED AS NECESSARY, REASSEMBLED, FUNCTIONALLY TESTED, AND OVERHAULED IN ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS.

TECHNICIAN: AXN

DATE: 06/10/21

INSPECTOR: NFN

MODIFICATION/SERVICE BULLETINS:

NO APPLICABLE AD'S AND NO SB'S INSTALLED.

TEST DATA USED:

ATA:80-11-13 REV#14 10FEB2020

Test Technician: AXN

Date: 06/10/21

WORK ORDER FORM 100

Page No. 2

VSE Aviation Services, Inc.

3361 Enterprise Way
Miramar, FL. 33025
Fax: 954/430-6601
954/430-6600



FAA CRS No: 9QAR940B

Work Order #: F41549

Step: SH-SHIPPING

Department: Shop FLA

Location: FLA PNE

Customer: **AJW001 / AJ WALTER AVIATION**

Cust RO#: **R377124**

Mfg: **HONEY**

Outgoing: **3505436-7 / ENG STARTER**

*****NO PMA PARTS*****

S/N: 2301

Warranty Code: 00

Goodthru AD#:

Incoming P/N: 3505436-7

Incoming S/N: 2301

Incoming work Req: RE

Outgoing Work Req: OVERHAULED

Final Inspection: NFN

Date: 06/10/21

ADDITIONAL COMMENTS:

N/A

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS OVERHAULED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE. OTHER PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Approved For Return to Service by *Nelson Navarro* **NELSON NAVARRO**



Date: 6/10/2021 2:58:14 PM