


1. Approving Competent Authority / Country CAA/UK		2.		AUTHORISED RELEASE CERTIFICATE CAA FORM 1				3. Form Tracking Number: WAV2320805	
4. Organization Name and Address:  Avia Technique SK AeroSafety Group				Avia Technique Ltd. Unit 1,3,4, 6 Fishponds Estate Fishponds Road Wokingham, Berkshire, GB RG41 2QJ Ph: +441189789789, Fax: +441189794511					
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	5. Work Order / Contract / Invoice Number: WAV2320805 R419093				
1	Fire Extinguisher	74-20	1.00	7688	11. Status / Work: Overhauled				
12. Remarks: CMM: 26-24-05 Revision: U Date Of Manufacture: 12/2003. Next Overhaul / Hydrostatic Test: 11/2033. Last Overhaul/Hydrostatic Test: 11/2023. Checked Weight: 2.120 kg. Avia Technique have checked and verified that there are no pertinent ADs or SBs relevant. "The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect to that work, the items are approved for return to service under certificate no. 18QY183X"									
13a. Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12									
13b. Authorised Signature:		13c. Certificate /Approval Ref No.:		14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in Block 12		14b. Authorised Signature: 			
13d. Name		13e. Date (dd/mm/yyyy):		14c. Certificate /Approval Ref No.: UK.145.00846		14d. Name Mark Northway			
13e. Date (dd/mm/yyyy):		14e. Date (dd/mm/yyyy): 03/Nov/2023							
USER / INSTALLER RESPONSIBILITIES									
This certificate does not automatically constitute authority to install the item(s).									
Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.									
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.									

1. Approving Competent Authority / Country EASA		2.		AUTHORISED RELEASE CERTIFICATE EASA FORM 1				3. Form Tracking Number: WAV2320805	
4. Organization Name and Address:  Avia Technique SK AeroSafety Group				Avia Technique Ltd. Unit 1,3,4, 6 Fishponds Estate Fishponds Road Wokingham, Berkshire, GB RG41 2QJ Ph: +441189789789, Fax: +441189794511					
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:				
1	Fire Extinguisher	74-20	1.00	7688	Overhauled				
12. Remarks: CMM: 26-24-05 Revision: U Date Of Manufacture: 12/2003. Next Overhaul / Hydrostatic Test: 11/2033. Last Overhaul/Hydrostatic Test: 11/2023. Checked Weight: 2.120 kg. Avia Technique have checked and verified that there are no pertinent ADs or SBs relevant.									
13a. Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12					14a. ☒ Part-145,A.50 Release to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.				
13b. Authorised Signature:		13c. Certificate /Approval Ref No.:			14b. Authorised Signature:  		14c. Certificate /Approval Ref No.: EASA.UK.145.00846		
13d. Name		13e. Date (dd/mm/yyyy):			14d. Name Mark Northway		14e. Date (dd/mm/yyyy): 03/Nov/2023		
USER / INSTALLER RESPONSIBILITIES									
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.									



Avia Technique Ltd.
Unit 1,3,4, 6 Fishponds Estate
Fishponds Road
Wokingham, Berkshire, GB RG41 2QJ
Ph: +441189789789, Fax: +441189794511
customerservices@aviatechnique.co.uk

Tear Down/Inspection

Work Order #: WAV2320805

Date Printed: 31/10/2023

Page: 1

To:

A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

Ship To:

A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

Reference: R419093
Date Received: 23/10/2023
Part Number: 74-20
Description: Fire Extinguisher
Serial Number: 7688

Customer Remarks:

Overhaul

Results from inspection:

Faults:

Unit is due overhaul.

Unit received with corroded valve assembly.

DOM: 12/2003.

Last overhaul: 09/2013.

Next overhaul due: 09/2023.

Corrective actions:

Overhaul with reference to the correct CMM Rev

Replace valve assembly.

Inspection report generated by: Harry Henson