


1. Approving Civil Aviation Authority / Country: FAA/United States	2. Authorized Release Certificate FAA Form 8130-3, Airworthiness Approval Tag			3. Form Tracking Number: 158670	
4. Organization Name and Address: Aviation Instruments Repair Specialists, Inc. A.I.R.S./14316 Commerce Way Miami Lakes, FL 33016 U.S.A. Phone: (305) 887-5600 Fax: (305) 820-0931				5. Work Order / Contract / Invoice Number: R370804	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	ICE DETECTOR	0871DL6	1ea.	04496	REPAIRED
12. Remarks: REPAIRED in accordance with CMM: 30-81-27 Revision: 2 Date: 2/28/2013 Full details of work carried out per work order no. 158670 Modification Level: N/A Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the ICE DETECTOR is considered ready for release to service under EASA Part 145 approval no. EASA EASA.145.5033 . FAA Ad's: None EASA Ad's: None					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.					
14a. ☐ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplish in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.					
13b. Authorized Signature: Not Applicable		13c. Approval/Authorization No.: Not Applicable		14c. Approval/Certificate No.: VTBR433V	
13d. Name (Typed or Printed): Not Applicable		13e. Date (dd/mm/yyyy): Not Applicable		14e. Date (dd/mm/yyyy): 15/Jan/2020	
14b. Authorized Signature:  14d. Name (Typed or Printed): Elio Kocijancic					
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block1. Statements in Block13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

TearDown/Inspection Form

Aviation Instruments Repair Specialists, Inc.

A.I.R.S./14316 Commerce Way

Miami Lakes, FL 33016

U.S.A.

Phone: (305) 887-5600 Fax: (305) 820-0931

C.R.S. No.: VTBR433V

Work Order: 158670

Date: January/15/2020

Phone: (305) 887-5600

Fax: (305) 820-0931

Sold To:

A J WALTER AVIATION

The Headquarters, Maydwell Ave. Slinfold

West Sussex RH13 0SH, UK

Ship To:

A J WALTER AVIATION LIMITED

THE HEADQUARTERS MAYDWELL AVENUE

SLINFOLD, WEST SUSSEX RH13 0SH

Part Number: 0871DL6

Serial: 04496

Manufacturer: GOODRICH

Description: ICE DETECTOR

Model:

Purchase Order: R370804

Service Performed: REPAIRED

Data used: Manual Number: 30-81-27 Revision: 2 Date: 2/28/2013

TearDown/Inspection Data

1. Removal: ICE DET L INOP

Inst.: REPAIR T&M

2. Initial Inspection Findings

Appearance: Normal on Visual Inspection

Loose or Missing Parts: No Loose or Missing Parts

Mod. Level: N/A

Corrosion: No Corrosion Noted

Physical Damage: No Damage Found

3. Teardown

Dissassembly: Normal

Painting: None

Cleaning: Normal Cleaning

Assembly: Normal Assembly

4. Test

Operation: Cold Solder Joint

Was Complaint Verified: No

Mods. Completed: None

5. Final

Warranty Accepted: N/A

Final Test and Inspection:

Final Inspection Normal

T.S.O.:

A.T.A.: 30-81-27

A.D. S.B. NO A.D. / S. B. REQUIRED

Work Done: UNIT WAS INSPECTED, DISASSEMBLED, CLEANED, ASSEMBLED, SOLDERED FL2 AND REPAIRED I/A/W MFG. SPECS. TESTED OPERATION AND FOUND READY TO RETURN TO SERVICE. NO APPLICABLE SB OR A/D'S ON FILE. ATA 30-81-27. WORK BY TITO RODRIGUEZ.

Maintenance Release


This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect to the work performed is approved to return to service. Pertinent details of the work performed are on File at this Agency under Work

Order No.: 158670

Inspector's Name: Elio Kocijancic

Certificate No. 2569075

Technician: Tito Rodriguez

Signature: 

Date: January/15/2020

Form CRS-3