


1. Approving Civil Aviation Authority/Country: FAA/United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: W22743	
4. Organization Name and Address:  General MRO Aerospace 3018 NW 72nd Ave MIAMI, FL 33122 Ph: 305-482-9903, Fax: 305-482-9905 sales@generalmroaerospace.com FAA Approval Holder: 19GR994Y				5. Work Order, Contract or Invoice Number: 35206	
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	VALVE	C24736001-0-1	1	U310	INSPECTED
12. REMARKS: Full details describing the actual work performed are contained and held in W/O # W22743. This unit was Inspected in accordance with FAA accepted and approved data. MFG: SAFRAN ATA Manual ID: 32-57-01, Revision #: 12, Revision Date: 3/17/2015					
Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number: "EASA.145.6095".					
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:	13c. Approval Authorization No:	14b. Authorized Signature: 		14c. Approval/Certificate No: 19GR994Y	
13d. Name (Typed or Printed):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed): Cristian Munoz		14e. Date (dd/mm/yyyy): 02/Oct/2015	
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1 it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

**General MRO Aerospace**

3018 NW 72nd Ave
MIAMI, FL 33122
Ph: 305-482-9903, Fax: 305-482-9905
sales@generalmroaerospace.com

Teardown**Work Order #: W22743**

Date Printed: 10/2/2015

Time: 4:06:20 PM

Page: 1

To:

Diversified Aero Svc Inc (DASI)
11920 SW 128th Street
Miami, FL 33186

Ship To:

Diversified Aero Svc Inc (DASI)
11920 SW 128th Street
Miami, FL 33186

Ref #: 35206

Phone #: 305-234-2333

Fax #: 305-234-6100

Email: QUOTES@DASI.COM

Code: 372

PN: C24736001-0-1

Descr: VALVE

Qty: 1

Mfg: SAFRAN

Serial Number: U310

Entry Date: 9/8/2015

Need Date: 10/2/2015

Compl. Date: 10/2/2015 4:01

Warranty: No Container:

REMARKS**SUBCOMPONENT PN AND SN**

Servo P/N A68982-002 S/N B3279

REASON FOR REMOVAL

None Given

PRELIMINARY INSPECTION

Verified P/N and S/N from RO and Unit. Unit arrived dirty.

PRE TEST (YES/NO)

Unit passed all functional testing

HIDDEN DAMAGE

N/A

TEARDOWN FINDINGS

During teardown inspection the following discrepancies were found:

Unit passed all functional testing. Unit was cleaned and inspected. Upon inspection found protective cap missing and faded fluid plate. Unit requires paint, reconditioning and all mentioned parts for inspection.

Discrepancies Noted:

1. Faded Fluid Plate- Requires replacement

Maintenance Release Statement (FAR Pars 121, 125 and 135)

The instruments and or Components above was Serviced and Inspected with Pride and in accordance with current F.A.A. Regulations and is
☒ Approved ☐ Not approved to Return to Service. Pertinent details of the Services are on files at this Repair Station.

Name:

Authorized Signature:

Inspector Seal:

Date: 10/2/2015

Cristian Munoz



Form created with Quantum Control(tm) technology. Product Licensed to: General MRO Aerospace

Form: GMA 340

**General MRO Aerospace**

3018 NW 72nd Ave
MIAMI, FL 33122
Ph: 305-482-9903, Fax: 305-482-9905
sales@generalmroaerospace.com

Teardown**Work Order #: W22743**

Date Printed: 10/2/2015

Time: 4:06:21 PM

Page: 2

To:

Diversified Aero Svc Inc (DASI)
11920 SW 128th Street
Miami, FL 33186

Ship To:

Diversified Aero Svc Inc (DASI)
11920 SW 128th Street
Miami, FL 33186

Ref #: 35206

Phone #: 305-234-2333

Fax #: 305-234-6100

Email: QUOTES@DASI.COM

Code: 372

PN: C24736001-0-1

Descr: VALVE

Qty: 1

Mfg: SAFRAN

Serial Number: U310

Entry Date: 9/8/2015

Need Date: 10/2/2015

Compl. Date: 10/2/2015 4:01

Warranty: No

Container:

2. Protective Cap Missing- Requires replacement

Rework Required:

1. Paint

Inspection Quote

Technician: P. Reyes

Inspector: D. Molina

Date: 09/22/2015.

AD/SERVICE BULLETINS/MODIFICATIONS

No AD applicable to this Assembly.

WORK PERFORMED

Replaced all mentioned parts. Unit was tested. Unit passed all functional test. Unit has been Inspected in accordance with current
SAFRAN CMM 32-57-01 REV 12 DTD March 17, 2015.

Technician: Patricio Reyes

Inspector: Daynel Molina

Date: 10/02/2015.

Maintenance Release Statement (FAR Pars 121, 125 and 135)

The instruments and or Components above was Serviced and Inspected with Pride and in accordance with current F.A.A. Regulations and is
☒ Approved || Not approved to Return to Service. Pertinent details of the Services are on files at this Repair Station.

Name:

Authorized Signature:

Inspector Seal:

Date: 10/2/2015

Cristian Munoz

Signed: