| Ci | United Kingdom Civil Aviation Authority Civil Aviation Authority | AUTHORISE | EASA FORM 1 | 3. Form Tracking Number: L 1881064 |
|----------------|--|-------------------|---|-------------------------------------|
| 4. Organisatio | 4. Organisation Name and Address: | Danasania | | |
| | | Quadrant House He | Panasonic Avionics Corporation | 5. Work Order/Contract/Invoice |
| | Panasonic | | The server, increase, increase, in animaliff hoad, Langley Berks, SL3 8XP, UK | 184291 |
| 6. Item | 7. Description | 8. Part No. | 9. Oty. 10. Serial No. | 11 Statue / Work |
| 4 | | | | Gratas / ANOIK |
| _ | PCU | RD-AX6740-54 | 1 D913481 | REPAIRED |
| , | | | | |

Certifies that unless otherwise specified in Block 12. the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. UZVY163X.

Panasonic Avionics Corporation internal reference SR 2857462

×

PART 145.A.50 Release to Service

×

Other regulation specified in block 12

| LICED/INICTALLED DECODORIGIDII ITIED | 1 de Palote (de minute wyw) | | 1.4 | The contract design dates specificate track to |
|--------------------------------------|--|--------------|---|---|
| | Mick White | | 14b. Authorised Signature: | Certifies that unless otherwise specified in Block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service. |
| | 14e. Date (dd mmm yyyy) 03-AUG-2012 | UK.145.00297 | 14c. Certificate/Approval reference No: | ock 12, the work identified in block 11 and ccordance with Part-145 and in respect or release to service. |

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the

the national regulations by the user/installer before the aircraft may be flown. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with

Panasonic

Panasonic Avionics Corporation

Quadrant House, Heron Drive, Parlaunt Road, Langley Berks, SL3 8XP, UK.

Tel: +44(0) 1753 741450 Fax: +44(0) 1753 741481

SOLD TO AJ WALTER AVIATION VISCOUNT HOUSE **PARTRIDGE GREEN**

SHIP TO AJ WALTER AVIATION VISCOUNT HOUSE **PARTRIDGE GREEN**

REPAIR REPORT / DELIVERY ORDER

WEST SUSSEX, ENGLAND RH13 8RA, GB WEST SUSSEX, ENGLAND RH13 8RA, GB PAGE 1 of 1 SHIP TRANSACTION: CUSTOMER P.O. NUMBER CUSTOMER TAIL NO. CUST PROD REF SERVICE REQUEST 184291 1001 XA-VOI 6285334 2857462 PART NUMBER NOMENCLATURE DATE REMOVED DATE RECEIVED RD-AX6740-54 PCU 20-JUL-2012 SERIAL NUMBER DATE OF MFG WTY START DATE DATE REPAIRED SHIP DATE WTY END DATE D913481 31-JUL-2008 14-JUL-2008 28-JUL-2012 13-JUL-2011 MOD IN 0 REASON PIN BROKEN FOR CUSTOMER REJECTION INTERNAL No Physical Damage - DIRTY. INSPECTION Physical Damage - DIRTY. SHEARED BACK COVER - WORN FIXING SCREW - MINOR SCRATCHES ON FRONT COVER NO ACTION TAKEN -**EXTERNAL** INSPECTION CUSTOMER COMPLAINT CONFIRMED.REPLACED INTERMITTENT JACK SOCKETS, FIXING SCREW & BACK COVER. UNIT CLEANED AND TESTED -ACTUAL PASSED ALL FUNCTIONAL TESTS. ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 44-23-04 REV 18 DTD FEB 12. FAILURE / CORRECTIVE ACTION MOD OUT: 0 INSPECTED BY: Mick White REPAIRED BY: PATEL, ASHOK **PART NUMBER** DESCRIPTION **MIVIUUIVI** R6KF298YA **BACK COVER** R6XSNBP19UWK TERMINAL SCREW, STEEL R5J1D24ZA JACK R5J1D23ZA JACK

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

* WTY CODES

NO = Not Covered

FOC = SB covers as FOC

SHOP = Shop Wty

WARR = Mfg Wty in Effect FIXED = Fixed Price Repair

CC = Panasonic Charged