

1. Approving Civil Aviation Authority/ Country: FAA/United States	2. Authorized Release Certificate FAA Form 8130-3, Airworthiness Approval Tag	3. Form Tracking Number: R330149
4. Organization Name and Address: AOG Accessories 2549 N.W. 74th Ave. Miami FL 33122 USA Phone: 305-591-1899 Fax: 305-489-0176 FAA APPROVED REPAIR STATION NO. XB4R642M * EASA 145.5924	5. Work Order/Contract/ Invoice Number: 14629	
6. Item: 1	7. Description: Vacuum Toilet Assy	8. Part Number: 7900104
	9. Quantity: 1ea.	10. Serial Number: 21-2884
		11. Status/Work: REPAIRED
12. Remarks: REPAIRED in accordance with CMM 38-30-21 Revision 5. Full details of work carried out per work order no. 14629 Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the Vacuum Toilet Assy is considered ready for release to service under EASA Part 145 approval no. EASA 145.5924 . A.D.: No AD required. S.B.: No SB required.		
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12.		
14a. ☒ 14 CFR 43.9 Return to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplish in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13b. Authorized Signature: Not Applicable	13c. Approval/Authorization No.: Not Applicable	14c. Approval/Certificate No.: XB4R642M
13d. Name (Typed or Printed): Not Applicable	14d. Name (Typed or Printed): AL Soto	14e. Date (dd/mm/yyyy): 27/Nov/2017
User/Installer Responsibilities		
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block1. Statements in Block13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.		

TearDown/Inspection Form

AOG Accessories

2549 N.W. 74th Ave.

Miami FL 33122

USA

Phone: 305-591-1899 Fax: 305-489-0176

C.R.S. No.: XB4R642M

Work Order: 14629

Date: November/27/2017

Sold To:

AJ WALTER AVIATION, LTD
THE HEADQUARTERS MAYDELL AVE SLINFOLD RH130AS
WEST SUSSEX UNITED KINGDOM

Ship To:

AJ WALTER AVIATION, LTD
THE HEADQUARTERS MAYDELL AVE SLINFOLD RH130AS
WEST SUSSEX UNITED KINGDOM

Part Number: 7900104

Serial: 21-2884

Manufacturer: MONOGRAM

Description: Vacuum Toilet Assy

Model: 7900104

Purchase Order: R330149

Service Performed: REPAIRED

Data used: Manual Number: 38-30-21 Revision: 5 Date: 3/16/2011

Teardown/Inspection Data

1.- Trouble Reported: WATER LEAKAGE TEST & RECERT Inst.: Repair Only.

Appearance: Normal

Corrosion: No Corrosion Noted.

Loose or Missing Parts: No Loose or Missing Parts.

Physical Damage: No damage found.

2. Teardown

Disassembly: Only as Required for Repair.

Painting: None Performed.

Cleaning: Performed cleaning as required

Assembly: As Required

3. Test

Operation: TESTED I/A/W Mfg. Specs.

Modifications: NONE

Was Complaint Verified: Yes

Other problems found: None Found

4. Final

Warranty Accepted: N/A

Final Test and Inspection: Final Inspection Normal.

A.D.: No AD required.

S.B.: No SB required.

5. Work Performed: LRU WAS DISASSEMBLED, CLEANED, INSPECTED AND REPAIRED. PERFORM RETURN TO SERVICE TEST, LRU MEETS MFGS SPECS AND IS READY FOR SERVICE.

Maintenance Release

This certifies the item identified above was serviced in accordance with current F.A.A. airworthiness regulations and in respect to the work performed is approved to return to service. Pertinent details of the work performed are on File at this Agency under Work

Order No.: 14629

Inspector's Name: AL Soto

Technician: Agustin Ansorena

Signature: AC Soto

Inspector

Date: November/27/2017

Form: AOG 103