


1. Approving Competent Authority / Country CAA UK		2.		AUTHORISED RELEASE CERTIFICATE CAA FORM 1			3. Form Tracking Number: WAV2110500	
4. Organization Name and Address:  Avia Technique SK AeroSafety Group				Avia Technique Ltd. Unit 1,3,4, 6 Fishponds Estate Fishponds Road Wokingham, Berkshire, United Kingdom RG41 2QJ Ph: +441189789789, Fax: +441189794511				5. Work Order / Contract / Invoice Number: WAV2110500 R386181
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:			
1	Oxygen Cylinder Assembly	5500-C1A-BF23B	1.00	P06101312	Repaired			
12. Remarks: CMM: 35-32-18 Revision: 2 Next Overhaul / Hydrostatic Test: 02-2022 Avia Technique have checked and verified that there are no pertinent AD's or SB's relevant. "The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect to that work, the items are approved for return to service under certificate no. I8QY183X"								
13a. Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12				14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.				
13b. Authorised Signature:		13c. Certificate /Approval Ref No.:		14b. Authorised Signature:		14c. Certificate /Approval Ref No.:		
						 UK. 145.00846		
13d. Name		13e. Date (dd/mm/yyyy):		14d. Name		14e. Date (dd/mm/yyyy):		
				Victoria Connelly		08/Sep/2021		
USER / INSTALLER RESPONSIBILITIES								
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.								

1. Approving Competent Authority / Country EASA		2.		AUTHORISED RELEASE CERTIFICATE EASA FORM 1			3. Form Tracking Number: WAV2110500	
4. Organization Name and Address:  Avia Technique SK AeroSafety Group				Avia Technique Ltd. Unit 1,3,4, 6 Fishponds Estate Fishponds Road Wokingham, Berkshire, United Kingdom RG41 2QJ Ph: +441189789789, Fax: +441189794511				5. Work Order / Contract / Invoice Number: WAV2110500 / R386181
6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:			
1	Oxygen Cylinder Assembly	5500-C1A-BF23B	1.00	P06101312	Repaired			
12. Remarks: CMM: 35-32-18 Revision: 2 Next Overhaul / Hydrostatic Test: 02-2022 Avia Technique have checked and verified that there are no pertinent AD's or SB's relevant.								
13a. Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12								
13b. Authorised Signature:		13c. Certificate /Approval Ref No.:		14a. ☒ Part-145.A.50 Release to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.		14c. Certificate /Approval Ref No.: EASA.UK.145.00846		
13d. Name		13e. Date (dd/mm/yyyy):		14b. Authorised Signature: 		14e. Date (dd/mm/yyyy): 08/Sep/2021		
14d. Name Victoria Connelly								
USER / INSTALLER RESPONSIBILITIES								
This certificate does not automatically constitute authority to install the item(s).								
Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.								
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.								



Avia Technique Ltd.
Unit 1,3,4, 6 Fishponds Estate
Fishponds Road
Wokingham, Berkshire, United Kingdom
RG41 2QJ
Ph: +441189789789, Fax: +441189794511

Tear Down/Inspection

Work Order #: WAV2110500

Date Printed: 03/09/2021

Page: 1

To:

A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

Ship To:

A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

Reference: R386181
Date Received: 26/08/2021
Part Number: 5500-C1A-BF23B
Description: Oxygen Cylinder Assembly
Serial Number: P06101312

Customer Remarks:

Repair

Results from inspection:

Unit requires Repair and Recertification
DOM: 06-2006

Corrective actions:

Repair & Test with reference to the correct CMM
Refill with Aviation/Breathing Oxygen compliant with MIL-PRF-27210 Specification

Inspection report generated by: Jordi Marti Haro