

4. ORGANIZATION NAME AND ADDRESS
IBERIA
MAINTENANCE

Adolfo Suarez Madrid - Barajas Intl.
Airport - Zona Industrial No. 2
28042 MADRID - SPAIN
www.iberiamaintenance.com

5. WORK ORDER / CONTRACT / INVOICE
7200691850

6. ITEM	7. DESCRIPTION	8. PART N°	9. QTY	10. SERIAL No.	11. STATUS / WORK
1	SIDE STICK ASSEMBLY	F27310012000AM	1	729	INSPECTED/TESTED

12. REMARKS
WORKS PERFORMED I.A.W. CMM:27-92-41 REV.81 JAN 2023 MFG DATE: 10-2005
Customer: AJW RO: T40727

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate No.ILAY037F.
TCCA Approval Number: 898-27

Records of works performed are on file at this maintenance organization under Work Order stated in block 5

13a. Certifies that the items identified above were manufactured in conformity to:

☐ approved design data and are in condition for safe operation

☐ non-approved design data specified in block 12

14a. ☒ Part 145.A.50 Release to Service ☒ Other regulation specified in block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with part 145 and in respect to that work the items are considered ready for release to service.

13b. AUTHORISED SIGNATURE	13d. APPROVAL/AUTHORISATION NUMBER	14b. AUTHORISED SIGNATURE Nº. DE NÓMINA 971861	14c. CERTIFICATE/APPROVAL REF. No. ES.145.011
13c. NAME	13e. DATE(dd/mm/yyyy)	14d. NAME: LUIS MIGUEL DEL PINO CARAVACA	14e. DATE (dd/mm/yyyy): 13/JUL/2023

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).
Where the user/installer works in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from their airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national

1. Approving Competent Authority / Country : CAA UK	2. AUTHORISED RELEASE CERTIFICATE CAA FORM 1	3. FORM TRACKING NUMBER. MI/23762064
---	---	--

4. ORGANIZATION NAME AND ADDRESS IBERIA MAINTENANCE	Adolfo Suarez Madrid - Barajas Intl. Airport - Zona Industrial No. 2 28042 MADRID - SPAIN www.iberiamaintenance.com	5. WORK ORDER / CONTRACT / INVOICE 7200691850
--	--	---

6. ITEM	7. DESCRIPTION	8. PART N°	9. QTY	10. SERIAL No.	11. STATUS / WORK
1	SIDE STICK ASSEMBLY	F27310012000AM	1	729	INSPECTED/TESTED

12. REMARKS WORKS PERFORMED I.A.W. CMM:27-92-41 REV/81 JAN 2023 Customer: AJW RO: T40727	MFG DATE: 10-2005
--	-------------------

Records of works performed are on file at this maintenance organization under Work Order stated in block 5

13a. Certifies that the items identified above were manufactured in conformity to: ☐ approved design data and are in condition for safe operation ☐ non-approved design data specified in block 12	14a. ☒ Part 145.A.50 Release to Service ☐ Other regulation specified in block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with part 145 and in respect to that work the items are considered ready for release to service.
--	---

13b. AUTHORISED SIGNATURE	13d. APPROVAL/AUTHORISATION NUMBER	14b. AUTHORISED SIGNATURE N° DE NÓMINA 971861	14c. CERTIFICATE/APPROVAL REF. No. UK.145.01413
13c. NAME	13e. DATE(dd/mm/yyyy)	14d. NAME: LUIS MIGUEL DEL PINO CARAVACA	14e. DATE (dd/mm/yyyy): 13/JUL/2023

USER/INSTALLER RESPONSIBILITIES
This certificate does not automatically constitute authority to install the item(s).
Where the user/installer works in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national

WORK SHOP REPORT

DIRECCIÓN TÉCNICA
 DIRECCIÓN DE COMPONENTES
 BARAJAS AIRPORT - 28042 MADRID - SPAIN
 PHONE: 34 91 5873013 FAX: 34 91 5873031
 MAIL: ibecomponentes@iberia.es

MAINTENANCE ORGANIZATION EASA PART 145 APPROVAL CERTIFICATE N° ES.145.011		FAA AIR AGENCY CERTIFICATE NUMBER ILAY037F	
IBERIA WORK ORDER	7200691850		
CUSTOMER	AJ WALTER AVIATION		
CUSTOMER REPAIR ORDER	T40727		
DENOMINATION	SIDE STICK ASSEMBLY		

INCOMING DATA		OUTGOING DATA	
INCOMING DATE:	02.JUN.2023	OUTGOING DATE:	13.JUL.2023
INCOMING P/N:	F27310012000AM	OUTGOING P/N:	F27310012000AM
INCOMING S/N:	729	OUTGOING S/N:	729
MOD IN:		MOD OUT:	
TASK REQUESTED:	INSPECTED/TESTED	STATUS/WORK PERFORMED:	INSPECTED/TESTED
REASON FOR REMOVAL:	IAW RO		
CMM NUMBER:	27-92-41 REV.81 JAN 2023		
AIRCRAFT TAIL NUMBER:	Not reported		
ENGINE SERIAL NUMBER:	Not reported		
WARRANTY REQUESTED:	NO.	WARRANTY STATUS:	Not applicable
WARRANTY COMMENTS:	Not applicable		

EXTERNAL CONDITION / INCOMING INSPECTION:

Equipment Identification Data	☒	Yes	☐	No	
Documentation	☒	Yes	☐	No	
Correct config and complete	☒	Yes	☐	No	
External misused (Burned, forced,	☐	Yes	☒	No	

CORRECTLY PACKED AT INCOMING: YES
TYPICAL SEQUENTIAL TASKS:

Visual Incoming inspection	☒	Yes	☐	No	☐	N/A	
Incoming test	☒	Yes	☐	No	☐	N/A	
Disassembly	☒	Yes	☐	No	☐	N/A	
Cleaning	☒	Yes	☐	No	☐	N/A	
NDT Check	☐	Yes	☐	No	☒	N/A	
Assembly	☒	Yes	☐	No	☐	N/A	
FOD Check inspection	☒	Yes	☐	No	☐	N/A	
Final Test	☒	Yes	☐	No	☐	N/A	

TYPE OF FAULT: NOT FOUND FAULTY

WORK SHOP REPORT

DIRECCIÓN TÉCNICA
DIRECCIÓN DE COMPONENTES
BARAJAS AIRPORT - 28042 MADRID - SPAIN
PHONE: 34 91 5873013 FAX: 34 91 5873031
MAIL: ibecomponentes@iberia.es

SHOP FINDINGS AND WORKS PERFORMED:

SHOP FINDING	WORK PERFORMED
No fault found	Tested/cleaned i.a.w. C.M.M

SERVICE BULLETINS: N/A

PARTS REPLACED: N/A

SUBASSYS REPLACED: N/A

REMARKS:

MFG DATE: 10-2005



DE: COMPONENTS CUSTOMER SUPPORT DEPT.
IBERIA LAE OPERADORA
CIF: A85850394
NUEVA ZONA INDUSTRIAL La Muñoza
Telefono: 915873194

A: Departamento de envios:
Nueva Zona Industrial La Muñoza
Almacenes
Telefono: 915873322
Mail: envios@iberia.es

PARA ENVIAR A: AJ WALTER AVIATION LTD.
THE HEADQUARTERS
Dangerous goods FDX 124277507

MAYDWELL AVENUE
GB-RH13 0A SLINFOLD, WEST SUSSEX
UNITED KINGDOM

NOTA IMPORTANTE: Las partidas abajo mencionadas son para uso de la Compañia

CANTIDAD	PART NUMBER	SERIAL NUMBER	DENOMINACION	PRICE
1	F27310012000AM:FAP	729	SIDE STICK	
FABRICANTE :				

CUSTOMER PROPERTY, REPAIR ORDER: T40727

Envio mediante transportista : DHL 960301029 .

Comunicar datos de envío al cliente, y al departamento de soporte a clientes de componentes mediante correo electrónico a la dirección de mail: Ibecomponentes@iberia.es

Número de bultos (Number of pieces)	Peso Neto (Net weight in Kgs)	Dimensiones (CMS)