


1. Approving Competent Authority / Country CAA/UK		2.		AUTHORISED RELEASE CERTIFICATE CAA FORM 1				3. Form Tracking Number: WAV2215475	
4. Organization Name and Address:  Avia Technique SK AeroSafety Group				Avia Technique Ltd. Unit 1,3,4, 6 Fishponds Estate Fishponds Road Wokingham, Berkshire, United Kingdom RG41 2QJ Ph: +441189789789, Fax: +441189794511				5. Work Order / Contract / Invoice Number: WAV2215475 R399713	
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:				
1	Oxygen Cylinder Assembly	9700-C1A-BF23B	1.00	P07092563	Overhauled				
12. Remarks: CMM: 35-31-55 Revision: 8 CMM: 35-31-55 Revision: 8						"The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR Part 43 and in respect to that work, the items are approved for return to service under certificate no. 1837183X"			
Next Overhaul / Hydrostatic Test: 09-2027									
Avia Technique have checked and verified compliance with all applicable AD's and SB's.									
14a. ☒ Part-145.A.50 Release to Service ☒ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.									
14b. Authorised Signature: 				14c. Certificate /Approval Ref No.:  UK.145.00846					
14d. Name Charlie Mountain				14e. Date (dd/mm/yyyy): 26/Sep/2022					
USER / INSTALLER RESPONSIBILITIES									
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.									

1. Approving Competent Authority / Country EASA		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1			3. Form Tracking Number: WAV2215475	
4. Organization Name and Address: Avia Technique SK AeroSafety Group Avia Technique Ltd. Unit 1,3,4, 6 Fishponds Estate Fishponds Road Wokingham, Berkshire, United Kingdom RG41 2QJ Ph: +441189789789, Fax: +441189794511		5. Work Order / Contract / Invoice Number: WAV2215475 / R399713				
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:	
1	Oxygen Cylinder Assembly	9700-C1A-BF23B	1.00	P07092563	Overhauled	
12. Remarks: CMM: 35-31-55 Revision: 8 CMM: 35-31-55 Revision: 8 Next Overhaul / Hydrostatic Test: 09-2027						
Avia Technique have checked and verified compliance with all applicable AD's and SB's.						
14a. ☒ Part-145 A.50 Release to Service ☐ Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Part-145, and in respect to that work the items are considered ready for release to service.						
14b. Authorised Signature: 			14c. Certificate /Approval Ref No.: EASA.UK.145.00846			
14d. Name Charlie Mountain			14e. Date (dd/mm/yyyy): 26/Sep/2022			
USER / INSTALLER RESPONSIBILITIES						
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						



Avia Technique
UK Aerospace Group

Avia Technique Ltd.
Unit 1,3,4, 6 Fishponds Estate
Fishponds Road
Wokingham, Berkshire, United Kingdom
RG41 2QJ
Ph: +441189789789, Fax: +441189794511

Tear Down/Inspection

Work Order #: WAV2215475

Date Printed: 15/09/2022

Page: 1

To:

A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

Ship To:

A.J. Walter Aviation Ltd.
Maydwell Avenue
The Headquarters
Slinford RH13 0AS
United Kingdom

Reference: R399713

Date Received: 31/08/2022

Part Number: 9700-C1A-BF23E

Description: Oxygen Cylinder Assembly

Serial Number: P07092563

Customer Remarks:

Repair

Results from inspection:

Unit requires Overhaul

DOM: 05-2007

ASSEMBLY DOM:09-2007

OVERHAUL DUE:04-2022

Corrective actions:

Overhaul with ref to the correct CMM

Refill with Aviation/Breathing Oxygen compliant with MIL-PRF-27210 Specification

Inspection report generated by: Sam Wilson