


1. Approving Civil Aviation Authority/Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE FORM ONE			3. Form Tracking Number. WO78996	
4. Organization Name and Address. AJW Technique Inc 7055, rue Alexander Fleming Saint-Laurent QC H4S-2B7 Canada						5. Work Order, Contract or Invoice Number: W45194-1
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:	
1	Bleed Monitoring Computer	785-002-61	1.00	1214	REPAIRED	
12. REMARKS UNIT REPAIRED AND TESTED SERVICEABLE AS PER CMM 36-11-34 REV:09 DATED DEC/3/2001. FOR ADDITIONAL INFORMATION REFER TO TEAR DOWN REPORT						
EASA Approval No.: EASA.145.7260 Maintenance performed in accordance with FAR 43.17						
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12		14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations. ☒ CAR 571.10 Maintenance Release ☒ Other regulation specified in Block 12				
13b. Signature:	13c. Approved Organization Number	14b. Signature	14c. Approval Organization Number 33-12			
13d. Name (Typed or Printed):	13e. Date	14d. Name (Typed or Printed) Alii Abdeljalil	14e. Date (dd/mm/yyyy) 28/Mar/2019			
Installer Responsibilities						
This certificate does not constitute authority to install the part.						
Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.						

Work Order: WO78996

Date Printed: 3/28/2019

Customer RO: W45194-1

Page: 1

To:

A J Walter Aviation Ltd.
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Code: AJW01

Fax:

Descr: Bleed Monitoring Computer

Phone:

P/N: 785-002-61

Qty: 1

Email:

S/N: 1214

Mfg: ZODIAC AEROTECHNICS

TSN: UNK

TSO: UNK

TSR: 0

CSN: UNK

CSO: UNK

CSR: 0

P/N Out: 785-002-61

S/N Out: 1214

Symptoms:

CODE: REPAIR

DETAILS: AIR BLEED WITH MESSAGE NO DATA FROM BMC 1.

Faults:

CODE: INITIAL TEST FAILURE

DETAILS: UNIT FAIL THE ACCEPTANCE TEST:
UNIT FAIL CHAPTER 2: REGULATED PRESURE FAIL

CODE: WARRANTY REQUESTED

DETAILS: Warranty requested is: DENIED.
WARRANTY NOT REQUESTED BUT UNIT LEFT SHOP ON AUG 17 2018. WARRANTY DENIED BECAUSE SNAG
REPORTED IS NOT RELATED TO PREVIOUS SNAG REPORTED. PREVIOUS VISIT SNAG WAS "WING LOOP B FAULT".
PREVIOUS VISIT WAS NFF.

CODE: REPAIR

DETAILS: The following repair(s) will be performed:
UNIT NEEDS TO BE REPAIRED: DIODE D16,D13,D17,D18,D14 AND D15 NEED TO BE REPLACED ON THE INPUT CARD

Corrective Actions:

CODE: REPAIRED

DETAILS: UNIT REPAIRED AND TESTED SERVICEABLE AS PER CMM 36-11-34 REV:09 DATED DEC3/2001.
FOR ADDITIONAL INFORMATION REFER TO TEAR DOWN REPORT