

1. Approving Competent Authority
/ Country / Autorité Compétente / Pays

2.

DIRECTION GENERALE DE
L'AVIATION CIVILE
FRANCE

AUTHORISED RELEASE CERTIFICATE

Certificat Libératoire Autorisé

EASA FORM 1

Formulaire 1 de l'EASA

3. Form Tracking Number
Numéro de repère du Formulaire

1223924

4. Organisation Name and Address :
Nom et Adresse de l'Organisme

AIR SUPPORT

ZA du Roulage
125, avenue du Roulage
32600 PUJAUDRAN
FRANCE

5. Work Order/Contract/Invoice
Bon de commande/Contrat/Facture

R397379

6. Item / Item

7. Description / Description

8. Part No. / N° de pièce

9. Qty / Qté

10. Serial No. / N° série

11. Status/Work / Etat/Travaux

1
Water heater

HFAWB2005-01

001

14284

Repaired

12. Remarks
Remarques

See Shop Finding Report N° 1223924.

in accordance with
CMM 25-34-88 rev. 4 dated Feb 19, 2016 - IACOBUCCI

The work identified in block 11 described here has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for release or return to service under certificate n°V11Y111Y

Authorized signature :

Name
Patrick PELLERIN

Date
18 Aug 2022

Printed from electronic file



FAA Repair station N°V11Y111Y

13a. Certifies that the items identified above were manufactured in conformity to :
Certifie que les éléments identifiés ci-dessus ont été fabriqués conformément aux :

- ☐ approved design data and are in a condition for safe operation
données de conception approuvées et sont en état de fonctionner en toute sécurité
- ☐ non-approved design data specified in block 12
données de conception non approuvées spécifiées dans la case 12

14a. ☒ Part-145.A.50 Release to Service
Approbation pour remise en service
selon Partie 145.A.50

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.
Certifie que, sauf indication contraire spécifiée en case 12, les travaux identifiés en case 11 et décrits en case 12, ont été réalisés conformément à la Partie 145 et qu'au vu de ces travaux, les pièces sont considérées prêtes à la remise en service.

☒ Other regulation specified in block 12
Autre réglementation précisée en case 12

13b. Authorised Signature / Signature autorisée

13c. Approval/Authorisation Number
Numéro d'agrément d'autorisation

14b. Authorised Signature / Signature autorisée

14c. Certificate/Approval Ref. No.
Numéro du Certificat/Agrément

FR.145.0058

13d. Name / Nom

13e. Date (dd/mm/yy) / Date (jj/mm/aaaa)

Electronic signature on file

14d. Name / Nom
Patrick PELLERIN



14e. Date (dd/mm/yy) / Date (jj/mm/aaaa)
18 Aug 2022

1. USER/INSTALLER RESPONSIBILITIES / Responsabilités de l'utilisateur/installateur

This certificate does not automatically constitute authority to install the item(s).
Ce document ne constitue pas forcément l'autorisation d'installer l'item(s).

2. Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Quand l'utilisateur/installateur travaille selon les réglementations d'une autorité de navigabilité différente de l'autorité de navigabilité mentionnée dans la case 1, il est essentiel que l'utilisateur/installateur s'assure que son autorité de navigabilité accepte les items libérés par l'autorité de navigabilité mentionnée dans la case 1.

3. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.
Les indications portées en cases 13a et 14a ne constituent pas une certification de montage. Dans tous les cas le dossier d'entretien de l'aéronef doit contenir une certification d'installation délivrée conformément aux règlements nationaux par l'utilisateur/installateur avant que l'aéronef puisse voler.

EASA Form 1-MF/CAO/145 issue 3 / Formulaire 1-MF/CAO/145 de l'EASA Edition 3

INCOMING INSPECTION
HAS BEEN PASSED BY A DIVISION
Incoming Inspector

ASB

2023-12-06

1. Approving Competent Authority / Country

2.

AUTHORISED RELEASE CERTIFICATE

3. Form Tracking Number

1223924

UK CAA

CAA FORM 1

4. Organisation Name and Address

AIR SUPPORT

ZA du Roulage
125, avenue du Roulage
32600 PUJAUDRAN

FRANCE

5. Work Order/Contract/Invoice

R397379

6. Item

7. Description

8. Part No.

9. Qty.

10. Serial No.

11. Status/Work

1

Water heater

HFAWB2005-01

001

14284

Repaired

12. Remarks

See Shop Finding Report Nr 1223924.

in accordance with
CMM 25-34-88 rev. 4 dated Feb 19, 2016 - IACOBUCCI

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished IAW Part 145 and in respect to that work the items are considered ready for release to service.

Printed from electronic file

13a. Certifies that the items identified above were manufactured in conformity to :

- ☐ approved design data and are in a condition for safe operation
- ☐ non-approved design data specified in block 12

14a. ☒ Part 145.A.50 Release to Service

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part 145 and in respect to that work the items are considered ready for release to service.

☐ Other regulation specified in block 12

13b. Authorised Signature

13c. Approval/Authorisation Number

14b. Authorised Signature

14c. Certificate/Approval Ref. No

UK. 145.01579

13d. Name

13e. Date (dd mmm yyyy)

14d. Name

14e. Date (dd mmm yyyy)

Patrick PELLERIN



18 Aug 2022

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



SHOP FINDING REPORT

CUSTOMER : AJ WALTER AVIATION LTD

DATE : 18 Aug 22

Customer R/O: R397379

Unit Received

P/N in : HFAWB2005-01

S/N in : 14284

Designation : Water heater

Our REF : 1223924

Opening date : 20 Jul 22

Reason of removal :

WRONG P/N INSTALLED

Work Requested :

Repair

Reason of removal confirmed ☐ YES ☒ NO

CMM : CMM 25-34-88 rev. 4 dated Feb 19, 2016 - IACOBUCCI

VISUAL CHECK

Water heater impacted on rear left cover and on right corner, to straightened. .

FINDINGS AND ANALYSIS

Incoming test : Failed

Disassembled and Inspected

Found : Water heater leaks water by flowmeter. Flowmeter and elbow adapter to replace. Water heater descaled. Equipment straightened.

WORK TO PERFORM

TEST ☐ REP ☒ MOD ☐ OVH ☐ SCRAP ☐

SHOP DETAILS

Replaced listed parts and hardware

Reassembled

Inspected/Tested

Prepared for shipment and storage

MAIN PARTS REPLACEMENT

HFE07-12	Flowmeter	1
HFE07-33	Adapter	2
HFE07-10	Adapter elbow	1
HFE07-78	O-ring	1
HFA07-31	Adapter straight	1

COMMENTS

Failure observed ☒ YES ☐ NO

Warranty requested : ☐ YES ☒ NO

WORK PERFORMED

INSPECTED/TESTED ☐
REPAIRED ☒
MODIFIED ☐
OVERHAULED ☐
SCRAPPED ☐

WARRANTY DECISION

ACCEPTED ☐ PARTIALLY ACCEPTED ☐ REFUSED ☐

CERTIFICATION

☐ EASA

☒ DUAL EASA/FAA

☐ DUAL EASA/TCAC

☐ CAAC

☐ OTHER

UNIT DELIVERED

P/N out HFAWB2005-01

S/N out 14284

Name of technician Salah AHAMADA