

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2.		AUTHORIZED RELEASE CERTIFICATE FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG				3. Form Tracking Number J9055			
4. Organization Name and Address: Velocity Aerospace - Burbank, Inc. 2840 N. Ontario Street Burbank, CA 91504 Ph: 818-333-5600,				5. Work Order/Contract/Invoice Number: R418094							
Repair Station Cert. # RB1R197K											
6. Item		7. Description:		8. Part Number:		9. Quantity:		10. Serial Number:		11. Status/Work:	
1		SMOKE DETECTOR		CGAB1400-00		1		6045		REPAIRED	
12. Remarks: All work has been accomplished in accordance with FAA approved data: CMM: 26-11-22 Rev: 6 Dated: 3/25/2009											
Certified that the work specified in block 11/12 was carried out in accordance with EASA PART 145 and in respect to that work the component is considered ready for release to service under EASA Part 145 approval no. EASA.145.4002. For complete details of work accomplished reference tracking number in block (3) three or as attached.											
13a. Certifies the items identified above were manufactured in conformity to: ☐ Approved design data and are in a condition for safe operation. ☐ Non-approved design data specified in Block 12				14a. ☒ 14 CFR 43.9 Return to Service ☒ Other regulation specified in Block 12							
				Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.							
13b. Authorized Signature:		13c. Approval Authorization No.:		14b. Authorized Signature: <i>For Ramon Flores</i>		14c. Approval/Certificate No.: RB1R197K					
13d. Name (Typed or Printed):		13e. Date (dd/mm/yyyy):		14d. Name (Typed or Printed): Jose Ramon Flores		14e. Date (dd/mm/yyyy): 16/Oct/2023					
User/Installer Responsibilities											
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.											
FAA Form 8130-3 (02-14)											
NSN:0052-00-012-9005											

**Velocity Aerospace - Burbank, Inc.**

2840 N. Ontario Street
Burbank, CA 91504
Ph: 818-333-5600,
Repair Station: RB1R197K FAA/EASA.145.4002

RECAP**Work Order #: J9055**

Date Printed: 10/16/2023

Time: 7:18:03 AM

Page: 1

To: AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVE, SLINFOLD
WEST SUSSEX RH13 0AS UK
payableinvoices@ajw-group.com, UNITED
KINGDOM

Ship To: AJ WALTER AVIATION LTD (UK)
THE HEADQUARTERS
MAYDWELL AVENUE, SLINFOLD
GB717870119000
WEST SUSSEX, RH13 0AS, UNITED
KINGDOM

Ref #: R418094

Phone #: 441403711414

Fax #:

Email: chris.copestake@ajw-aviation.com

Mfg: SIEMENS SAS

Serial #: 6045

PN: CGAB1400-00

Descr: SMOKE DETECTOR

ATA Chapter: 26-11-22

Revision #: 6

Revision Date: 3/25/2009

Test Record: 2252B

Technician: AMACIAS

Type:

Entry Date: 10/12/2023

Need Date: 10/22/2023

Compl. Date: 10/15/2023 7:17:36 AM

Container:

Warranty: No

Symptoms:

WORKSCOPE: RP

REASON FOR REMOVAL

LOOP A FAULT LIGHT

Faults:

PRELIMINARY TEST & TEARDOWN

Unit Passed FT.

Visually Inspected unit came in dirty. Requires internal inspection. Open unit for inspection labyrinth and PCB's are dirty. Requires cleaning.

Corrective Actions:

FINAL DISPOSITION: REPAIR

FINAL WORK ACCOMPLISHED

Cleaned labyrinth assembly, connector pins and housing. Inspected components and wiring. No parts replaced. Assembled, Calibrated and FT unit to mfg's specs.

STAMP TO THE RIGHT INDICATING THAT YOU HAVE VERIFIED THE FOLLOWING:

Purchase Order, Part Number, Serial Number, Mods, ATA Number, Revision, Date,
Customer Documents, and AD's

Final Insp.: